

辉 陽 汽 車 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

MS HM 19
LKK
17/12/19

16/12/2019

Owner: U&G CAR LEASING

Not Authorized
U&G?
Recovery After Repair

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID 1.8S A - SLN2749U

1pc	rear tailgate "PRIUS" emblem	Me	\$	61.75	—
1pc	rear tailgate "HYBRID" emblem	Me	\$	53.75	—
1pc	rear tailgate "TOYOTA" logo	Me	\$	61.10	—
1pc	rear tailgate outer garnish		\$	741.35	?
1pc	rear tailgate inner lock	Me	\$	381.85	X
1pc	rear tailgate inner rubber	Me	\$	281.50	X
1pc	rear tailgate inner garnish		\$	381.00	?
2pcs	rear taillamp lower bracket @\$121.50		\$	243.00	?
1pc	rear bumper	Me	\$	928.35	—
2pcs	rear bumper side retainer @\$141.40	Me	\$	282.80	X
2pcs	rear bumper side lamp @\$371.45.00		\$	742.90	?
2pcs	rear bumper side lower garnish @\$274.45	ols?	\$	548.90	—
1pc	rear bumper diffuser	Me	\$	379.00	—
1pc	rear bumper reinforcement		\$	458.00	?
1pc	rear bumper towing cover	odd/Me	\$	61.00	—
1pc	rear bumper lower centre cover		\$	281.50	?
2pcs	rear bumper lower side cover @\$191.55		\$	383.10	?
1pc	rear end panel		\$	970.25	?
1pc	rear end panel inner garnish		\$	381.90	?
1pc	rear end panel sensor		\$	281.50	?

less 25%

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1set rear number plate & casing
1set rear parking sensor

Me s.nett \$ 50.00 *455N*
Me s.nett \$ 280.00 *2005N*

tuffkote
wiring
spray painting
labour charges
Total

\$ 180.00 ?
\$ 180.00 *200*
\$ 1,200.00 *600*
\$ 1,200.00 ?
\$ 9,018.38

