

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: CHINA	DATE	: 17/12/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SKX3203E	Asher	
MODEL	: TOYOTA HARRIER 2.0		
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 11-Dec-19
		TIME	: 11:12HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	SIDE SKIRT LH <i>ut</i>	1	\$ 890.00	\$ 890.00 ✓ 689
2	REAR DOOR LH <i>vented</i>	1	\$ 1,855.50	\$ 1,855.50 ✓ 1569
3	REAR DOOR OUTER CHROME GARNISH LH <i>old</i>	1	\$ 320.00	\$ 320.00 ✓
4	REAR FENDER LH <i>Regis</i>	1	\$ 1,422.20	\$ 1,422.20 ✗
5	REAR FENDER MUD FLAG LH <i>ut</i>	1	\$ 88.30	\$ 88.30 ✓
6	REAR QUARTER GLASS WITH MOULDING <i>Regis</i>	1	\$ 820.00	\$ 820.00 ✗
7	REAR BUMPER <i>Regis</i>	1	\$ 1,533.20	\$ 1,533.20 ✗
8	REAR BUMPER SIDE RETAINER LH <i>new</i>	1	\$ 62.40	\$ 62.40 ✗

2356.30

TOTAL PRICE \$ 6,991.60

1767.22

LESS 25% \$ 1,747.90

SUB TOTAL PRICE \$ 5,243.70

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR FENDER MUD FLAP CLIP(SET) <i>new</i>	1	\$ 30.00	\$ 30.00 ✗
2	QUARTER GLASS SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00 ✗
3	REAR BUMPER CLIP(SET) <i>new</i>	1	\$ 30.00	\$ 30.00 ✗

4	REAR WHEEL RIM LH <i>ut</i>	1	\$ 850.00	\$ 850.00	<i>600</i>
5	REAR WHEEL TYRE LH <i>the m</i>	1	\$ 450.00	\$ 450.00	<i>x</i>

600

TOTAL \$ 1,440.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,200.00	<i>500</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	<i>650</i>	
3	TUFF COAT	\$ 180.00	<i>60</i>	
4	WIRING CHECK	\$ 120.00	<i>30</i>	
5	UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	\$ 120.00	<i>x</i>	
6	REMOVE AND REFIX REAR DOOR MECHANISM LH	\$ 160.00	<i>80</i>	
7	REMOVE AND REFIX QUARTER GLASS	\$ 120.00	<i>x</i>	
8	FOUR WHEEL ALIGNMENT	\$ 120.00	<i>80</i>	

1400

TOTAL \$3,220.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,683.70
TOTAL LABOUR COST : \$ 3,220.00
TOTAL REPAIR COST : \$ 9,903.70

Adrian Ling
L/S 17/12/19.
04 days.

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

total: 3767.22
L/S 3K

31c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: