

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9855K**AAD1912-141***Not Authorized
L/Sny & 1900k*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

19 DEC 2019

SHB 9855K

VF1ABL15AUC273454

RENAULT

LATITUDE

18.12.19

CHINA TAIPING

20/8/2013

		PART		LIST	
1	1	BUMPER COVER REAR	\$	<i>As</i> 561.70	✓
2	1	BUMPER LOWER REAR	\$	<i>As</i> 411.90	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 98.10	X
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 82.10	X
5	1	BUMPER RETAINER RH REAR	\$	<i>SL</i> 59.80	X
6	1	BUMPER REFLECTOR RH	\$	<i>SL</i> 16.60	X
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 80.80	X
8	1	BUMPER RETAINER LH REAR	\$	<i>SL</i> 54.20	X
9	1	BUMPER REFLECTOR LH	\$	<i>SL</i> 16.60	X
10	1	BUMPER BEAM REAR	\$	<i>As</i> 547.80	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>SL</i> 114.50	} X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>SL</i> 100.90	
13	1	BUMPER BLOCK LH REAR	\$	<i>SL</i> 75.70	
14	1	BUMPER BLOCK RH REAR	\$	<i>SL</i> 76.50	
15	1	BUMPER HARNESS REAR	\$	<i>SL</i> 301.10	
16	1	BOOT REAR	\$	<i>SL</i> 1,677.20	
17	1	BOOT FINISHER	\$	<i>SL</i> 344.70	
18	1	BOOT WHEATERSTRIP	\$	<i>SL</i> 178.20	
19	1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 277.70	
20	1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 277.70	
21	1	BOOT BADGE 'RENAULT'	\$	<i>SL</i> 82.40	
22	1	BOOT BADGE	\$	<i>SL</i> 95.80	
23	1	BOOT STRUT LH	\$	<i>SL</i> 145.10	
24	1	BOOT STRUT RH	\$	<i>SL</i> 145.10	
25	1	BOOT HINGE LH	\$	<i>SL</i> 254.20	
26	1	BOOT HINGE RH	\$	<i>SL</i> 253.80	
27	1	BOOT INNER BOARD	\$	<i>SL</i> 611.00	
28	1	BOOT SWITCH	\$	<i>SL</i> 113.00	
29	1	BOOT LOCK	\$	<i>SL</i> 246.60	
30	1	BOOT LOCK CATCH	\$	<i>SL</i> 41.70	

Trans-cab Auto Services Pte Ltd**AAD1912-141**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9855K

31	2	LICENCE PLATE LAMP	\$	26.30
32	2	BOOT RUBBER PLUG	\$	139.30
33	2	BOOT BUFFER	\$	26.80
34	1	BOOT LOCK LINKAGE	\$	20.60
35	1	BOOT LOCK LINKAGE HOLDER	\$	99.50
36	1	BOOT TRIM BOARD	\$	611.00
37	1	FENDER PANEL INNER TRIM REAR LH	\$	671.45
38	1	FENDER PANEL REAR LH	\$	1,933.20
39	1	WHEELARCH REAR LH	\$	181.60
40	1	FENDER PANEL INNER TRIM REAR RH	\$	671.45
41	1	FENDER PANEL REAR RH	\$	1,933.20
42	1	WHEELARCH REAR RH	\$	275.40
43	1	AIR VENT LH	\$	59.40
44	1	AIR VENT RH	\$	59.40
45	1	TAILLAMP RH	\$	313.10
43	1	TAILLAMP PANEL RH	\$	401.40
44	1	TAILLAMP LH	\$	401.40
45	1	TAILLAMP PANEL LH	\$	401.40
46	1	OUTER PANEL REAR (End Panel)	\$	745.80
47	1	OUTER PANEL REAR (End Panel)TRIM	\$	404.56
48	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	1,229.40
49	1	SPARE WHEEL PANEL TRIM	\$	612.21
50	1	SPARE TYRE BOARD	\$	680.90
51	1	EXHAUST REAR	\$	5,263.60
52	1	EXHAUST CAP REAR	\$	125.40

Back
X

TOTAL	\$	24,630.27
10%	\$	2,463.03
	\$	22,167.24

Special Nett

1	1SET PARKING AID	\$	700.00	X
2	1SET REAR BUMPER CLIP	\$	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	66.00	✓

Trans-cab Auto Services Pte Ltd**AAD1912-141**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9855K

10	1	EXHAUST MOUNTING REAR	\$	16.00
11	1	EXHAUST BRACKET REAR	\$	24.80
12	1SET	BOOT FINISHER CLIP	\$	24.20
13	1	BOOT STICKER "Trans-cab"	\$	30.00
14	1	BOOT STICKER "6555-3333"	\$	30.00
15	1	BOOT INNER TRIM CLIP	\$	45.00
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	35.00
17	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00
18	1	SPARE TYRE	\$	330.00
19	1	FENDER INNER TRIM CLIP LH	\$	28.00
20	1	TAILLAMP CLIP RH	\$	5.00
21	2	REAR WINDSCREEN SEALANT	\$	80.00
22	1	WINDSCREEN MOULDING	\$	100.00
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00
24	1	TAILLAMP CLIP LH	\$	5.00
25	1	Rear Bumper Protector	\$	100.00
26	1	REAR LEFT TYRE	\$	300.00
27	1	REAR LEFT TYRE RIM	\$	380.00
28	1	REAR RIGHT TYRE	\$	300.00
29	1	REAR RIGHT TYRE RIM	\$	380.00
30	1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00
31	1	FENDER INNER TRIM CLIP RH	\$	28.00
32	1SET	Rear licence plate with holder	\$	80.00
TOTAL			\$	3,788.00

*See X***TOTAL PARTS \$ 25,955.24****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	<i>4401</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	<i>4201</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>~</i> 380.00	<i>X</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>~</i> 170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1912-141**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9855K

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	50
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To Rust-Proofing Of The Affected Areas.	\$	~ 170.00	X
To repair and realign rear exhaust pipe.	\$	~ 170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	~ 170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	60
To Check Electrical Lighting Concerned.	\$	170.00	10
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~ 380.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	~ 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00	X

Trans-cab Auto Services Pte Ltd**AAD1912-141**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9855K

TOTAL	\$	19,200.00
--------------	-----------	------------------

Over All Total	\$	45,155.24
-----------------------	-----------	------------------

(LUMP SUM) Repair Days~~25 DAYS~~

2 day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: