

COMFORTDELGRO ENGINEERING

Our Job Ref No 305367839

Date : 20.12.19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr RAM

Vehicle Reg No. SHA99T CCPL

17.12.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- SJC7380Y
2. The finalized amount shall be:

(a) Spare Parts after List discount	<u>\$1,739.⁹⁰85</u>
(b) Labour Charges	<u>\$1,270.00</u>
Total for Part-By-Part Repair Cost	<u>\$3,009.⁹⁰85</u>
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	
Final Lumpsum Repair cost	

To: ASHER

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : RAM

Date : 26/12/2019

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305367839
 REGN NO : SHA 999T
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 12.07.2017
 DATE/TIME IN : 17.12.2019 22:00
 ACCIDENT DATE : 17.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2269-G	PRIG4 ORNAMENT SUB-ASSY B	1 L	47.00	25.00	35.25	<i>rec</i>
0002	04-01-0302-2270-G	PRIG4 PLATE-BACK DOOR NAM	1 L	52.90	25.00	39.67	<i>rec</i>
0003	04-01-0302-2271-G	PRIG4 PLATE-BACK DOOR NAM	1 L	52.90	25.00	39.67	<i>rec</i>
0004	28-01-9999-2026-A	APP LOGO REAR BONNET CCPL	1 N	40.00	2.50-	40.00	<i>rec</i>
0005	28-01-0302-0010-A	PRIVC REAR BOOT 65521111	1 N	30.00	0.25	30.00	<i>rec</i>
0006	04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1 L	458.60	25.00	343.95	<i>cr</i>
0007	04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1 L	552.60	25.00	414.45	<i>cr</i>
0008	04-01-0302-2288-G	PRIG4 REINFORCEMENT SUB-A	1 L	318.80	25.00	239.10	<i>BT</i>
0009	04-01-0302-2267-G	PRIVC BUMPER PIECE	10 L	22.00	25.00	16.50	<i>rec</i>
0010	FNPS	NO PLATE(S) WITH TRIM COV	1 N	100.00	2.50-	100.00	<i>BT</i>
0011	28-01-0302-2016-A	PRIVC REAR BONNET COMFORT	1 N	30.00	0.25	30.00	<i>rec</i>
0012	04-01-0302-0585-A	PRIG4 LENS & BODY RR COMB	1 L	548.40	25.00	411.30	<i>cr</i>

SUB-TOTAL : 1,739.89

JOB NATURE

COMFORTDELGRO ENGINEERING PTE LTD

Date: 20.12.2019

REPAIR ESTIMATE

Time: 13:40:41

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305367839
REGN NO : SHA 999T
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 12.07.2017
DATE/TIME IN : 17.12.2019 22:0
ACCIDENT DATE : 17.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0000 L	PANEL BEATING	640.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	600.00
0002 L	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 1,270.00

TOTAL : 3,009.89

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :
AUTHORISED : YES / NO

CITY CAB PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHA 999T

18/12/2019 10:06

MAKE :

Like

CHINA

MODEL : TOYOTA PRIUS

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR TRUNK LID COVER <i>x(R)</i>			\$ 1,126.60	
REAR TRUNK LID LOCK ?			\$ 457.90	
REAR TRUNK LID GLASS (BLACK COLOR) <i>xun</i>			\$ 733.50	
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE BR <i>x(R)</i>			\$ 889.70	
REAR TRUNK LID LOGO(PRIUS) <i>rec</i>			\$ 52.90	
REAR TRUNK LID LOGO(HYBRID) <i>rec</i>			\$ 52.90	
REAR TRUNK LID LOGO(TOYOTA STAR) <i>rec</i>			\$ 47.00	
ROOF TOP GARNISH SUB, LH <i>xun</i>			\$ 72.00	
ROOF TOP GARNISH SUB, RH <i>xun</i>			\$ 75.00	
REAR BUMPER <i>cra</i>			\$ 458.60	
REAR BUMPER RE-INFORCEMENT <i>BT</i>			\$ 318.80	
REAR BUMPER UNDER COVER <i>cra</i>			\$ 552.60	
REAR BUMPER SIDE RETAINER <i>xun</i>			\$ 112.70	
REAR BUMPER CLIPS <i>rec</i>			\$ 22.00	
SEAL, REAR BUMPER SIDE, RH <i>xun</i>			\$ 148.40	
TAIL LAMP ASSY (UPPER) (LH/RH) <i>xun</i>	\$	557.90	\$ 1,115.80	
TAIL LAMP ASSY (LOWER) (LH/RH) <i>xun</i> <i>(RH)</i>	\$	548.40	\$ 1,096.80	
REAR END PANEL ?			\$ 602.10	
REAR END PANEL GARNISH ?			\$ 165.80	
SUB TOTAL			\$ 8,101.10	
LESS 25%			\$ 2,025.28	
DISCOUNTED TOTAL			\$ 6,075.83	
REAR NO. PLATE WITH TRIM COVER <i>BR</i>			\$ 100.00	NETT
REAR TRUNK LID APPS STICKER <i>rec</i>			\$ 40.00	NETT
REAR TRUNK LID COMFORT & TEL NO. STCIKER <i>rec</i>			\$ 60.00	NETT
REAR BUMPER REVERSE SENSOR <i>xun</i>			\$ 135.70	NETT
REAR FENDER ADVERTISEMENT LOGO (LH/RH) BR <i>xun</i>		100.00	\$ 200.00	NETT
			\$ 535.70	
LABOUR CHARGE				
Panel Beating			\$ 800.00	\$640
Spray Painting Charge			\$ 700.00	\$600
Wiring Charge			\$ 50.00	<i>xun</i>
Tuff Kote			\$ 50.00	<i>xun</i>
Remove/Refix Reverse Sensor			\$ 80.00	\$30
TOTAL LABOUR			\$ 1,680.00	
ESTIMATE TOTAL			\$ 8,291.53	

Ram (Like)
18/12/19 12:00pm
farasham@likeauto.com
8862778
(PIP) B&P paint photo
3 repair days

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.