

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3361Y

DATE 17/12/2019 10:03

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>DD</i>			\$ 2,174.90
	Boot Lid Lock Upper <i>xnn</i>			\$ 102.60
	Boot Lid Lock Lower <i>xnn</i>			\$ 31.70
	Boot Lid 'H' Emblem <i>rec</i>			\$ 28.70
	Boot Lid CRDI Plate <i>rec</i>			\$ 27.90
	Boot Lid Lamp (LH) <i>ora</i>			\$ 565.60
	Bootlid Moulding ?			\$ 85.00
	Bootlid i40 Emblem <i>rec</i>			\$ 27.90
	Bootlid Lower Garnish <i>xnn</i>			\$ 227.90
	Rear Bumper <i>BUL</i>			\$ 553.00
	Rear Bumper Reinforcement ?			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>rec</i>			\$ 22.00
	Rear Bumper Bracket <i>xnn</i>		\$ 35.60	\$ 71.20
	Rear Bumper Sponge ?			\$ 103.50
	Rear Bumper Under Cover <i>xnn</i>			\$ 228.00
	Rear Bumper Reflector Lamp (LH/RH) <i>xnn</i>			\$ 61.20
	Tail Lamp (LH) <i>rec</i> ?			\$ 697.80
	Rear Panel ?			\$ 526.70
	Rear Panel Garnish ?			\$ 57.70
	Rear Panel Lower Panel ?			\$ 495.50
	SUB TOTAL			\$ 6,677.80
	LESS 20% Acknowledged by Repairer			\$ 1,335.56
	DISCOUNTED TOTAL			\$ 5,342.24
	Boot Lid Comfort Logo & Tel No. Sticker <i>rec</i>			\$ 30.00
	Rear Bumper Reverse Sensor <i>xnn</i>			\$ 135.70
	Rear Bumper Rubber Mat <i>rec</i>			\$ 50.00
				\$ 215.70
	Labour Charge			
	Panel Beating		\$ 850.00	\$ 850.00
	Spray Painting Charge		\$ 750.00	\$ 750.00
	Wiring Charge		\$ 50.00	\$ 50.00
	Tuff Kote		\$ 50.00	\$ 50.00
	Remove/Refix Reverse Sensor		\$ 80.00	\$ 80.00
	Towing		\$ 60.00	\$ 60.00
	TOTAL LABOUR			\$ 1,780.00
	ESTIMATE TOTAL			\$ 7,337.94

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____
Date: _____

Mileage
photo

Rem (use)
17/12/19 1345
Parasuram
88622728 hp
34 repair days
HS
aft repair photo

\$560
\$600
xnn
\$30
\$30
?