

Our Job Ref No 305358030
Date : 26/12/2019

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax :
Attn : RAM
: SHD3361Y 5367141 28.11.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA -- SLG4044T
###
2. The finalized amount shall be:

(a) Spare Parts after List discount To: answer

(b) Labour Charges ###

Total for Part-By-Part Repair Cost ###


(c) Lumpsum Repair (if applicable) N


Total for Lumpsum repair cost after Less: 20% **\$4,000.00**

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature : 
Name : Ram
Date : 30/12/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

VEHICLE NO. : SHD3361Y

TYPE OF CASE : CHINA

JOB CARD NO. 305358030

SURVEY BY : LKK – RAM

ACC. DATE 28.11.19

DATE :

SUPPLEMENTARY OF PARTS AND LABOUR COSTS			
DESCRIPTION	QTY	ESTIMATE	REMARKS
CHECK ITEM			
REAR BUMPER REINFORCEMENT	1	\$428.80	
REAR BUMPER STAY BRACKET LH	1	\$80.30	
REAR BUMPER STAY BRACKET RH	1	\$80.30	
REAR PANEL	1	\$526.70	
REAR PANEL GARNISH	1	\$57.70	
LABOUR			
TOWING	1	\$60.00	
TOTAL:		\$1,233.80	JUMANI

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3361Y

DATE 17/12/2019 10:03

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>DP</i>			\$ 2,174.90
	Boot Lid Lock Upper <i>xnn</i>			\$ 102.60
	Boot Lid Lock Lower <i>xnn</i>			\$ 31.70
	Boot Lid 'H' Emblem <i>rec</i>			\$ 28.70
	Boot Lid CRDI Plate <i>rec</i>			\$ 27.90
	Boot Lid Lamp (LH) <i>Cra</i>			\$ 565.60
	Bootlid Moulding ? <i>xnn</i>			\$ 85.00
	Bootlid i40 Emblem <i>rec</i>			\$ 27.90
	Bootlid Lower Garnish <i>xnn</i>			\$ 227.90
	Rear Bumper <i>BUL</i>			\$ 553.00
	Rear Bumper Reinforcement <i>1 cut</i>			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) <i>1 ST</i>		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>rec</i>			\$ 22.00
	Rear Bumper Bracket <i>xnn</i>		\$ 35.60	\$ 71.20
	Rear Bumper Sponge ? <i>rec</i>			\$ 103.50
	Rear Bumper Under Cover <i>xnn</i>			\$ 228.00
	Rear Bumper Reflector Lamp (LH/RH) <i>xnn</i>			\$ 61.20
	Tail Lamp (LH) <i>rec</i> ? <i>xnn</i>			\$ 697.80
	Rear Panel <i>1 BU</i>			\$ 526.70
	Rear Panel Garnish <i>1 BU</i>			\$ 57.70
	Rear Panel Lower Panel ? <i>xnn</i>			\$ 495.50
	SUB TOTAL			\$ 6,677.80
	LESS 10% Acknowledged by Repairer			\$ 1,335.56
	DISCOUNTED TOTAL			\$ 5,342.24
	Boot Lid Comfort Logo & Tel No. Sticker <i>rec</i>			\$ 30.00
	Rear Bumper Reverse Sensor <i>xnn</i>			\$ 135.70
	Rear Bumper Rubber Mat <i>rec</i>			\$ 50.00
				\$ 215.70
	Labour Charge			
	Panel Beating		\$ 850.00	\$ 560
	Spray Painting Charge		\$ 750.00	\$ 600
	Wiring Charge		\$ 50.00	<i>xnn</i>
	Tuff Kote		\$ 50.00	430
	Remove/Refix Reverse Sensor		\$ 80.00	530
	Towing		\$ 60.00	?
	TOTAL LABOUR			\$ 1,780.00
	ESTIMATE TOTAL			\$ 7,337.94

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____
Date: _____

mileage photo

Rem (LCC) 17/12/19 1245
Paramount Motor Auto.com
886227284

3 repairings
HS
repair photo