



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2006732
INV Date 29/09/2020
Reference CC4/LPC19022505/Qba3q2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SLP 8819B
Insured Veh. GZ 5349S
Claim No. 19/19/20/VC00/022804
Policy No. Z/19/VC00/103567
Accident Date 19/12/2019
Inspection Date 20/12/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19022505/Qba3q2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 29-09-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 5349S	Veh. Inspected	SLP 8819B
Policy No.	Z/19/VC00/103567	Coverage (\$)	0.00
Claim No.	19/19/20/VC00/022804	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	20/12/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS HYBRID 1.8	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FUX03560573	Colour	SILVER
Odometer	218506	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	ROVELO	5 mm
L/H Front Tyre	195/65 R15	ROVELO	5 mm
R/H Rear Tyre	195/65 R15	ROVELO	5 mm
L/H Rear Tyre	195/65 R15	ROVELO	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	19/12/2019	Inspection Date	20/12/2019
Survey held at	LION CITY RENTALS PTE LTD 60 JALAN LAM HUAT# 04-01 CARROS CENTRE, 728862 SINGAPORE.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 8819B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED	423.90	423.90
1	REAR BUMPER CENTER PAD	CRUMPLED	552.30	552.30
1	REAR BUMPER RH RETAINER	SERVICEABLE	112.70	-
1	REAR BUMPER LH RETAINER	SERVICEABLE	112.70	-
1	REAR BUMPER REINFORCEMENT	DENTED	318.80	318.80
1	REAR BUMPER LOWER COVER	SERVICEABLE	303.90	-
1	REAR BUMPER TOW COVER	SCRATCHED	35.90	35.90
1	REAR END PANEL	SERVICEABLE	356.80	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	105.30	-
	LESS 25% DISCOUNT		-580.57	-332.72
			1,741.73	998.18
	<u>SPECIAL NETT ITEMS</u>			
1	SET BUMPER CLIPS (SN)	NECESSARY	200.00	30.00
1	SET REVERSE SENSOR (SN)	SERVICEABLE	260.00	-
			460.00	30.00
	<u>LABOUR</u>			
	TO LABOUR CHARGE FOR REMOVING REAR END PANEL, SPARE TYRE PANEL, REAR BUMPER AND REAR BUMPER REINFORCEMENT OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS.		1,200.00	400.00
	TO RESPRAY REAR BUMPER, REAR BACK DOOR, REAR BUMPER, END PANEL.		1,000.00	380.00
	TRANSFER DOOR MECHANISM TO FACILITATE REPAIRS AND REPLACEMENT OF PARTS.	NOT NECESSARY	200.00	-
	TO CONDUCT A STANDARD OF OPERATING PROCEDURES POST SCAN TEST AS AREQUIREMENTS FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS.	NOT NECESSARY	300.00	-
	TO DEACTIVATE AND ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENT FOR SAFETY PRECAUTIONS.	NOT NECESSARY	300.00	-
			3,000.00	780.00
	GRAND TOTAL		5,201.73	1,808.18

Report Ref No. CC4/LPC19022505/Qba3q2



RECOMMENDED COST OF REPAIRS			1,808.18
-----------------------------	--	--	----------

Report Ref No. CC4/LPC19022505/Qba3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLP 8819B

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

