



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2004730
INV Date 06/07/2020
Reference CC4/LPC19022509/Uba3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SFD 821E
Insured Veh. SLE 4690M
Claim No. 19/19/20/VP05/022802
Policy No. Z19VP05023557
Accident Date 18/12/2019
Inspection Date 26/12/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19022509/Uba3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 06-07-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 4690M	Veh. Inspected	SFD 821E
Policy No.	Z19VP05023557	Coverage (\$)	0.00
Claim No.	19/19/20/VP05/022802	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	20/12/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W 523I (A)	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WBAFP320X0C868460	Colour	BLACK
Odometer	121819	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 ZR19	MICHELIN	6 mm
L/H Front Tyre	245/40 ZR19	MICHELIN	6 mm
R/H Rear Tyre	275/35 ZR19	MICHELIN	6 mm
L/H Rear Tyre	275/35 ZR19	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/12/2019	Inspection Date	26/12/2019
Survey held at	SM SPRAY PAINTING PTE LTD NO. 25 KAKI BUKIT ROAD 4 #08-30 SYNERGY @ KAKI BUKIT SINGAPORE 417800		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFD 821E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DENTED / DEFORMED	1,571.95	1,571.95
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	156.70	-
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	156.70	-
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	37.75	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	37.75	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	775.95	-
1	REAR BUMPER TOWING COVER	SERVICEABLE	47.85	-
1	BOOTLID	TO REPAIR SEE LABOUR	1,650.65	-
1	BOOTLID EMBLEM	NECESSARY	71.60	71.60
1	BOOTLID "523I" EMBLEM	NECESSARY	64.45	64.45
1	REAR END PANEL	TO REPAIR SEE LABOUR	821.40	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	116.15	-
	LESS 5% DISCOUNT		-275.45	-85.40
			5,233.45	1,622.60
<u>SPECIAL NETT ITEMS</u>				
1	BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	35.00	-
4	REAR BUMPER SENSOR (SN)	SHORTED	200.00	200.00
8	END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	65.00	-
			330.00	230.00
<u>LABOUR</u>				
	TO REMOVE AND REFIT,STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REAR EXHAUST SILENCER AND MOUNTINGS.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		80.00	50.00
	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS.		30.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT,BOOTLID AND REAR END PANEL.		1,200.00	400.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	80.00	-
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	NOT NECESSARY	90.00	-
	TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING & SANDING OF SURFACES,FINAL POLISHING & WAXING ARE ALSO AVAILABLE.		800.00	600.00
			2,460.00	1,080.00
GRAND TOTAL			8,023.45	2,932.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CC4/LPC19022509/Uba3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFD 821E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFD 821E

RE-INSPECTION

