

SM SPRAY PAINTING

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ON BEHALF OF OWNER :

Policy Particulars: - THIRD PARTY CLAIM

Insured veh.	SFD821E	Excess.	NIL
Policy No.	2019-V0100715-VDP-R002	Coverage.	
Claiming Against.	SLE4690M		
Insured Under.	GREAT EASTERN GENERAL INSURANCE LIMITED		

Vehicle Particulars & Condition

Make & Model	BMW 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Engine No.	09467889N52B25AF
Chassis No.	WBAFP320X0C868460
Odometer	
Engine CC.	
Year Of Reg.	
Colour.	GREY
Parf/COE Rebate.	

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

FRONT PORTION

General Information

Accident Date. 18/12/2019
Survey held at

Yew Tee Automobile Tech Pte Ltd
SYNERGY@KB 25 KAKI BUKIT ROAD 4 #01-61 5417800

Remarks

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: 6 Days

not authorized
26/12/19
merous
the other up
3 day.
L/S

SM SPRAY PAINTING

Qty.	Description Of Parts	Pricing
1	REAR BUMPER <i>20/De</i>	\$ 1,571.95 ✓
1	REAR BUMPER SIDE RETAINER RH <i>11</i>	\$ 156.70 X
1	REAR BUMPER SIDE RETAINER LH <i>11</i>	\$ 156.70 X
1	REAR BUMPER REFLECTOR RH <i>11</i>	\$ 37.75 X
1	REAR BUMPER REFLECTOR LH <i>11</i>	\$ 37.75 X
1	REAR BUMPER REINFORCEMENT	\$ 775.95 ?
1	REAR BUMPER TOWING COVER <i>sm</i>	\$ 47.85 X
1	BOODLID <i>n</i>	\$ 1,650.65 X
1	BOODLID EMBLEM <i>ner</i>	\$ 71.60 =
1	BOOTLID "5231" EMBLEM <i>ner</i>	\$ 64.45 =
3	REAR END PANEL <i>n</i>	\$ 821.40 X
1	REAR END PANEL TOP GARNISH <i>11</i>	\$ 116.15 X

List items \$ 5,508.90
Less 5% \$ 275.45
Sub Total \$ 5,233.45

1	BUMPER CLIPS <i>ner</i>	\$ 30.00 ✓
1	REAR NUMBER PLATE <i>11</i>	\$ 35.00 X
4	REAR BUMPER SENSOR <i>shut</i>	\$ 200.00 ✓
8	END PANEL TOP GARNISH CLIP <i>nn</i>	\$ 65.00 X

S/N \$ 330.00

SM SPRAY PAINTING

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
<u>LABOUR</u>		
	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	11 \$ 180.00 X
	To Remove and Refit Rear Bumper Sensor.	\$ 80.00 50
	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	\$ 30.00 ✓
	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	\$ 1,200.00 400
	To Carry-Out Body Cavity Preservation.	11 \$ 80.00 X
	To Supply Spray Terostat Sealant On The Cutting Areas.	11 \$ 90.00 X
	To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polising & waxing are also available.	\$ 800.00 600
	LABOUR	\$ 2,460.00
	Sub Total.	\$ 8,023.45
	7% GSt	\$ 561.64
	Grand Total	\$ 8,585.09

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.