

Glockwerke

21 Kaki Bukit Road 4, #01-02

Singapore 417810

UEN: 53373583A

Repair Estimate

Vehicle number: SMJ4022D

Make and Model: Mazda 6

Chassis number: JM6GL1072K0311255

Qty Spare parts

List price

1	Front RH fender	\$	bt ✓	383.70
1	Front RH fender inner splash shield	\$	de ✓	161.40
1set	Front RH fender inner splash shield clips	\$	ner ✓	40.00
1	RH front door	\$	bt ✓	975.20
1	RH front door frame black sticker	\$	ner ✓	65.60
1	RH front door upper hinge	\$	Rx	37.40
1	RH front door lower hinge	\$	Rx	37.40
1	RH front sport rim	\$	cut ✓	1,196.80
1	RH front lower arm	\$	x	259.10
1	RH front shock absorber	\$	x	392.40
1	RH front knuckle arm	\$	?	378.10
1	RH front wheel bearing	\$	?	566.70

\$ 4,493.80

-20% \$ 898.76

\$ 3,595.04

Qty Spare parts

Special Nett

1 RH front tyre \$ x 300.00

Labour to remove, refit and replace affected parts. To panel beating affected areas. \$ 450 800.00

Putty and respray on affected areas \$ 450 800.00

Transfer RH front door inner mechanism to new door \$ 60 100.00

Apply rust coating on affected areas and panels \$ 40 80.00

Remove and replace RH front undercarriage parts \$? 100 240.00

photo.

Adjust wheel alignment system

\$ 60. 100.00

\$ 6,015.04

Tanpin 97495749
20/12/19.

lumpsum

Resurvey after repair
tanpin@lkkauto.com
04days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: