

Glockwerke

21 Kaki Bukit Road 4, #01-02

Singapore 417810

UEN: 53373583A

Repair Estimate

Vehicle number: SMJ4022D

Make and Model: Mazda 6

Chassis number: JM6GL1072K0311255

Qty	Spare parts	List price
1	Front RH fender <i>bt</i> ✓	\$ 383.70
1	Front RH fender inner splash shield <i>de</i> ✓	\$ 161.40
1set	Front RH fender inner splash shield clips <i>all</i> ✓	\$ 40.00
1	RH front door <i>bf</i> ✓	\$ 975.20
1	RH front door frame black sticker <i>hec</i> ✓	\$ 65.60
1	RH front door upper hinge <i>R</i> ✗	\$ 37.40
1	RH front door lower hinge <i>R</i> ✗	\$ 37.40
1	RH front sport rim <i>cut</i> ✓	\$ 1,196.80
1	RH front lower arm ✗	\$ 259.10
1	RH front shock absorber ✗	\$ 392.40
1	RH front knuckle arm ✗	\$ 378.10
1	RH front wheel bearing ✗	\$ 566.70
<i>nn</i>		
<i>2822.70</i>		\$ 4,493.80
<i>-20%</i>		\$ 898.76
<i>2258.16</i>		\$ 3,595.04

Qty	Spare parts	Special Nett
1	RH front tyre	\$ <i>nn</i> ✗ 300.00 ✗
	Labour to remove, refit and replace affected parts. To panel beating affected areas.	\$ <i>450</i> 800.00
	Putty and respray on affected areas	\$ <i>450</i> 800.00
	Transfer RH front door inner mechanism to new door	\$ <i>60</i> 100.00
	Apply rust coating on affected areas and panels	\$ <i>40</i> 80.00
	Remove and replace RH front undercarriage parts	\$ <i>3100</i> 240.00 <i>ph-t</i>

Adjust wheel alignment system

\$ 60 100.00

\$ 6,015.04

2258.16
1160

1160

3418.16
L/S \$2700

04 days ##

Taufik

97495749

20/12/19

Lumpsum

Resurvey after repair

taufikh@lkkauto.com

04 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: