



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

ER HOCK CHAI
BLK 121B CANBERRA STREET #11-717
SINGAPORE 752121

Attention : THE OWNER
Contact : 96617429

Estimate : ES006876

Date : 21/12/2019
Vehicle Num. : SLW8772P
Make/Model : TOYOTA VIOS E AUTO-2018
Chassis/Eng# : MR2B23F3701112514/2NR5201519
Accident Date : 21/12/2019
Claim No. :
Reference :
Policy No. :

Not Autherized
Future Repairing
4-5 day

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	2	BOOT LID		
3.	1	BOOT LID HINGES	66.90	
4.	1	VIOS EMBLEM		
5.	1	E EMBLEM		
6.	1	TOYOTA LOGO		
7.	1	BOOT LID LOCK		
8.	1	REAR BUMPER		
9.	6	REAR BUMPER REINFORCEMENT		
10.	2	REAR BUMPER CLIP		
11.	1	REAR BUMPER SIDE RETAINER		
12.	1	REAR MUDFLAP L/H		
13.	1	TAIL LAMP L/H		
14.	1	REAR END PANEL		
		REAR END PANEL TOP GARNISH		

List TotalS\$:
25.00% Discount S\$:

3,709.10
927.28

2,781.82

1. 1 SPECIAL NETT ITEMS :
REVERSE SENSOR SET

280.00 X

Special Nett Total S\$:

280.00

LABOUR :
CHANGE TAIL LAMP AND CHECK LIGHTING
RUST PROOFING TREATMENT
SPRAY PAINT DAMAGED AREA AFFECTED

65.00
100.00
1,000.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

CONTINUE / ...

Acknowledged by Repairer

Signature:

Date:



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

ER HOCK CHAI
BLK 121B CANBERRA STREET #11-717
SINGAPORE 752121

Attention : THE OWNER
Contact : 96617429

Estimate : ES006876

Date : 21/12/2019
Vehicle Num. : SLW8772P
Make/Model : TOYOTA VIOS E AUTO-2018
Chassis/Eng# : MR2B23F3701112514/2NR5201519
Accident Date : 21/12/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR L/H CORNER PANEL, REAR CHASSIS FRAMES, AND CHANGE ALL NECESSARY PARTS		1,100.00 ?
		Labour Total S\$:		2,265.00

SingDollars : Five Thousand Three Hundred Twenty-Six & Cents Eighty-Two Only

Total S\$: 5,326.82
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun