

Surveyor:

TAUFIKH

DOI:

ASSIGNMENT
24/12/2019

Date / Time : 23/12/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SHA 9878A

Name of Insured : CITYCAB PTE LTD

Insured Tel No. : HP:

Excess Sec II : \$ D.O.A : 18.12.2019

Is driver the owner? (YES / ☒ NO) Nature of Accident :

If NO, Driver Name / Age : LOH YUE KONG

Driver Tel No. : +65-83588437 (V/L: YES / NO)

Claim No. : D19008016MFSH

Policy No. : D-19092579MFSH

Make / Model : HYUNDAI I40

Place of Accident : PEOPLES PARK COMPLEX TAXI STAND

OI GIA REPORT: ☒ YES / NO : TP GIA REPORT: ☒ YES / NO

Insured Liability : % Final ? Yes / No

PC 7798E

INSRS:
WSP: EM-1 AUTO
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/Time	STAGE	DATE / PIC
	PC 7798E - X	
	SHA 9878A - CS/FCI18006196/Kqbn2; DOA: 27.3.18	
	- NS/INC17012234/Gvbe2; DOA: 21.6.17	
15/3/2020	FILE PASS TO H/MIL TO CLOSE	
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OE:	
	After call ltr to OE:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	☐
	After call ltr to OE	☐
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☐
	Towing Invoice:	☐
	LTA / GIA :	☒
	Medical Bill:	☐
	PTR:	☐
	Mandate/Reject Instruction:	☒
	LOD	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐
PRELIMINARY ADVICE Date/Time: Sent By:		
FINALIZATION Date/Time: Confirm with: Confirm by:		
Repair Cost:	\$S (days) Reduction: %	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time: 2/3/2020 Confirm with Chia Sin Mui Email ☒ Call ☐		
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. : 28	If NO or B 28, Ass. Lia : 01
Repair Cost: (w/ LRI)	\$S 4066.00	3 veh c.c., 02 nos 2nd
Loss of Rental (LOR):	\$S - (days)	
Loss of Use (LOU):	\$S 400.00 (\$ 80 x 5 days)	
Loss of Income (LOI):	\$S - (\$ x days)	
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]		
GIA/LTA Search	\$S 50.45	
Medical:	\$S -	
Disbursement:	\$S - (e.g. Tow/ Independent)	
Legal Cost	\$S -	
Total:	\$S 4516.45 Global Sum \$S:	
FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐		
Payee 1:	\$S 4516.45 Name 1: EM-1 Auto Pte Ltd	
Payee 2: (Strike if N.A.)	\$S Name 2:	
Payee 3: (Strike if N.A.)	\$S Name 3:	



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19008016MFSH
Our ref: CC4/FCI19022525/T1da3

Date: 27.12.2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

PC 7798E

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24-12-2019 at the premises of M/s EM-1 Auto Pte Ltd have the following to report:-

Workshop Estimate Amount	: S\$	6,088.88
Revised Estimate Amount	: S\$	3,996.02
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	3,996.02
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5.0 day

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : PC 7798E
Vehicle Model : TOYOTA HIACE
Accident Date : 18.12.2019
Original Reg Date : 26.02.2019

Date : 23.12.2019
Chassis : GDH2232001048
TP Ins. FIRST CAPITAL

ESTIMATE

1	1 pc	Tailgate	26.21.50		bt / 1,780.00
2	1 pc	Tailgate Badge			ne / 62.00
3	1 pc	Tailgate Sticker Emblem (Hiace)			ne / 62.00
4	1 pc	Tailgate Sticker Emblem (GL)			ne / 62.00
5	1 pc	Tailgate Windscreen Inner Seal			ne / 50.00
6	1 pc	Tailgate Inner Lock			bt / 461.60
7	1 pc	Tailgate Auto Lock Actuator			nn x 456.20
8	1 pc	Tailgate Lock Mechanism			nn x 235.10
9	1 pc	Tailgate Lock Catch			nn x 42.00
10	1 pc	Tailgate Weatherstrip			cut / 381.90
11	1 pc	Rear Bumper			de / 423.50
12	2 pcs	Rear Bumper Side Retainers	LH-RH	69.20	nn R/H x 138.40
13	1 set	Rear Bumper Clips			nn / 30 50.00
14	2 pcs	Rear Bumper Stay	x 2	18.00	bt / 72.00
15	1 pc	End Panel			bt / 994.80
16	1 pc	End Panel Top Plate			x 172.00
17	1 pc	Spare Tyre Carrier			nn x 223.60
18	1 set	Spare Tyre Carrier Bolt			x 58.20
19	1 pc	Spare Tyre Carrier Nut			x 69.50

5,794.80

Less 25%

1,448.70

4,346.10

Special Nett

1	2 pc	Tailgate Inner Sticker (Pte Hire Bus)	40.00	ne / 80.00
2	1 pc	Tailgate Sticker 80/90 KM		ne / 30.00
3	1 pc	Tailgate Sticker 70km/h		ne / 15.00
4	1 pc	Rear Windscreen Sealant		nn / 60.00
5	1 set	Body Panel Joint Sealant		nn x 120.00
6	1 set	Reverse Sensor		200mm / 250.00

385

C/F

4,901.10

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : PC 7798E
Vehicle Model : TOYOTA HIACE
Accident Date : 18.12.2019
Original Reg Date : 26.02.2019

Date : 23.12.2019
Chassis : GDH2232001048
TP Ins. FIRST CAPITAL

ESTIMATE

1	1 pc	Tailgate		bt	1,780.00
2	1 pc	Tailgate Badge		ne	62.00
3	1 pc	Tailgate Sticker Emblem (Hiace)		ne	62.00
4	1 pc	Tailgate Sticker Emblem (GL)		ne	62.00
5	1 pc	Tailgate Windscreen Inner Seal		ne	50.00
6	1 pc	Tailgate Inner Lock		bt	461.60
7	1 pc	Tailgate Auto Lock Actuator		x	456.20
8	1 pc	Tailgate Lock Mechanism		x	235.10
9	1 pc	Tailgate Lock Catch		x	42.00
10	1 pc	Tailgate Weatherstrip		wt	381.90
11	1 pc	Rear Bumper		de	423.50
12	2 pcs	Rear Bumper Side Retainers	LH-RH	69.20	RH 138.40
13	1 set	Rear Bumper Clips		ne	50.00
14	4 pcs	Rear Bumper Stay	x 2	18.00	72.00
15	1 pc	End Panel		bt	994.80
16	1 pc	End Panel Top Plate		x	172.00
17	1 pc	Spare Tyre Carrier		x	223.60
18	1 set	Spare Tyre Carrier Bolt		x	58.20
19	1 pc	Spare Tyre Carrier Nut		x	69.50

5,794.80

Less 25% 1,448.70

4,346.10

Special Nett

1	2 pc	Tailgate Inner Sticker (Pte Hire Bus)	40.00	ne	80.00
2	1 pc	Tailgate Sticker 80/90 KM		ne	30.00
3	1 pc	Tailgate Sticker 70km/h		ne	15.00
4	1 pc	Rear Windscreen Sealant		ne	60.00
5	1 set	Body Panel Joint Sealant		x	120.00
6	1 set	Reverse Sensor		200mm	250.00

C/F

4,901.10

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : PC 7798E

B/F

4,901.10

Labour charge

Panel Beating	600	1,000.00
Spray painting	700	1,000.00
Check Wiring	30	40.00
Anti rust	30	80.00
Remove and install rear winscreen.	120	140.00
Remove and install tailgate parts.	60	90.00
Remove and install carpet and interior.	50	150.00
Remove and install reverse sensor.	30	90.00
Remove and install reverse camera	30	120.00

7,611.10

Less 20% 1,522.22

Lump sum 6,088.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taylor 97495745
24/12/192/12

0 5 days

Lump sum

Resurvey after repair
see lkkauto.com

First CAP

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Business

Owner ID:

839K

Vehicle Details

Vehicle No.:

PC7798E

Vehicle to be

No

Exported:

Intended

23 Dec 2019

Deregistration Date:

Vehicle Make:

TOYOTA

Vehicle Model:

HIACE COMMUTER
GL 2.8 AT

Primary Colour:

White

Manufacturing Year:

2018

Engine No.:

1GD8347226

Chassis No.:

GDH2232001048

Maximum Power

-

Output:

Open Market Value:

\$34,814.00

Original Registration

26 Feb 2019

Date:

First Registration

26 Feb 2019

Date:

Transfer Count:

0

Actual ARF Paid:

\$1,741.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry

-

Date:

PARF Rebate

\$0.00

Amount:

Intended COE Rebate Details

COE Expiry Date:

25 Feb 2029

COE Category:

C - Goods Vehicle &
Bus

COE Period(Years):

10

QP Paid:

\$26,230.00

COE Rebate Amount:

\$24,059.00

Total Rebate Amount:

\$24,059.00

The information contained herein is correct as at 23 Dec 2019

OK

Nivitha (LKK Auto)

From: Aini Binte <Aini@msfirstcapital.com.sg>
Sent: Monday, 23 December 2019 4:41 PM
To: 'assignments@lkkauto.com'
Cc: Merina Chia
Subject: CHANGE OF WORKSHOP (FW: Arrange survey for vehicle no. PC 7798E, your ref. no. SHA9878A, DOA : 18.12.2019 TP - First Cap)
Attachments: PC7798E, FIRST CAP-23122019154658.pdf

Dear Nivitha

O/REF: D19008016MFSH

Kindly assist as 3P change workshop.

Thanks & Regards

Aini
Motor Claims Department

MS First Capital Insurance Ltd | 36 Robinson Road, City House, #16-01 Singapore 068877 | TEL: 6507 3848
Fax: 6507 3849 | Company Reg. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):
Under the PDPA, there are various requirements that regulate the processing of your personal data.
Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.
If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.
If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Caroline Cabrera <Caroline@msfirstcapital.com.sg>
Sent: Monday, December 23, 2019 4:19 PM
To: Aini Binte <Aini@msfirstcapital.com.sg>
Subject: FW: Arrange survey for vehicle no. PC 7798E, your ref. no. SHA9878A, DOA : 18.12.2019 TP - First Cap

Dear Aini,

For survey – CCPL / D19008016MFSH

Thank you & Regards,
Caroline Cabrera
Motor Claims

MS First Capital Insurance Ltd
36 Robinson Road #16-01 City House | Singapore 068877 | D: 6507 3848 | F: 6507 3849 | Reg. No. 195000106C

A member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

ans - no record - 23/12

ms 23/12

5:02pm @ 23/12/19
P: Mr. chauh.
Y: IN
agreed my on 24/12/19

¹ Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

² Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Chia Sin Muk <em1autopteltd@gmail.com>

Sent: Monday, December 23, 2019 3:52 PM

To: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Motor_Claims <Motor_Claims@msfirstcapital.com.sg>

Subject: Arrange survey for vehicle no. PC 7798E, your ref. no. SHA9878A, DOA : 18.12.2019 TP - First Cap

WITHOUT PREJUDICE

Dear Sir/Madam,

Kindly arrange survey for vehicle no. PC7798E as per attached file.
Please arrange surveyor list as soon as possible as Holiday is on the way.

Thanks & Best Regards,

Karen, on behalf of,

Chia Sin Muk (Mr)

m: (65) 9666 6556 | **o:** (65) 6452 3298 | **f:** (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: emlautopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Your Vehicle: SHA9878A (3rd Party Vehicle)

Our Vehicle: PC7798E

Date: 23.12.2019

M/s MS First Capital Insurance Ltd

36 Robinson Road

16-01 City House

Singapore 068877

By fax : 6222 3547

only 6507 3849

Dear Sir/Madam,

ACCIDENT INVOLVING PC 7798E & SHA9878A ON 18/12/2019

We refer to the above matter.

I hereby give you 2 days' notice to conduct a pre-repair survey of vehicle

PC 7798E at my premises.

Yours faithfully

Chia

Vehicle to be survey at follow:

160 Sin Ming Drive

#05-21 Sin Ming Autocity

Singapore 575722

PIC - Mr. Chia a 96666556

MOTOR SURVEY ASSIGNMENT

Date 19-12-2019 Our Ref No. D19008016MFSH
Accident Date 18-12-2019 Claim Type. Third Party
Insured Vehicle SHA9878A Third Party Vehicle. PC7798E
Survey Location 176 SIN MING DRIVE #01-10 SIN MING AUTOCARE
Contact Person. AGNES LEE
Contact No. 67486558/ 0 Fax No. 62806860
Survey Type WITHOUT PREJUDICE:
Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD
Contact Person NA Fax No. 68416315
Contact Number. NA

10am @ 23/12/19
P: Agnes
V: Not In
Report to DO PS

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop AUTOSOON PTE LTD Attention. NIL
Cc : TP Solicitor NA TP Solicitor Fax No. NA
Officer Incharge MERINA CHIA SAN SAN

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

MOTOR SURVEY ASSIGNMENT

Date	19-12-2019	Our Ref No. D19008016MFSH
Accident Date	18-12-2019	Claim Type. Third Party
Insured Vehicle	SHA9878A	Third Party Vehicle. PC7798E
Survey Location	160 SIN MING DRIVE #05-21 SIN MING AUTOCITY	
Contact Person.	CHIA SIN MUK	
Contact No.	64523298/ 96666556	Fax No. 64575776
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	EM-1 AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA

Officer Incharge MERINA CHIA SAN SAN

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI19022525/T1da3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 17-03-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9878A	Veh. Inspected	PC 7798E
Policy No.	D-19092579MFSH	Coverage (\$)	0.00
Claim No.	D19008016MFSH/1	Excess (\$)	0.00
Assign From	MERINA CHIA	Assign Date	23/12/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE COMMUTER	c.c	2754
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GDH2232001048	Colour	WHITE
Odometer	81722	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/65 R16	YOKOHAMA	6 mm
L/H Front Tyre	215/65 R16	YOKOHAMA	6 mm
R/H Rear Tyre	215/65 R16	YOKOHAMA	6 mm
L/H Rear Tyre	215/65 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	18/12/2019	Inspection Date	24/12/2019
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 7798E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	BENT	1,780.00	1,780.00
1	TAILGATE BADGE	NECESSARY	62.00	62.00
1	TAILGATE STICKER EMBLEM (HIACE)	NECESSARY	62.00	62.00
1	TAILGATE STICKER EMBLEM (GL)	NECESSARY	62.00	62.00
1	TAILGATE WINDSCREEN INNER SEAL	NECESSARY	50.00	50.00
1	TAILGATE INNER LOCK	BENT	461.60	361.00
1	TAILGATE AUTO LOCK ACTUATOR	NOT NECESSARY	456.20	-
1	TAILGATE LOCK MECHANISM	NOT NECESSARY	235.10	-
1	TAILGATE LOCK CATCH	NOT NECESSARY	42.00	-
1	TAILGATE WEATHERSTRIP	CUT	381.90	215.00
1	REAR BUMPER	DEFORMED	423.50	423.50
2	REAR BUMPER SIDE RETAINERS @\$69.20	N/S DEFORMED/ O/S NOT NECESSARY	138.40	69.20
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	30.00
4	REAR BUMPER STAY @\$18.00	BENT (2 PCS ONLY)	72.00	36.00
1	END PANEL	BENT	994.80	492.50
1	END PANEL TOP PLATE	NOT NECESSARY	172.00	-
1	SPARE TYRE CARRIER	NOT NECESSARY	223.60	-
1	SET SPARE TYRE CARRIER BOLT	NOT NECESSARY	58.20	-
1	SPARE TYRE CARRIER NUT	NOT NECESSARY	69.50	-
	LESS 25% DISCOUNT		-1,448.70	-910.80
			4,346.10	2,732.40
SPECIAL NETT ITEMS				
2	TAILGATE INNER STICKER (PTE HIRE BUS) @\$40.00 (SN)	NECESSARY	80.00	80.00
1	TAILGATE STICKER 80/90 KM (SN)	NECESSARY	30.00	30.00
1	TAILGATE STICKER 70KM/H (SN)	NECESSARY	15.00	15.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	SET BODY PANEL JOINT SEALANT (SN)	NOT NECESSARY	120.00	-
1	SET REVERSE SENSOR (SN)	NOT WORKING	250.00	200.00
			555.00	385.00

Report Ref No. CC4/FCI19022525/T1da3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING.		1,000.00	600.00
	SPRAY PAINTING.		1,000.00	700.00
	CHECK WIRING .		40.00	30.00
	ANTI RUST.		80.00	30.00
	REMOVE AND INSTALL REAR WINDSCREEN.		140.00	120.00
	REMOVE AND INSTALL TAILGATE PARTS.		90.00	60.00
	REMOVE AND INSTALL CARPET AND INTERIOR.		150.00	50.00
	REMOVE AND INSTALL REVERSE SENSOR .		90.00	30.00
	REMOVE AND INSTALL REVERSE CAMERA.		120.00	30.00
			2,710.00	1,650.00
	GRAND TOTAL		7,611.10	4,767.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00

Report Ref No. CC4/FCI19022525/T1da3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.