

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : PC 7798E
Vehicle Model : TOYOTA HIACE
Accident Date : 18.12.2019
Original Reg Date : 26.02.2019

Date : 23.12.2019
Chassis : GDH2232001048
TP Ins. FIRST CAPITAL

ESTIMATE

1	1 pc	Tailgate	26.21.50		bt ✓	1,780.00	
2	1 pc	Tailgate Badge			ne ✓	62.00	
3	1 pc	Tailgate Sticker Emblem (Hiace)			ne ✓	62.00	
4	1 pc	Tailgate Sticker Emblem (GL)			ne ✓	62.00	
5	1 pc	Tailgate Windscreen Inner Seal			ne ✓	50.00	
6	1 pc	Tailgate Inner Lock			bt ✓	461.60	361
7	1 pc	Tailgate Auto Lock Actuator			nn x	456.20	
8	1 pc	Tailgate Lock Mechanism			nn x	235.10	
9	1 pc	Tailgate Lock Catch			nn x	42.00	
10	1 pc	Tailgate Weatherstrip			cut ✓	381.90	215
11	1 pc	Rear Bumper			de ✓	423.50	
12	2 pcs	Rear Bumper Side Retainers	LH-de ✓	69.20	nn RH x	138.40	69.20
13	1 set	Rear Bumper Clips			nn ✓ 30	50.00	
14	2 pcs	Rear Bumper Stay	x 2	18.00	bt ✓	72.00	36
15	1 pc	End Panel			bt ✓	994.80	495
16	1 pc	End Panel Top Plate			x	172.00	
17	1 pc	Spare Tyre Carrier			nn x	223.60	
18	1 set	Spare Tyre Carrier Bolt			x	58.20	
19	1 pc	Spare Tyre Carrier Nut			x	69.50	
						5,794.80	3643.20
						Less 25%	1,448.70
							4,346.10

Special Nett

1	2 pc	Tailgate Inner Sticker (Pte Hire Bus)	40.00	ne ✓	80.00	
2	1 pc	Tailgate Sticker 80/90 KM		ne ✓	30.00	
3	1 pc	Tailgate Sticker 70km/h		ne ✓	15.00	
4	1 pc	Rear Windscreen Sealant		ne ✓	60.00	
5	1 set	Body Panel Joint Sealant		nn x	120.00	
6	1 set	Reverse Sensor		200nw	250.00	

385

C/F

4,901.10

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : PC 7798E

B/F

4,901.10

Labour charge

Panel Beating		600	1,000.00
Spray painting		700	1,000.00
Check Wiring		30	40.00
Anti rust		30	80.00
Remove and install rear winscreen.		120	140.00
Remove and install tailgate parts.		60	90.00
Remove and install carpet and interior.		50	150.00
Remove and install reverse sensor.		30	90.00
Remove and install reverse camera		30	120.00

Less 20% 1650 7,611.10
Lump sum 1 1,522.22
6,088.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taylin 97415745
24/12/19/11/12

05 days

Lump sum

Resurvey after repair
see thank you

4767.40
4/58 3800
05 days