

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : PC 7798E
Vehicle Model : TOYOTA HIACE
Accident Date : 18.12.2019
Original Reg Date : 26.02.2019

Date : 23.12.2019
Chassis : GDH2232001048
TP Ins. FIRST CAPITAL

ESTIMATE

1	1 pc	Tailgate		bt	1,780.00
2	1 pc	Tailgate Badge		ne	62.00
3	1 pc	Tailgate Sticker Emblem (Hiace)		ne	62.00
4	1 pc	Tailgate Sticker Emblem (GL)		ne	62.00
5	1 pc	Tailgate Windscreen Inner Seal		ne	50.00
6	1 pc	Tailgate Inner Lock		bt	461.60
7	1 pc	Tailgate Auto Lock Actuator		x	456.20
8	1 pc	Tailgate Lock Mechanism		x	235.10
9	1 pc	Tailgate Lock Catch		x	42.00
10	1 pc	Tailgate Weatherstrip		cut	381.90
11	1 pc	Rear Bumper		de	423.50
12	2 pcs	Rear Bumper Side Retainers	LH-de 69.20	RH-x	138.40
13	1 set	Rear Bumper Clips		ne	50.00
14	2 pcs	Rear Bumper Stay	x2 18.00	bt	72.00
15	1 pc	End Panel		bt	994.80
16	1 pc	End Panel Top Plate		x	172.00
17	1 pc	Spare Tyre Carrier		x	223.60
18	1 set	Spare Tyre Carrier Bolt		x	58.20
19	1 pc	Spare Tyre Carrier Nut		x	69.50

5,794.80

Less 25%

1,448.70

4,346.10

Special Nett

1	2 pc	Tailgate Inner Sticker (Pte Hire Bus)	40.00	ne	80.00
2	1 pc	Tailgate Sticker 80/90 KM		ne	30.00
3	1 pc	Tailgate Sticker 70km/h		ne	15.00
4	1 pc	Rear Windscreen Sealant		ne	60.00
5	1 set	Body Panel Joint Sealant		x	120.00
6	1 set	Reverse Sensor		200mm	250.00

C/F

4,901.10

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : PC 7798E

B/F

4,901.10

Labour charge

Panel Beating	600	1,000.00
Spray painting	700	1,000.00
Check Wiring	30	40.00
Anti rust	30	80.00
Remove and install rear winscreen.	120	140.00
Remove and install tailgate parts.	60	90.00
Remove and install carpet and interior.	50	150.00
Remove and install reverse sensor.	30	90.00
Remove and install reverse camera	30	120.00

7,611.10

Less 20% 1,522.22

Lump sum 6,088.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97415749
24/12/19/11/20

0 5 days

Lump sum

Resurvey after repair
sure thank you.