

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**WIP : 23861**

## Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1508/2019/NS
Date	:	24-Dec-19

**Vehicle NOT IN workshop. Please arrange for survey**

**Your Insured Vehicle no : SLL 5322 H**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

Owner's Name	:	Li Li
Address	:	31 Punggol Field #05-06 Singapore 828816
Telephone	:	HP +65 90032759
Type of Claim	:	Third Party Claim
Policy No.	:	1700030241-02
Vehicle No	:	<b>SLQ 8696 H</b>
Model Code	:	Audi A3 Sedan 1.0 TFSI 8V
Model / Year	:	25/7/2017
Engine No	:	CHZ 382442
Chassis No	:	WAUZZZ8V9HA143310
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	22-Dec-19
Place of Accident	:	Junction Of Punggol Rd Exit TPE Towards SLE

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLQ 8696 H

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	✓
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00	\$ 00
3	To respray rear bumper.	\$ 900.00	\$ 50
4	To carry out diagnostic check.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 2,422.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLQ 8696 H

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	REAR BUMPER / ee	\$	1,708.00	1366.4
2	REAR BUMPER STICKY PAD X {nn	2 \$	11.00	
3	REAR BUMPER FIXING PARTS X	\$	175.00	
4	REAR BUMPER LOCKING MECHANISM - LH / RH X NN	2 \$	24.00	
5	REAR BUMPER SPOILER - LH X NN	\$	216.00	
6	REAR LIGHT REFLECTOR - LH / RH X	2 \$	54.00	
7	REAR BUMPER SIDE REINFORCEMENT BEAM X {nn	\$	522.00	
8	REAR BUMPER BRACKET - LH X	\$	25.00	
9	REAR BUMPER BRACKET - RH X	\$	26.00	
10	REAR PARKING AID SENSOR - INNER/OUTER X NN	2 \$	462.00	
11	REAR PARKING AID SEAL RING X X NN	4 \$	12.00	
12	SUNDRIES X NN	\$	200.00	
TOTAL SPARE PARTS		:	\$ 3,435.00	
TOTAL LABOUR CHARGES		:	\$ 2,422.00	
GRAND TOTAL		:	\$ 5,857.00	2888.4

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

3 Days .

before paint photos.

Guo Q: ang - 82880282

26/12/19.

## Please Note

- : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant