Date/Time, File Pass to?	: Preli. Report	Day	s Of Repair: 3		
1)	: Final Report	Res	urvey No. of Trip:	Survey Fee:	160
Date/Time, File Return to?		p	name of the same o	Transportation:	
3/1 -typist		Add Fee:	: Site Insp (\$)3 +R\$\$I	
. 31			: Interview (\$) Pholos	
Report Formal:	TP		: Tech. Invs (\$) Others	
Lump Sum / US /: /3	5144.27		: Meet and (#	1	

160

Veron Chen (LKKAuto)

From:

MTCL@income.com.sg

Sent:

Friday, 3 January 2020 4:16 PM

To:

Veron Chen (LKKAuto)

Subject:

FW: REQUEST FOR CLAIM NUMBER

Hi,

Please refer to below from claim number, thanks.

Ignatius Koh Motor Insurance www.income.com.sg











At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers



From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Friday, 3 January 2020 12:24 PM

To: MTCL@income.com.sg

Subject: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Kindly provides us claim number.

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehic
		COMFORT TRANSPORTATION PTE LTD	SH 9979A	SLD 5272

D.O.A	Time of Accident	Estimate	Tentative repair cost
22/12/2019	11:35	\$7,396.90	\$5,144.27

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

eBao Tech										Genera	alClaim
Hello, NAC_PAYA_UBI_80 My Desktop		cy Query					→ Change	e Languag	e Chan	ge Password	• Log Ou
Notice of Loss	Policy No. Vehicle No.(For Motor)		SLD52	72K	Certificate Number		22/12/2019 09:16				
	Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Search Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	0	5108039457		HL LIMO PTE. LTD.	201624645Z	GPC	drivo CLASSIC		SLD5272K	08/03/2019	26/10/2020

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the lodgement of this report to the insurers, you aforesaid.	ou hereby consent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	23/12/2019 11:05
Date Of Accident	22/12/2019 11:35
Exact Location Of Accident	HOUGANG AVE 8 SLIP RD TO AVE 10
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SH9979A
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXX821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	IONIQ HYBRID

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

TAXI

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy YES

Policy Number D-18088936MFSH

Cover Note Number

Driver

Name of Driver CHUA KIN MIN NRIC No SXXXX287A Date Of Birth 25/04/1953 Occupation OUTDOOR Date Of Driving Pass 13/02/1973

Driving Experience 46 YEARS AND 10 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-91735453

Fax Number

Contact Number

EMail Address ZINNIA-GERRALLE@HOTMAIL.COM

BLK 704 HOUGANG AVENUE 2 Address

#08-231

Postcode 530704

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

OTHER - TAXI DRIVER

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes.Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLD5272K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

MOHAMED FARID BIN KHAIROMAN

NRIC/Passport Number

SXXXX429B

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRONT

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 3. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CONTROL PROGRAM TO TRANSPORT

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.

Sketch Plan Pg. 2

SKETCH PLAN DESCRIBE CIRCUMSTANCES OF THE ACCIDENT Dr. Dec. (a) 11-34 YEH (A) Slaw down Suddout UCH Rean the Le H M Kew. accident too Male Dak 1 W/ mel DECLARATION I/We declare the foregoing particulars are true in every respect. COMPONE TRANSPORTED IN DIE CO

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder)

Date & Time NRI

Name: NRIC/FIN No.:

Reporting Centre Personnel's Signature

DH 9979 A DSLD 5272 K

Durggo PK

Hougang Ave TO-

Hougang Ave 8

Hagany A ve 10















OMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 5280 Facaimile + 65 6280 9755

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun industrial Park A Singapore 768732

MILEAGE

TARGET DATE

Mainime - Workshops
Workshops
99 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
15 Dancian Road Singapore 508286 Date/Time? 002303120020019 13:43

Page : 1

JOB CARD

Sales Order:

MAKE:

MODEL

REGN NO.: SH 9979A

HYUNDAI

YR OF MANU. 11.2019

IONIQ(G3)

CHASSIS CODE RMHC851CVLU18880

JC NO.: 305369011

....1/2.. PATE 2519 12:15

COMPLETION DATE/TIME:

MER

(R)

Team:

COMFORT TRANSPORTATION PTE LTD

7010045

MER NO. 383 SIN MING DRIVE

ARC Repair TP(CLSO)1

Singapore SINGAPORE 575717

65508755

UNT CARD NO.

JOB DESCRIPTION

Accident Date: 22.12.2019


NATURE: 3P 22.12.2019

med to Service Reception upon collection

S/NO

LABOR CODE

DESCRIPTION



ED & PASSED OUT BY	193	8			
SERVICE ADVISOR				CUSTOMER'S SIGNATURE	
dgement Slip		Exit Pass	9 9		
SH 9979A	LKE	Vehicle No.:	SH 9979A		
Service Advisor	Signature/Date	Name of Service Ad	When	Date	

To be kept by Security Guard

REPAIR ESTIMATE*

VEHICLE NO: SH 9979A

MAKE :

MODEL : HYUNDAI IONIO

DATE 23/12/2019 13:23

1.1C.

NTUC

DEL	: HYUNDAI IONIQ	L	100		N	11.
Qty	Parts Description/ Labour	Type	Unit Price		Amount	
	Boot Lid 99			\$	2,480.40	
	Boot Lid Lock Upper			\$	224.00	
	Boot Lid Lock Lower XMM			\$	51.30	
	Boot Lid Key Lock Xnn			\$	141.00	
	Boot Lid 'H' Emblemnec Xnn			\$	28.00	
	Emblem -Hybridvec			S	24.30	
	Emblem -Ioniq rec			S	31.30	
	Boot Lid Glass, Lower Nec			S	384.90	
	Boot Lid Lamp (RH) Xw√			\$	794.40	
	Rear Rumper O			S	459.40	
	Rear Bumper Reinforcement			\$	294.80	
	Rear Bumper Reinforcement Bracket (LH/RH)	0	\$ 138.10	S	276.20	
	Rear Bumper Centre Moulding Assy (Vol		5 156.10	725		
				\$	451.25	
	Rear Bumper Lower Centre Moulding Assy			\$	155.00	
	Rear Bumper Stay	Consultant	to bence notify	\$	138.10	
	Rear Bumper Side Bracket (LH/RH) × vv LKK Aut	ALC: OF THE TO	MOWINGS	\$	66.20	
	Rear Bumper Cover Clips Vec - To resum	ey before/after	spray painting	\$	22.00	1
		y damaged part ces are subject t	ts) during resurvey	\$	31.90	
	Rear Panel 4 Third par	ty survey is on a	a "Without Prejudice" basis	\$	532.00	
	Rear Panel Garnish XM A	modification(s)	s allowed	\$	155.00	1
	Rear Panel Lower Panel 7 nn *Supplem is Subject	antary item(s) m to final approva	nus be resurveyed and 39.40 at from Insurance Company	\$	78.80	
	SUB TOTAL	ged by Repairer		\$	6,820.25	
	LESS-20%	,		\$	1,364.05	
	DISCOUNTED TOTAL			\$	5,456.20	
	Boot Lid Comfort Logo & Tel No. Sticker \(\)			\$	30.00	Nett
	Rear No.Plate (Va			8	25.00	1
	D N DI TI C PV			\$	30.00	1
	Rear No.Plate Trim Cover By Rear Bumper Reverse Sensor	1.0	(VC) S	9	135.70	1
	Rear Bumper Rubber Mat Ve	Barr (350 h	No.		
	APP Logo rear boquet rect you	112/19	ALYCAUTO.CO	Ф.	\$40	Nett
	Labour Change	CUEN	Call (PIP)	\$	270.70	
	Labour Charge	no no	8 Och our	0.0	500.00	36
	Panel Beating	627	1 C BO BARY	\$	700.00	56
	Spray Painting Charge	re Bair	day 10	\$	750.00	1
	Wiring Charge	18	(Spy 10/2)	\$		830
	Tuff Kote	(groto	800	\$	50.00	_
	Remove/Refix Reverse Sensor	Bro	OF OID LUS	\$	80.00	45
	TOTAL LABOUR			\$	1,630.00	
	A SHALL PROJUCTURE AND THE ARTHUR AN	1		1		
	ESTIMATE TOTAL		7396.90	\$	7,356.90	
			7396.90	\$	7,356.90	

COMFORTDELGRO ENGINEERING

Our Job Ref No 305369011		280011		LINGINEERIN				
Our Job Ref No 305369011 Date : 31.12.19				59 Loy	rtDelGro Engineering Pte Ltd rang Drive Singapore 508969 546 8156			
FINA	ALIZATIO	N FORM			1.544.5			
То	:		LKK		Fax:			
Attn			RAM					
Vehi	icle Reg l	No. SH9979A	CTPL		7	22.12.19		
The	SURVEY 3	nd estimates of the	repairs of the above-m	entioned vehicl	e are as follows:	-		
						SLD5272K		
1.	The re	pair job shall bill to:		NTUC		SLD3212R		
2.	The fir	nalized amount shall	be:					
	(a)	Spare Parts after Li	st discount			\$3,774.27		
	(b)	Labour Charges				\$1,370.00		
		Total for Part-By-P	Part Repair Cost			\$5,144.27		
	(c.)	Lumpsum Repair (if Total for Lumpsum Final Lumpsum Re	repair cost after Less:	20%	6			
3. 4.	We sh	ated normal period for all treat the above ng days	or repairs: amount as Correct a	nd Confirmed i				
5.	Thank	you for your assista	ance.		Ve confirm the e nalized amount	stimates and		
			A					
	Signat	ure:	A	s	Signature:	4		
	Signat Name		ing	_	ignature:	Pam		
	850	: LIM KWOK E	A	_ ^		Ram 3/01/1020		
	Name	: LIM KWOK E	ENG	_ ^	lame :			
For	Name Tel Fax	: LIM KWOK E	ing	_ ^	lame :			
For	Name Tel Fax	: LIM KWOK E : 62148316 : 65468156	ENG Amount	_ ^	Confirm By			
	Name Tel Fax Official	: LIM KWOK E : 62148316 : 65468156		Document	Confirm By	3/01/2020		
1. F	Name Tel Fax Official I	: LIM KWOK E : 62148316 : 65468156 Use Only		Document Attached Yes or No	Confirm By	3/01/2020		
1. F	Name Tel Fax Official I	: LIM KWOK E : 62148316 : 65468156 Use Only tem ate P/Day acome Paid		Document Attached Yes or No	Confirm By	3/01/1020		
1. F 2. L 3. S 4. L	Name Tel Fax Official I	: LIM KWOK E : 62148316 : 65468156 Use Only tem ate P/Day come Paid ees ch Fee		Document Attached Yes or No	Confirm By	3/01/1020		
1. F 2. L 3. S 4. L 5. N	Name Tel Fax Official I Rental Ra coss of In Survey Fe TA Sear	: LIM KWOK E : 62148316 : 65468156 Use Only tem ate P/Day acome Paid ees	Amount	Document Attached Yes or No	Confirm By	3/01/1020		

REPAIR ESTIMATE*

· VEHICLE NO: SH 9979A

MAKE

DATE 23/12/2019 13:23

Lice

NTU(

DEL	: HYUNDAI IONIQ			T	7
. Qty	Parts Description/ Labour	Type	Unit Price	Amount	-
	Boot Lid Lock Upper			\$ 2,480.40	1
	Boot Lid Lock Upper			\$ 224.00	(
	Boot Lid Lock Lower XXXX			\$ 51.30	1
	Boot Lid Key Lock Xnn			\$ 141.00	
	Boot Lid 'H' Emblem			\$ 28.00	×
	Emblem -Hybridvlc			\$ 24.30	H
	Emblem -Ioniq N2C			\$ 31.30	1
	Boot Lid Glass, Lower rec			\$ 384.90	1
	Boot Lid Lamp (RH) XMV	,		\$ 794.40	X
	Rear Bumper DO	1		\$ 459.40	
	Rear Bumper Reinforcement	001		\$ 294.80	1
	Rear Bumper Reinforcement Bracket (LH/RH)	BY	\$ 276.2 (138.10	\$ 276.20	V
	Rear Bumper Centre Moulding Assy (VO)			\$ 451.25	1
	Rear Bumper Lower Centre Moulding Assy Xun			\$ 155.00	X
	Rear Bumper Stay XV	1		\$ 138.10	×
	Rear Bumper Side Bracket (LH/RH) 🗙 🐪		\$ 33.10	\$ 66.20	K
	Rear Bumper Cover Clips vec			\$ 22.00	1
	Rear Bumper Reflector Lamp (RH)			\$ 31.90	X
	Rear Panel 7 Xhv			\$ 532.00	X
	Rear Panel Garnish XM A			\$ 155.00	×
	Rear Panel Lower Panel 7 XVV		\$ 39.40	\$ 78.80	×
-			(4)		
	SUB TOTAL		\$3539.64	\$ 6,820.25	
	LESS 20%		٧.	\$ 1,364.05	
	DISCOUNTED TOTAL	1		\$ 5,456.20	
	Boot Lid Comfort Logo & Tel No. Sticker W(-	27	\$ 30.00	Ne
	Rear No.Plate (Va /		\$122.13 4965	\$ 25.00	
	Rear No.Plate Trim Cover			0 20.00	1
		b 1	1450 NV 5 10 1450 NV 5 10 101/101/101/101/101/101/101/101/101/1	\$ 135.70	Ne
	Rear Bumper Rubber Mat	san (1450 00	\$ 50.00	Ne
	app kgo rear Boot	12/19	Wart 631	£\$40.	_
	23	1101	(all)	\$ 270.70	
	Labour Charge	asules			1
	Panel Beating	12217	8 Box Paris	\$ 700.00	\$
		GV	WY 2	\$ 750.00	5
	Wiring Charge	18aire	OF OIR LUS	\$ 50.00	83
	Tuff Kote	-	OF OID LINES	\$ 50.00	_
	Remove/Refix Reverse Sensor	(0x0+0	No Bo	\$ 80.00	4
	ACING FORMATION TO FORMATION OF THE PARTY OF	•		50100	
	TOTAL LABOUR			\$ 1,630.00	
	DOMAN A DD DOMAN			\$ 7,356.90	
	ESTIMATE TOTAL			\$ 7,356.90	
ł	This is an initial estimate based on a visual inspection of th	e above veb	icle. The final repair on	antum will	
		C AUDITVE VET	THE THE THIS TENSOR OF	antum will	1

Date: 31.12.2019 -Time: 08:56:06

REPAIR ESTIMATE

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO MILEAGE 305369011 SH 9979A 0000000000

MAKE MODEL HYUNDAI

MODEL DATE OF REGN IONIQ(G3) 14.11.2019

DATE/TIME IN

22.12.2019 12:15

ACCIDENT DATE

: 22.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2256-G IONIQVC PANEL ASSY-TAIL G 1 L 2,480.40 20.00 1,984.32 VV 19.44 000 0002 04-01-0104-2270-G IONIQ EMBLEM-HYBRID 1 L 24.30 20.00 0003 04-01-0104-2271-G IONIQ EMBLEM-IONIQ 1 L 31.30 20.00 25.04 m 101/10 0004 28-01-0103-0005-A (I40/SONATA)REAR BOOT LOG 1 N 20.00 10.00 18.00 rec PONIO 9.00 hec 0005 28-01-0103-0006-A (I40/SONATA)REAR BOOT TEL 1 N 10.00 10.00 1 L 384.90 20.00 307.92 0006 04-01-0104-2257-G IONIQ GLASS ASSY-TAIL GAT 1 L 459.40 20.00 367.52 DD 0007 04-01-0104-2282-G IONIQVC COVER-RR BUMPER# 1 L 451.25 20.00 361.00 (YC) 0008 04-01-0104-2533-G IONIQV2 MOULDING ASSY-RR 17.60 Nec 10°L 22.00 20.00 0009 04-01-0101-0111-G HYUNDAI BUMPER COVER CLIP 36.00 nei 1 N 40.00 10.00 0010 28-01-9999-2025-A APP LOGO REAR BONNET CTPL 1 N 135.70 10.00 122.13 50x 0011 09-01-9999-0068-A HYUNDAI REVERSE SENSOR AS NO PLATE(S) WITH TRIM COV 1 N 55.00 10.00 49.50 CVA 0012 FNPS 1 L 138.10 20.00 110.48re 0013 04-01-0104-3819-G IONIQ STAY-RR BUMPER LH

Date: 31.12.2019 Time: 08:56:06

Page: 2

REPAIR ESTIMATE

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO **REGN NO** : 305369011 : SH 9979A

MILEAGE

: 0000000000

MAKE

: HYUNDAI

MODEL

: IONIQ(G3)

DATE OF REGN : 14.11.2019 DATE/TIME IN : 22.12.2019 12:1

ACCIDENT DATE : 22.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0104-3919-G IONIQ STAY-RR BUMPER RH 1 L 138.10 20.00 110.48 MC

0015 04-01-0104-2288-G IONIQ BEAM-RR BUMPER 1 L 294.80 20.00 235.84 CA

SUB-TOTAL : 3,774.27

JOB NATURE

0000 L	PANEL BEATING	640.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	600.00
0002 17-01	CHECK ALL LIGHTING	30.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00
0004 20-22	REMOVE/REFIX REVERSE SENSOR	50.00

SUB-TOTAL : 1,370.00

Date: 31.12.2019 Time: 08:56:06

Page: 3

REPAIR ESTIMATE

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO

: 305369011

REGN NO MILEAGE : SH 9979A : 0000000000

MAKE

: HYUNDAI

MODEL : IONIQ(G3)
DATE OF REGN : 14.11.2019
DATE/TIME IN : 22.12.2019 12:1

ACCIDENT DATE : 22.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 5,144.27

AUTHORISED: YES / NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE DATE:

DATE:

Veron Chen (LKKAuto)

From:

Lim Kwok Eng limke@cdge.com.sg>

Sent:

Tuesday, 31 December 2019 10:43 AM

To:

Parasuram (LKK Auto); Veron Chen (LKKAuto)

Cc:

Roger How Keen Meng; Tan Pei Wei

Subject:

SH9979A finalize

Attachments:

2627_001.pdf; IMG_8847.JPG; IMG_8848.JPG; IMG_8849.JPG; IMG_8850.JPG; IMG_

8853.JPG; IMG_8856.JPG; IMG_8857.JPG; IMG_8858.JPG

Dear Ram / Veron,

Pls refer attachments

Best Regards Lim Kwok Eng Taxi Crash Repairs / ComfortDelgro Engineering Pte Ltd Tel. 6214-8355 / 6214-8156



This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



137					
NTU	C INCOME INSUF	RANCE CO-OPERATIVE LTD	Ref:	NS/INC1902254	6/Fvf3e2
		D UNION HOUSESINGAPORE	Date:	07-01-2020	
U			Code:	INC4	
1.		Policy Particulars	_		
	Insured Veh.	SLD 5272K	_	nspected	SH 9979A
	Policy No.	5108039457	_	age (\$)	0.00
	Claim No.	MT/1076809-002	Exces		0.00
	Assign From		Assig	n Date	23/12/2019
2.		Vehicle Parti	culars &	Condition	In the second second second
	Make & Model	HYUNDAI IONIQ	c.c		1580
	Engine No.	HIDDEN	Year o	of Reg.	2019
	Chassis No.	KMHC851CVLU188802	Colou	r	BLUE
	Odometer	18688	Steeri	ng	IN ORDER
	Brakes	IN ORDER Modification		SPORTS RIM	
	General	GOOD			
3.		Conditi	ons of	Tyres	
		Size	Make		Balance
	R/H Front Tyre	195/65 R15	MICHE	LIN	8 mm
	L/H Front Tyre	195/65 R15	MICHE	LIN	8 mm
	R/H Rear Tyre	195/65 R15	MICHE	LIN	8 mm
	L/H Rear Tyre	195/65 R15	MICHE	LIN	8 mm
4.		Descripti	on of Da	amages	INCLUDE THE RESIDENCE
	THE VEHICLE SU	STAINED DAMAGES AT THE RE	AR POR	TION.	
	DAMAGES SEE D	ETAILS.			
5.		Genera	I Inform	ation	
	Accident Date	22/12/2019	Inspec	ction Date	23/12/2019
	Survey held at	COMFORTDELGRO ENGINEER		HERMINGS.	And the state of t
		59 LOYANG DRIVE SINGAPORE 508969			
5a.		R	emarks		
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W			
5b.		Estimate	Days of	Repair	
	FOTHATED HOD	MAL DEDICE FOR BERLIN		0 M/	

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 9979A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOT LID	DENTED	2,480.40	2,480.40
1	BOOT LID LOCK UPPER	NOT NECESSARY	224.00	-
1	BOOT LID LOCK LOWER	NOT NECESSARY	51.30	-
1	BOOT LID KEY LOCK	NOT NECESSARY	141.00	5
1	BOOT LID 'H' EMBLEM	NOT NECESSARY	28.00	
1	EMBLEM - HYBRID	NECESSARY	24.30	24.30
1	EMBLEM - IONIQ	NECESSARY	31.30	31.30
1	BOOT LID GLASS, LOWER	NECESSARY	384.90	384.90
1	BOOT LID LAMP (RH)	NOT NECESSARY	794.40	
1	REAR BUMPER	DENTED	459.40	459.40
1	REAR BUMPER REINFORCEMENT	CUT	294.80	294.80
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$138.10	NECESSARY	276.20	276.20
1	REAR BUMPER CENTRE MOULDING ASSY	CRACKED	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	NOT NECESSARY	155.00	-
1	REAR BUMPER STAY	NOT NECESSARY	138.10	
2	REAR BUMPER SIDE BRACKET (LH/RH) @\$33.10	NOT NECESSARY	66.20	-
10	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER REFLECTOR LAMP (RH)	NOT NECESSARY	31.90	-
1	REAR PANEL	NOT NECESSARY	532.00	
1	REAR PANEL GARNISH	NOT NECESSARY	155.00	9
2	REAR PANEL LOWER PANEL @\$39.40	NOT NECESSARY	78.80	-
	LESS 20% DISCOUNT		-1,364.05	-884.91
			5,456.20	3,539.64
	NETT ITEMS			
1	BOOT LID COMFORT LOGO & TEL NO. STICKER (N)	NECESSARY	30.00	30.00
1	REAR NO. PLATE (N)	CRACKED	25.00	25.00
1	REAR NO. PLATE TRIM COVER (N)	BROKEN	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (N)	SHORT CIRCUIT	135.70	135.70
1	REAR BUMPER RUBBER MAT (N)	NOT NECESSARY	50.00	-

Report Ref No. NS/INC19022546/Fvf3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	APP LOGO REAR BONNET (N)	NECESSARY	40.00	40.00
	LESS 10% DISCOUNT		-	-26.07
			310.70	234.63
	LABOUR			
	PANEL BEATING.		700.00	640.00
	SPRAY PAINTING CHARGE.		750.00	600.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	50.00
	REMOVE / REFIX REVERSE SENSOR.		80.00	50.00
			1,630.00	1,370.00
	GRAND TOTAL		7,396.90	5,144.27

RECOMMENDED COST OF REPAIRS (CONFIRMED)		5,144.27
-----------------------------------------	--	----------

Report Ref No. NS/INC19022546/Fvf3e2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

M

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.