

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 23385

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1501/2019/NS
Date : 21-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Siow Oi Lin
Address : 73 Chishurst Grove
Singapore 558656
Telephone : (HP) +65 98389982
Type of Claim : Own Damage Claim
Policy No. : 2100437985-04
Vehicle No : **SGV 1616 T**
Model Code : Audi A4 1.8 TFSI MU
Model / Year : Nov-15
Engine No : CJE 112319
Chassic No. : WAUZZZ8K7FA174851
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Dec-19
Place of Accident : Clementi Rd / Commonwealth West Ave

Telefax

Estimated Labour Charges for Accident Vehicle. SGV 1616 T

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer Assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper, bonnet and both headlights. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00 500 ✓	
3	To respray front bumper and bonnet.	\$ 2,000.00 550 ✓	
4	To carry out diagnostic check	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 5,352.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGV 1616 T

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Regis</i>	\$ 2,100.00	*
2	FRONT BUMPER FIXING PARTS	\$ 234.00	+
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 207.00	+
4	FRONT BUMPER GRILLE - LOWER CENTRE	\$ 123.00	+
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>Carbide</i>	\$ 177.00	✓ 141.20 ✓
6	FRONT BUMPER SUPPORT ELEMENT - UPPER <i>HEM</i>	\$ 54.00	+
7	RADIATOR GRILLE <i>Carbide</i>	\$ 1,005.00	✓ 804
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>HEM</i>	2 \$ 246.00	+
9	FRONT WHEEL SPOILER - LH / RH <i>HEM</i>	2 \$ 90.00	+
10	FRONT BUMPER FOAM FILLER PIECE <i>RH HEM</i>	\$ 113.00	? X
11	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>HEM</i>	\$ 802.00	? X
12	FRONT BUMPER SUPPORT <i>HEM</i>	2 \$ 23.00	+
13	FRONT BUMPER COVER <i>HEM</i>	\$ 116.00	+
14	FRONT BUMPER GUIDE SECTION - LH / RH <i>HEM</i>	2 \$ 66.00	+
15	CAUTION SIGN STICKER <i>HEM</i>	NEC \$ 13.00	+
16	AIRCON STICKER <i>HEM</i>	NEC \$ 22.00	+
17	SIGNAL HORN - RH LOW TONE <i>HEM</i>	\$ 184.00	+
18	SIGNAL HORN - LH HIGH TONE <i>HEM</i>	\$ 184.00	+
19	SPRING SHACKLE - RH / LH	2 \$ 46.00	+
20	BONNET <i>HEM</i>	\$ 2,549.00	+
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 8,354.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGV 1616 T

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
21	BONNET PROTECTIVE FILM - FRONT	\$	42.00	X
22	BONNET ATTACHMENT PARTS	\$	152.00	X
23	BONNET CATCH HOOK	\$	127.00	X
24	BONNET GAS FILLED STRUT - LH	\$	109.00	X
25	BONNET EDGE PROTECTION - FRONT	\$	25.00	X
26	BONNET LID LOCK	\$	196.00	X
27	MICRO SWITCH	\$	67.00	X
28	BONNET LOCK COVER	\$	21.00	X
29	HEADLIGHT MOUNTING - LH / RH	2 \$	214.00	X
30	HEADLAMP BRACKET - LH / RH	2 \$	192.00	X
31	HEADLIGHT - LH / RH	2 \$	4,304.00	X
32	HALOGEN FOG LAMP - LH / RH	2 \$	484.00	X
33	RADIATOR AIR GUIDE - LH / RH	2 \$	48.00	X
34	FRONT NO PLATE	S/N \$	40.00	✓
35	SUNDRIES	\$	300.00	?

TOTAL SPARE PARTS CHARGES

: \$ 14,675.00

TOTAL LABOUR CHARGES

: \$ 5,352.00

GRAND TOTAL CHARGES

: \$ 20,027.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Admin
Surveyed Date : 23/12/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorized, 03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 23385

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1501/2019/NS
Date : 21-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,
3 days - ok - Jy - 30 Mar 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Siow Oi Lin
Address : 73 Chishurst Grove
Singapore 558656
Telephone : (HP) +65 98389982
Type of Claim : Own Damage Claim
Policy No. : 2100437985-04
Vehicle No : **SGV 1616 T**
Model Code : Audi A4 1.8 TFSI MU
Model / Year : Nov-15
Engine No : CJE 112319
Chassic No. : WAUZZZ8K7FA174851
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Dec-19
Place of Accident : Clementi Rd / Commonwealth West Ave

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGV 1616 T

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
2	To dismantle and renew front bumper, bonnet and both headlights. Re-organise crash management components. Reinstall all parts removed.	\$	2,800.00	\$ 500.00
3	To respray front bumper and bonnet.	\$	2,000.00	\$ 550.00
4	To carry out diagnostic check	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,352.00	\$ 1,602.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGV 1616 T

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,100.00	
2	FRONT BUMPER FIXING PARTS	\$ 234.00	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 207.00	
4	FRONT BUMPER GRILLE - LOWER CENTRE	\$ 123.00	
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	\$ 177.00	\$ 141.20
6	FRONT BUMPER SUPPORT ELEMENT - UPPER	\$ 54.00	
7	RADIATOR GRILLE	\$ 1,005.00	\$ 804.00
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 246.00	
9	FRONT WHEEL SPOILER - LH / RH	2 \$ 90.00	
10	FRONT BUMPER FOAM FILLER PIECE	\$ 113.00	
11	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 802.00	
12	FRONT BUMPER SUPPORT	2 \$ 23.00	
13	FRONT BUMPER COVER	\$ 116.00	
14	FRONT BUMPER GUIDE SECTION - LH / RH	2 \$ 66.00	
15	CAUTION SIGN STICKER	NEC \$ 13.00	
16	AIRCON STICKER	NEC \$ 22.00	
17	SIGNAL HORN - RH LOW TONE	\$ 184.00	
18	SIGNAL HORN - LH HIGH TONE	\$ 184.00	
19	SPRING SHACKLE - RH / LH	2 \$ 46.00	
20	BONNET	\$ 2,549.00	
SUB TOTAL SPARE PARTS CHARGES		: \$ 8,354.00	\$ 945.20

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGV 1616 T

		Damaged Parts & Prices	
S/N	Parts Description	S/Nett	Remarks
			\$ 945.20
	c/f		
21	BONNET PROTECTIVE FILM - FRONT	\$ 42.00	
22	BONNET ATTACHMENT PARTS	\$ 152.00	
23	BONNET CATCH HOOK	\$ 127.00	
24	BONNET GAS FILLED STRUT - LH	\$ 109.00	
25	BONNET EDGE PROTECTION - FRONT	\$ 25.00	
26	BONNET LID LOCK	\$ 196.00	
27	MICRO SWITCH	\$ 67.00	
28	BONNET LOCK COVER	\$ 21.00	
29	HEADLIGHT MOUNTING - LH / RH	2 \$ 214.00	
30	HEADLAMP BRACKET - LH / RH	2 \$ 192.00	
31	HEADLIGHT - LH / RH	2 \$ 4,304.00	
32	HALOGEN FOG LAMP - LH / RH	2 \$ 484.00	
33	RADIATOR AIR GUIDE - LH / RH	2 \$ 48.00	
34	FRONT NO PLATE	S/N \$ 40.00	\$ 40.00
35	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS CHARGES		: \$ 14,675.00	\$ 985.20
TOTAL LABOUR CHARGES		: \$ 5,352.00	\$ 1,602.00
GRAND TOTAL CHARGES		: \$ 20,027.00	\$ 2,587.20

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.