

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 23590

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1498/2019/NS
Date : 21-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Siow Oi Lin
Address : 73 Chiselhurst Grove
Singapore 558656
Telephone : HP +65 98389982
Type of Claim : Own Damage Claims
Policy No. : 2100437985-04
Vehicle No : **SGV 1616 T**
Model Code : Audi A4 Sedan 1.8 TFSI MU
Model / Year : Nov-15
Engine No : CJE 112319
Chassis No : WAUZZZ8K7FA174851
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Oct-19
Place of Accident : B2 Carpark Triple One Somerset Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGV 1616 T

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00 ✓	
2	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N \$ 600.00 ✓	
3	To install rear windscreen solar film.	S/N \$ 400.00 ✗	X
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00 ✓	
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00 ✓	
SUB TOTAL LABOUR CHARGES		: <u>\$ 4,160.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGV 1616 T

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To remove and transfer rhs rear door's multi-lock system and power window devices. Check function and renew if necessary.	S/N \$ 280.00 ✓	
7	To dismantle rear bumper, rear lid and rhs rear door. Cut out and weld rhs rear fender. To renew rhs rear door and rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 6,300.00 3500 ✓	
8	To respray rear bumper, rhs front door, rhs rear door, door handle, rhs rear fender, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	2850 2850 ✓ 2300 2300 ✓ \$ 6,300.00 2750 ✓ Handle = 100	1.5 x 550 = 2750 Handle = 100
9	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00 ✓	
10	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 17,512.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGV 1616 T

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Neu</i>	\$ 2,100.00	<i>+</i>
2	REAR BUMPER STICKY PAD	4 \$ 21.00	<i>+</i>
3	REAR BUMPER FIXING PARTS	\$ 206.00	<i>+</i>
4	REAR BUMPER GUIDE SECTION - RH	\$ 41.00	<i>+</i>
5	REAR BUMPER GUIDE SECTION - RH UPPER	\$ 20.00	<i>+</i>
6	SIDE PANEL - RH <i>Dented</i>	\$ 2,353.00	<i>✓ 1882.40</i>
7	REAR WINDSCREEN <i>3m</i>	\$ 1,030.00	<i>✓ 824</i>
8	SIDE WINDOW - RH	\$ 278.00	<i>✓ 272.40</i>
9	SIDE WINDOW TRIM STRIPS - RH REAR <i>neu</i>	\$ 298.00	<i>+</i>
10	REAR DOOR - RH <i>Dented</i>	\$ 2,639.00	<i>✓ 2111.20</i>
11	REAR DOOR ATTACHMENT PARTS <i>neu</i>	\$ 76.00	<i>+</i>
12	REAR DOOR OUTER SEAL - RH <i>neu</i>	NEC \$ 201.00	<i>✓ 162.80</i>
13	BONDING AGENT <i>3 Neu Neu</i>	NEC \$ 45.00	<i>?</i> <i>X</i>
14	CLEANING SOLUTION	NEC \$ 65.00	<i>?</i> <i>X</i>
15	REAR DOOR CATCH <i>neu</i>	\$ 109.00	<i>+</i>
16	REAR ALUMINIUM RIM - RH <i>lit</i>	\$ 1,162.00	<i>✓ 729.60</i>
17	ALUMINIUM RIM RUBBER VALVE <i>neu</i>	4 \$ 13.00	<i>+</i>
18	WHEEL HOUSING LINER - RH <i>neu</i>	\$ 207.00	<i>+</i>
19	WHEEL HOUSING LINER ATTACHMENT PARTS <i>neu</i>	\$ 41.00	<i>+</i>
20	ACRYLIC SEALANT <i>Neu</i>	S/N \$ 180.00	<i>✓</i>
SUB TOTAL SPARE PARTS		: \$ 11,085.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGV 1616 T

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	CAVITY WAX	S/N \$	140.00 //
22	STONE CHIP	S/N \$	180.00 //
23	METAL FILLER POWDER	S/N \$	280.00 //
24	REAR WINDSCREEN SEALANT	S/N \$	200.00 //
25	1/4 GLASS SEALANT	S/N \$	100.00 //
26	SUNDRIES	\$	400.00 ? X
TOTAL SPARE PARTS		:	\$ 12,385.00
TOTAL LABOUR CHARGES		:	\$ 17,512.00
GRAND TOTAL		:	\$ 29,897.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adain King
23/12/19.0
:
:
:
:
: Not Antloased, 13 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 23590

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1498/2019/NS
Date : 21-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian,
13 days - ok - Jy - 30 Mar 20

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Siow Oi Lin
Address : 73 Chiselhurst Grove
Singapore 558656
Telephone : HP +65 98389982
Type of Claim : Own Damage Claims
Policy No. : 2100437985-04
Vehicle No : **SGV 1616 T**
Model Code : Audi A4 Sedan 1.8 TFSI MU
Model / Year : Nov-15
Engine No : CJE 112319
Chassis No : WAUZZZ8K7FA174851
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Oct-19
Place of Accident : B2 Carpark Triple One Somerset Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGV 1616 T

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$	360.00	\$ 360.00
2	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N \$	600.00	\$ 600.00
3	To install rear windscreen solar film.	S/N \$	400.00	
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	\$ 1,400.00
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, luggage compatment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,400.00	\$ 1,400.00
SUB TOTAL LABOUR CHARGES		:	\$ 4,160.00	\$ 3,760.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGV 1616 T

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
		<i>c/f</i>		\$ 3,760.00
6	To remove and transfer rhs rear door's multi-lock system and power window devices. Check function and renew if necessary.	S/N	\$ 280.00	\$ 280.00
7	To dismantle rear bumper, rear lid and rhs rear door. Cut out and weld rhs rear fender. To renew rhs rear door and rear bumper. Re-organise crash management components. Reinstall all parts removed.		\$ 6,300.00	\$ 3,500.00
8	To respray rear bumper, rhs front door, rhs rear door, door handle, rhs rear fender, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.		\$ 6,300.00	\$ 2,850.00
9	To renew rhs rear rim and carry out wheel alignment.	S/N	\$ 280.00	\$ 280.00
10	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 17,512.00</u>	<u>\$ 10,862.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGV 1616 T

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 2,100.00	
2	REAR BUMPER STICKY PAD	4 \$ 21.00	
3	REAR BUMPER FIXING PARTS	\$ 206.00	
4	REAR BUMPER GUIDE SECTION - RH	\$ 41.00	
5	REAR BUMPER GUIDE SECTION - RH UPPER	\$ 20.00	
6	SIDE PANEL - RH	\$ 2,353.00	\$ 1,882.40
7	REAR WINDSCREEN	\$ 1,030.00	\$ 824.00
8	SIDE WINDOW - RH	\$ 278.00	\$ 222.40
9	SIDE WINDOW TRIM STRIPS - RH REAR	\$ 298.00	
10	REAR DOOR - RH	\$ 2,639.00	\$ 2,111.20
11	REAR DOOR ATTACHMENT PARTS	\$ 76.00	
12	REAR DOOR OUTER SEAL - RH	NEC \$ 201.00	\$ 160.80
13	BONDING AGENT	NEC \$ 45.00	
14	CLEANING SOLUTION	NEC \$ 65.00	
15	REAR DOOR CATCH	\$ 109.00	
16	REAR ALUMINIUM RIM - RH	\$ 1,162.00	\$ 929.60
17	ALUMINIUM RIM RUBBER VALVE	4 \$ 13.00	
18	WHEEL HOUSING LINER - RH	\$ 207.00	
19	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 41.00	
20	ACRYLIC SEALANT	S/N \$ 180.00	\$ 180.00
SUB TOTAL SPARE PARTS		: \$ 11,085.00	\$ 6,310.40

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Material List for Accident Vehicle Regn No. SGV 1616 T

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
			\$ 6,310.40
		c/f	
21	CAVITY WAX	S/N \$ 140.00	\$ 140.00
22	STONE CHIP	S/N \$ 180.00	\$ 180.00
23	METAL FILLER POWDER	S/N \$ 280.00	\$ 280.00
24	REAR WINDSCREEN SEALANT	S/N \$ 200.00	\$ 200.00
25	1/4 GLASS SEALANT	S/N \$ 100.00	\$ 100.00
26	SUNDRIES	\$ 400.00	
TOTAL SPARE PARTS		:	\$ 12,385.00 \$ 7,210.40
TOTAL LABOUR CHARGES		:	\$ 17,512.00 \$ 10,862.00
GRAND TOTAL		:	\$ 29,897.00 \$ 18,072.40