

**S&H Motor Pte Ltd**  
**160 Sin Ming Drive #07-02**  
**Sin Ming Autocity**  
**Singapore 575722**

**Insurer Reference:**  
**Repairer Reference: 025033**  
**Date calculated: 23/12/2019 6:01 PM**

**Full Report**  
**Registration: SJZ9019H**  
**Printed: 23/12/2019 6:01 PM**

## Summary Information

|                               |                |                          |                         |
|-------------------------------|----------------|--------------------------|-------------------------|
| <b>Claim</b>                  |                | <b>Work Provider:</b>    | China Taiping Insurance |
| <b>Location:</b>              | Singapore (SG) |                          | (Singapore) Pte Ltd     |
| <b>Printed by:</b>            | SH Motor       | <b>Currency:</b>         | SGD                     |
| <b>Claim Reference:</b>       |                | <b>Date of Incident:</b> | 15/12/19                |
| <b>Estimated Repair Time:</b> |                | <b>Hire Car Start:</b>   |                         |
| <b>Actual Repair Days:</b>    |                | <b>Hire Car End:</b>     |                         |

## Vehicle Details

**Vehicle**  
**Manufacturer:** VW  
**Model:** TOURAN (1T3)  
**Sub Model:** TRENDLINE  
**Model Sheet Number:** 06 CA 01  
**Registration:** SJZ9019H  
**VIN number:** WVGZZZ1TZW017420  
**Odometer:**

### Model Specs

|                    |                      |                      |                     |
|--------------------|----------------------|----------------------|---------------------|
| FROM 09/2010       | SAFE SECURITY        | CLIMATRONIC          | RADIO RCD 310       |
| RAIN SENSOR        | LIGHT SWITCHING AUTO | ELEC FOLD DR MIRRORS | AUTO DIPPING MIRROR |
| 8 SPEAKER          | EQUIP CLOTH CHARLY   | HEIGHT ADJ PASS SEAT | 3RD SEAT ROW        |
| LEATHER STRG WHEEL | OIL LEVEL GAUGE      | FRONT CENTRE ARMREST | SMOKER EQUIPMENT    |
| 1.4 LTR 103 KW     | 7-SPEED DSG          | UPHILL TRACTION CONT | WHEELS 6J X 16      |
| HD COOLING         | ROOF RAILS           | TWO COAT METALLIC    | PREPARE OFF VEHICLE |

*Ex*  
  
*Not Authorized*  
*May be 7/10/19*  
*7 days*  
*Fax: 62564315*

## Labour

**Time Base 10 WU/h**

**Price = 42.00 SGD/h**  
**WU Price SGD**

| Code        | Description                                                     |     |       |
|-------------|-----------------------------------------------------------------|-----|-------|
| 10 83 19 00 | R + R ENGINE COVER                                              | 2.0 | 8.40  |
| 87 03 17 00 | DRAIN + REFILL REFRIGERANT                                      | 5.0 | 21.00 |
| 63 29 19 00 | R + R FRONT BUMPER COVER                                        | 7.0 | 29.40 |
| 63 29 55 50 | RENEW FRONT BUMPER COVER (REMOVED)                              | 5.0 | 21.00 |
|             | INCLUDES: CONVERT ATTACHED PARTS                                |     |       |
| 94 15 55 50 | RENEW L/HEADLAMP (REMOVED)                                      | 1.0 | 4.20  |
| 94 15 55 50 | RENEW R/HEADLAMP (REMOVED)                                      | 1.0 | 4.20  |
| 50 55 19 50 | R + R LEFT FRONT WING (BUMPER COVER REMOVED)                    | 9.0 | 37.80 |
|             | INCLUDES: WHEEL, W-HOUSE LINER AND CORN-WINDOW REMOVE AND REFIT |     |       |
| 50 55 51 50 | L/F WING SEAL (COMPOSITE WORK)                                  | 3.0 | 12.60 |
| 50 55 19 50 | R + R RIGHT FRONT WING (BUMPER COVER REMOVED)                   | 9.0 | 37.80 |

| Code                             | Description                                                                                            | WU           | Price SGD     |
|----------------------------------|--------------------------------------------------------------------------------------------------------|--------------|---------------|
|                                  | INCLUDES: WHEEL, W-HOUSE LINER AND CORN-WINDOW REMOVE AND REFIT                                        | 3.0          | 12.60         |
| 50 55 51 50                      | R/F WING SEAL (COMPOSITE WORK)                                                                         | 7.0          | 29.40         |
| 55 22 19 00                      | REMOVE/REFIT BONNET PANEL                                                                              |              |               |
|                                  | INCLUDES: ADJUST BONNET CLEARANCES                                                                     | 5.0          | 21.00         |
| 55 22 55 50                      | RENEW BONNET<br>(BONNET REMOVED)                                                                       |              |               |
|                                  | INCLUDES: R + R ALL PARTS                                                                              | 3.0          | 12.60         |
| 55 25 56 50                      | RENEW BOTH FRONT BONNET HINGES<br>(BONNET REMOVED)                                                     | 13.0         | 54.60         |
| 50 38 19 50                      | R + R FRONT LOCK CARRIER<br>(BUMPER COVER REMOVED)                                                     |              |               |
|                                  | INCLUDES: R + R NOISE CONTROL PAN<br>DOES NOT INCLUDE: ADJUST HEADLAMPS,<br>DRAIN + REFILL REFRIGERANT | 11.0         | 46.20         |
| 50 38 55 50                      | RENEW FRONT LOCK CARRIER (REMOVED)                                                                     |              |               |
|                                  | INCLUDES: CONVERT ATTACHED PARTS                                                                       | 2.0          | 8.40          |
| 92 60 19 50                      | R + R WASHER RESERVOIR<br>(BUMPER COVER REMOVED)                                                       |              |               |
|                                  | INCLUDES: R + R WASHER PUMP                                                                            | 1.0          | 4.20          |
| 92 60 55 50                      | RENEW WASHER RESERVOIR<br>(REMOVED)                                                                    | 4.0          | 16.80         |
| 87 44 19 50)                     | R + R CONDENSER/EVAPORATOR PIPE<br>(BUMPER COVER REMOVED)                                              |              |               |
|                                  | DOES NOT INCLUDE: DRAIN + REFILL<br>REFRIGERANT                                                        | 4.0          | 16.80         |
| 87 43 19 50                      | R + R COMPRESSOR/CONDENSER PIPE<br>(SOUND PROTECTION PAN REMOVED)                                      |              |               |
|                                  | DOES NOT INCLUDE: DRAIN + REFILL<br>REFRIGERANT                                                        | 4.0          | 16.80         |
| 19 40 19 00                      | R + R OVERFLOW TANK                                                                                    | 3.0          | 12.60         |
| 19 70 55 50                      | RENEW RADIATOR (REMOVED)                                                                               |              |               |
|                                  | INCLUDES: CONVERT ATTACHED PARTS                                                                       | 2.0          | 8.40          |
| 19 20 55 73                      | RENEW COOLING BLOWER HOUSING<br>INCLUDES: R + R ELECTRIC FAN                                           | 4.0          | 16.80         |
| 24 25 19 23                      | R + R AIR CLEANER                                                                                      | 1.0          | 4.20          |
| 21 32 19 23)                     | R + R HOT AIR PANEL                                                                                    | 3.0          | 12.60         |
| 94 15 16 00                      | ADJUST HEADLAMPS                                                                                       | 20.0* 7      | 84.00         |
| 1163                             | L/UPP OUT SIDEMEMBER REPAIR                                                                            | 20.0* 7      | 84.00         |
| 1164                             | R/UPP OUT SIDEMEMBER REPAIR                                                                            | 30.0* 7      | 126.00        |
| 1201                             | L/F SIDE MEMBER CPL REPAIR                                                                             | 30.0* 7      | 126.00        |
| 1202                             | R/F SIDE MEMBER CPL REPAIR                                                                             |              |               |
| <b>Labour Cost</b>               |                                                                                                        | <b>Hrs</b>   | <b>WU</b>     |
| <b>Panel / Mechanical Labour</b> |                                                                                                        | <b>21.20</b> | <b>212.0</b>  |
| <b>Total of Labour</b>           |                                                                                                        |              | <b>890.40</b> |

## Paint

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

| Code | Description - TWO COAT METALLIC | WU   | Price SGD |
|------|---------------------------------|------|-----------|
|      | BONNET NEW PART PAINTING        | 20.0 |           |
|      | L/F WING NEW PART PAINTING      | 10.0 |           |
|      | R/F WING NEW PART PAINTING      | 10.0 |           |

## Paint Work

## SYSTEM AZT

Time Basis 10 WU/h

| Code | Description - TWO COAT METALLIC    | WU   | Price SGD |
|------|------------------------------------|------|-----------|
|      | FRONT BUMPER NEW PART PAINT K1R    | 12.0 |           |
|      | L/F SIDE MEMBER CPL SURFACE PAINT  | 4.0  |           |
|      | R/F SIDE MEMBER CPL SURFACE PAINT  | 4.0  |           |
|      | L/UPP OUT SIDEMEMBER SURFACE PAINT | 4.0  |           |
|      | R/UPP OUT SIDEMEMBER SURFACE PAINT | 4.0  |           |
|      | LEFT FRONT DOOR SURFACE PAINT      | 8.0  |           |
|      | RIGHT FRONT DOOR SURFACE PAINT     | 8.0  |           |

## Paint Material Per Part

| Code | Description                        | Price SGD |
|------|------------------------------------|-----------|
| 0471 | BONNET NEW PART PAINTING           | 63.98     |
| 0741 | L/F WING NEW PART PAINTING         | 19.09     |
| 0742 | R/F WING NEW PART PAINTING         | 19.09     |
| 0283 | FRONT BUMPER NEW PART PAINT K1R    | 60.02     |
| 1201 | L/F SIDE MEMBER CPL SURFACE PAINT  | 2.99      |
| 1202 | R/F SIDE MEMBER CPL SURFACE PAINT  | 2.99      |
| 1163 | L/UPP OUT SIDEMEMBER SURFACE PAINT | 2.49      |
| 1164 | R/UPP OUT SIDEMEMBER SURFACE PAINT | 2.49      |
| 1481 | LEFT FRONT DOOR SURFACE PAINT      | 20.42     |
| 1482 | RIGHT FRONT DOOR SURFACE PAINT     | 20.42     |

## Labour Cost - Paint

|                                | Hrs          | WU           | Price SGD     |
|--------------------------------|--------------|--------------|---------------|
| Factor                         |              |              |               |
| Time Paint                     |              | 84.0         |               |
| Preparation Main Work Metal    | 2.50         | 25.0         | 105.00        |
| Preparation Comp. Work Plastic | 0.50         | 5.0          | 21.00         |
| <b>Total</b>                   | <b>11.40</b> | <b>114.0</b> | <b>478.80</b> |

42.00 SGD/h

10 WU/h

## Material Cost - Paint

|                                     | Price SGD     |
|-------------------------------------|---------------|
| New Part Painting                   | 102.16        |
| New Part Painting - Plastic K1R     | 60.02         |
| Surface-/Blend Paint                | 51.80         |
| Material-constant Metal Preparation | 28.60         |
| Material-constant Plastic           | 9.00          |
| <b>Total</b>                        | <b>251.58</b> |

## Spare Parts

| Code | Description          | Part Number       | Supplier | prices as at 2015-06-01 | Price SGD |
|------|----------------------|-------------------|----------|-------------------------|-----------|
| 0283 | FRONT BUMPER         | 1T0 807 221 M GRU |          | 7/11                    | 550.00    |
| 0297 | L/F AIR GUIDE GRILLE | 1T0 853 665 M 9B9 |          | 7/11                    | 90.00     |
| 0298 | R/F AIR GUIDE GRILLE | 1T0 853 666 R 9B9 |          | 7/11                    | 90.00     |
| 0299 | FRT CTR COWL GRILLE  | 1T0 853 677 C 9B9 |          | 7/11                    | 120.00    |

| Code | Description          | Part Number    | Supplier | Price SGD  |
|------|----------------------|----------------|----------|------------|
| 0319 | L/F OUT BUMPER BRKT  | 1T0 807 183 C  |          | 011 55.00  |
| 0320 | R/F OUT BUMPER BRKT  | 1T0 807 184 C  |          | 011 55.00  |
| 0340 | FRT BUMPER SUPPORT   | 1T0 807 109 D  |          | 011 290.00 |
| 0341 | FRT BUMPER FILLING   | 1T0 807 248 K  |          | 011 45.00  |
| 0410 | GRILLE               | 1T0 853 651 BQ |          | CM 240.00  |
|      |                      | PWF            |          |            |
| 0471 | BONNET               | 1T0 823 031 Q  |          | 011 680.00 |
| 0475 | LEFT BONNET HINGE    | 1T0 823 301 F  |          | 011 80.00  |
| 0476 | RIGHT BONNET HINGE   | 1T0 823 302 F  |          | 011 80.00  |
| 0481 | BONNET INSULATION    | 1T0 863 831 G  |          | 011 195.00 |
| 0493 | LOWER LOCK           | 2K5 823 509 E  |          | 011 95.00  |
| 0500 | BONNET REL CABLE     | 1T2 823 531 E  |          | 011 28.00  |
| 0561 | LEFT HEADLAMP ASSY   | 1T2 941 005 H  |          | 011 325.00 |
| 0562 | RIGHT HEADLAMP ASSY  | 1T2 941 006 H  |          | 011 325.00 |
| 0741 | L/F WING             | 1T0 821 021 D  |          | 011 350.00 |
| 0742 | R/F WING             | 1T0 821 022 D  |          | 011 350.00 |
| 0841 | L/F WHEELHOUSE       | 1T0 805 911 N  |          | 011 95.00  |
|      | COVER                |                |          |            |
| 0842 | R/F WHEELHOUSE       | 1T0 805 912 G  |          | 011 95.00  |
|      | COVER                |                |          |            |
| 0930 | FRT LOCK CARRIER     | 1T0 805 588 AF |          | CM 550.00  |
|      |                      | 9B9            |          |            |
| 0935 | L/LOCK CARRIER STRUT | 1T0 805 931 A  |          | 011 45.00  |
| 0936 | R/LOCK CARRIER STRUT | 1T0 805 932 A  |          | 011 45.00  |
| 1436 | FLUID RESERVOIR      | 1K0 955 453 S  |          | 011 105.00 |
| 4465 | CONDENSER            | 1K0 820 411 AK |          | 011 380.00 |
| 4481 | EVAP/CONDENSER HOSE  | 1T0 820 741 AL |          | 011 450.00 |
| 4482 | COMPR/CONDENSER      | 1K0 820 721 BQ |          | 011 450.00 |
|      | HOSE                 |                |          |            |
| 7747 | L/LWR RADIATOR BRKT  | 1K0 121 367 F  |          | 011 20.00  |
| 7748 | R/LWR RADIATOR BRKT  | 1K0 121 367 F  |          | 011 20.00  |
| 7749 | L/UPP RADIATOR BRKT  | 1K0 121 367 P  |          | 011 40.00  |
| 7750 | R/UPP RADIATOR BRKT  | 1K0 121 367 P  |          | 011 40.00  |
| 7751 | UPPER AIR DUCT       | 1T0 121 330    |          | 011 60.00  |
| 7753 | L/RADIATOR AIR GUIDE | 1T0 121 283 D  |          | 011 40.00  |
| 7754 | R/RADIATOR AIR GUIDE | 1T0 121 284 D  |          | 011 40.00  |
| 7761 | RADIATOR             | 5K0 121 251 AA |          | 011 380.00 |
| 7767 | FAN SHROUD           | 1K0 121 205 AJ |          | CM 140.00  |
|      |                      | 9B9            |          |            |
| 7787 | EXPANSION TANK       | 1K0 121 407 A  |          | 011 45.00  |
| 7789 | L/ELECTRIC FAN       | 1K0 959 455 FR |          | 011 320.00 |
| 7790 | R/ELECTRIC FAN       | 1K0 959 455 ET |          | 011 450.00 |
| 8388 | FRT INTAKE AIR GUIDE | 1K0 805 962 D  |          | 011 70.00  |
|      |                      | 9B9            |          |            |
| 8391 | AIR FILTER ASSY      | 1K0 129 607 AC |          | 011 290.00 |
| 8745 | INTERCOOLER          | 1K0 145 803 CD |          | 011 420.00 |
| 8804 | WARM AIR PANEL       | 03C 253 041 AM |          | 011 180.00 |

f: OEM Parts  
n: Non-OEM Parts  
u: Used parts

**Savings**  
**Subtotal**  
**Fixed Sundry Parts Price**

**Total**

0.00  
8,813.00  
100.00  
8,913.00

## Extras

| Code                | Description                     | Price SGD     |
|---------------------|---------------------------------|---------------|
| 1001                | ECU diagnostic ECU diagnostic   | 180.00*       |
| 1002                | Electrical work Electrical work | 201 40.00*    |
| 1003                | Air con coolant Air con         | ✓ 50.00*      |
| 1004                | Front number plate Number Plate | R 35.00*-     |
| <b>Total Extras</b> |                                 | <b>305.00</b> |

## Final Calculation

|                                       | SGD      | SGD              |
|---------------------------------------|----------|------------------|
| <b>Parts</b>                          | 8,813.00 |                  |
| Fixed Sundry Parts Price              | 100.00   |                  |
| <b>Total Parts</b>                    |          | <b>8,913.00</b>  |
| <b>Labour Time Base 10 WU/h</b>       |          |                  |
| Total 212.0 WU X 42.00 SGD/h          | 890.40   |                  |
| <b>Total of Labour</b>                |          | <b>890.40</b>    |
| <b>Total Of Extras</b>                |          | <b>305.00</b>    |
| <b>Paint Work Time Base 10 WU/h</b>   |          |                  |
| Labour Cost 114.0 WU X 42.00 SGD/h    | 478.80   |                  |
| Material Cost                         | 251.58   |                  |
| <b>Total Paint Including Material</b> |          | <b>730.38</b>    |
| <b>Repair Cost Excludes GST</b>       |          | <b>10,838.78</b> |
| GST (+7.0%)                           |          | <b>758.71</b>    |
| <b>Repair Cost Included GST</b>       |          | <b>11,597.49</b> |

## Comments

- \* - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
- ) - WU PARTIAL INCL IN OTHER POSITIONS

## Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: