

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person): Tan Kah Loong

of CTI

Date/Time: 24.12.19 11.08 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

or Inquest Vehicle No:

SJZ 9019 H

Insured:

at Workshop no: S R H Motor

Tel: 64534730

of 160 Sin Ming Drive #07-02

Policy No: DMPRSN 3435361900

Claim No: Svm 19 D 206029 /

Sum Insured:

Excess:

Waive

Make of Veh:

D.O.A. 15.12.2019

(Client's Record)

CA REV / REP / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 24.12.19 11.45 a.m

Person Contacted: Miss Wong

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SJZ 9019 H - CS/CTI 19022557/KV4362</u> <u>Date: 14/03/2019</u>
<u>24/12/19</u>	<u>Revert via mesmen, pending repair cost from repairer</u>
<u>24/12/19</u>	<u>@337pm Doris will come back on the repair cost</u>
<u>26/12/19</u>	<u>Kenneth said offer \$7500</u>
<u>26/12/19</u>	<u>@5pm Doris request for LS \$9000/.</u>

ASS. REC. BY:

REF: C 72 /

CS/CTI19022557/Krf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

236

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJZ 901914

Yr Regn:

01, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volks wagen Touran cc 1390

Colour:

M. Grey

AC: Insured / Std / NI / NA

Sp. Reading

163902

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVG 8881 TTBW C17420

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim or

Tyre Size:

Continental

R: Nil 215/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7 mm

R/Bal.

3 mm

L/Bal.

7 mm

L/Bal.

3 mm

D.O.A.

15/12/19

D.O.I.

24/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 23 JAN 2020

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

270

Transportation:

S - RS - SI

Fees

Others

TOTAL

270

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Merimen

Lump Sum / I.B.I. (\$

7650/2

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Dec 2019 Sendback Est	23 Dec 2019 18:11 S\$10,838.78	24 Dec 2019 11:08 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	RAYMOND LEE KIEN TIONG, ID: 57919050J, Tel: +6590487479, Email: NOEMAIL		
Vehicle Reg. No.:	SJZ9019H	Date of Loss:	15/12/2019 14:00 - :59 [107 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM19D206029/SJZ9019H/TKL	Policy/Cover Note No.:	DMPCSN3035361900 (Comprehensive)
		Excess:	S\$0.00
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/01/2020]		
Driver/Custodian:	RAYMOND LEE KIEN TIONG (40 / Male), NRIC: 57919050J, Tel: +6590487479 Email: NOEMAIL		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 27 December 2019 4:36 PM
To: 'Wong'; SUR; Doris
Subject: RE: Vehicle no : SJZ9019H OD claim D.O.A. 15/12/2019

Dear Doris,

As instructed by our client , please proceed to repair the **insured vehicle SJZ 9019H, Not Exceeding Lump Sum S9000/- or whichever lower, (Excess WAIVED).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wong <wong@sh-motor.com>
Sent: Tuesday, 24 December 2019 2:36 PM
To: SUR <sur@lkkauto.com>
Subject: FW: Vehicle no : SJZ9019H OD claim D.O.A. 15/12/2019

Re-send.

Thanks & Best Regards,

Ms Wong

S&H MOTOR PTE LTD

160 Sin Ming Drive #07-02

Sin Ming AutoCity

Singapore 575722

Tel: 6453 4730 Fax: 6457 1931

From: Wong [mailto:wong@sh-motor.com]
Sent: Tuesday, 24 December 2019 2:34 PM
To: 'sur@lkk.auto.com'
Subject: Vehicle no : SJZ9019H OD claim D.O.A. 15/12/2019

Dear Veron,

Pls see attached.

Thanks & Best Regards,

Ms Wong

S&H MOTOR PTE LTD

160 Sin Ming Drive #07-02

Sin Ming AutoCity

Singapore 575722

Tel: 6453 4730 Fax: 6457 1931

View Received Message

This mail is associated with :

SJZ9019H (SNM19D206029/SJZ9019H/TKL)

OD

Dec 15 2019 2:00PM

[RAYMOND LEE KIEN TIONG]

S & H Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **27/12/2019 16:13 PM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$9000.00) - SJZ9019H - Claim Handler: Tan Kah Leong

Approved:9000.00:Proceed to authorize repairs NO MORE THAN \$9,000.00. (inclusive of supplementary items) Excess is waived, Re-inspection of vehicle required.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Tan Kah Leong	Date:	27 Dec 2019
<u>Preliminary Advice</u>			

Vehicle No	: SJZ9019H	Accident Date	: 15/12/2019
Make	: VOLKSWAGEN TOURAN	Policy No.	: DMPCSN3035361900
Assignment Date	: 24/12/2019	Excess	: S\$0.00
Date of Inspection	: 24/12/2019	Est. Duration of Repair	: 7
Inspection At	: S & H MOTOR PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,838.78
Revised Amount	:S\$	6,851.38
Check Items (Estimated)	:S\$	3,743.00
Total	:S\$	10,594.38
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	23,000.00
COE / PARF Rebate	:S\$	14,286.00
Salvage Value	:S\$	
Margin for Repair	:S\$	8,714.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Repairer asking for Lump Sum \$9000/-.
- According to repairer, they are expected to have further supplementary.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Tan Kah Leong	Date:	24 Dec 2019
<u>Preliminary Advice</u>			

Vehicle No	: SJZ9019H	Accident Date	: 15/12/2019
Make	: VOLKSWAGEN TOURAN	Policy No.	: DMPCSN3035361900
Assignment Date	: 24/12/2019	Excess	: S\$0.00
Date of Inspection	: 24/12/2019	Est. Duration of Repair	: 7
Inspection At	: S & H MOTOR PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,838.78
Revised Amount	:S\$	6,851.38
Check Items (Estimated)	:S\$	3,743.00
Total	:S\$	10,594.38
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	23,000.00
COE / PARF Rebate	:S\$	14,286.00
Salvage Value	:S\$	
Margin for Repair	:S\$	8,714.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Pending repair cost from repairer.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	050J
Vehicle Details	
Vehicle No.:	SJZ9019H
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Dec 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TOURAN 1.4L AT TSI 1T32B4
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	CAV226685
Chassis No.:	WVGZZZ1TZBW017420
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$18,695.00
Original Registration Date:	04 Jan 2011
First Registration Date:	04 Jan 2011
Transfer Count:	4
Actual ARF Paid:	\$18,695.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Jan 2021
PARF Rebate Amount:	\$10,282.00
Intended COE Rebate Details	
COE Expiry Date:	03 Jan 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$39,000.00
COE Rebate Amount:	\$4,004.00
Total Rebate Amount:	\$14,286.00

The information contained herein is correct as at 24 Dec 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	050J
Vehicle Details	
Vehicle No.:	SJZ9019H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	17 Dec 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TOURAN 1.4L AT TSI 1T32B4
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	CAV226685
Chassis No.:	WVGZZZ1TZBW017420
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$18,695.00
Original Registration Date:	04 Jan 2011
First Registration Date:	04 Jan 2011
Transfer Count:	4
Actual ARF Paid:	\$18,695.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Jan 2021
PARF Rebate Amount:	\$10,282.00
Intended COE Rebate Details	
COE Expiry Date:	03 Jan 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$39,000.00
COE Rebate Amount:	\$4,078.00
Total Rebate Amount:	\$14,360.00

The information contained herein is correct as at 17 Dec 2019

OK

HOTTEST NEW CAR
PROMOTIONS

Honda Freed

\$96,999! Sensing, LED Lamps, Navi S, Twin Power Door & Honda Sensing, 1 Bid Glead COE Without Top Up! Full Accessories, CASETRUST

DON'T MISS OUT!

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Audi S4 Avant 3.0A TFSI Quattro.

Last Selling Date:
Recently Accident Free, Very Low
Mileage, Immaculate Condition
Direct OwnerLake View
Credit Pte Ltd

view our cars

- Low prices guaranteed
- Specialist in Japanese cars
- Easy loan approval
- All terms are negotiable

Browse by Category

Sort by Date Posted

20 results/page

8 vehicles

Volkswagen Touran

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Volkswagen Touran		Any	Any	2011	Any	Any	Any	Available
	Volkswagen	Touran 1.4A TSI	\$22,800	\$9,070 /yr	08-Jun-2011	1,390 cc	-	MPV	Available
6 Months Warranty, Excellent Condition, Accident Free, Bank Loan/In House Loan Available, Trade In Welcome. Appointment Viewing Only.									
Posted: 20-Dec-2019 Tags: 2011 Volkswagen Touran, 2011 volkswagen touran, Volkswagen Touran, volkswagen touran, Volkswagen, Touran, touran, Used Volkswagen									
	Volkswagen	Touran 1.4A TSI	\$25,300	\$10,030 /yr	06-Jul-2011	1,390 cc	-	MPV	Available
Full Loan Available, Regularly Serviced, Very Well Maintained, Still In Very Good Condition. Call Us Now.									
Motor Universe Credit Pte Ltd									
Posted: 19-Dec-2019 Tags: 2011 Volkswagen Touran, 2011 volkswagen touran, Volkswagen Touran, volkswagen touran, Volkswagen, Touran, touran, Used Volkswagen									
	Volkswagen	Touran Sport 1.4A TSI	\$26,800	\$10,730 /yr	18-Feb-2011	1,390 cc	-	MPV	Available
Original Condition. Low Interest Rate Financing And Insurance Can Be Arranged. Call For Viewing. Exporters Are Also Welcome.									
Posted: 19-Dec-2019 Tags: 2011 Volkswagen Touran, 2011 volkswagen touran, Volkswagen Touran, volkswagen touran, Volkswagen, Touran, touran, Used Volkswagen									
	Volkswagen	Touran 1.4A TSI	\$21,588	\$11,430 /yr	19-Jan-2011	1,390 cc	-	MPV	Available
Black Touran 1.4 TSI With 17 Inch Sport Rims And Michelin Pilot Sport Tyre. Just Change 4 Shock Absorber, Water Pump, Spark Plug And Coil. Number Plate Not Included In The Car Sale.									
Posted: 09-Dec-2019 Tags: 2011 Volkswagen Touran, 2011 volkswagen touran, Volkswagen Touran, volkswagen touran, Volkswagen, Touran, touran, Used Volkswagen									
GET YOUR COE RENEWAL LOAN									
Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.									
	Volkswagen	Touran Sport 1.4A TSI	\$26,300	\$11,070 /yr	20-Jan-2011	1,390 cc	-	MPV	Available
One Of The Most Popular MPV That Packs A Punch And Yet Generous On Cabin And Boot Space! Well Maintained By Owner! Comes With Upgraded Head Unit With Navigation! Buy With Peace Of Mind! Drive With Passion. Trade In And Loan Available. Please Call For Appointment.									
Posted: 06-Dec-2019 Tags: 2011 Volkswagen Touran, 2011 volkswagen touran, Volkswagen Touran, volkswagen touran, Volkswagen, Touran, touran, Used Volkswagen									
	Volkswagen	Touran 1.4A TSI	\$28,800	\$10,120 /yr	26-Sep-2011	1,390 cc	-	MPV	Available
Fuss-Free Transaction Guaranteed, Full Loan Available At \$1k Plus, We Can Help To Convert To Z10 Usage If Needed, Insurance By Instalment With Zero Interest Available. In House Loan Or Bank Loan Available! Fast, Easy And Flexible Loan Approval! Viewing And Tes...									
Posted: 03-Dec-2019 Tags: 2011 Volkswagen Touran, 2011 volkswagen touran, Volkswagen Touran, volkswagen touran, Volkswagen, Touran, touran, Used Volkswagen									
	Volkswagen	Touran Sport 1.4A TSI	\$28,300	\$12,710 /yr	27-Jan-2011	1,390 cc	156,809 km	MPV	Available
7 Seater MPV. Full Stock Car. Car In Good Condition. Consignment Unit. Insurance, Bank Loans And In House Loans Available. Trade-Ins Welcomed. Viewing By Appointment Only.									
Posted: 27-Nov-2019 Tags: 2011 Volkswagen Touran, 2011 volkswagen touran, Volkswagen Touran, volkswagen touran, Volkswagen, Touran, touran, Used Volkswagen									

Compare


Volkswagen Touran Sport 1.4A TSI
\$34,800
\$11,040 /yr
31-Oct-2011
1,390 cc
119,000 km
MPV
Available

2 Owner Only. Powerful 167BHP Sport Model! Low Fuel Consumption, High OMV At \$28723, High Paper Value, Paddle Shift, Cruise Control, Multi Function Steering, Rear Air-Con, Bluetooth Audio, Fog Lamp, Original Low Mileage Done 14000km Per Year, Just Done Ser...

Posted: 20-Nov-2019

Tags: 2011 Volkswagen Touran, 2011 volkswagen touran, Volkswagen Touran, volkswagen touran, Volkswagen, Touran, touran, Used Volkswagen

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

 For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & DPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Volkswagen Touran, Volkswagen Touran Singapore, used Volkswagen Touran Singapore, used Volkswagen Touran, used vehicles Singapore or even buy used Volkswagen Touran Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/12/2019 11:38
Date Of Accident	15/12/2019 14:45
Exact Location Of Accident	SLIP RD OF PUNGGOL RD TOWARDS TPE/SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ9019H
Insured/Policyholder	
Name Of Registered Owner	RAYMOND LEE KIEN TIONG
NRIC No	S7919050J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90487479
Alternative Phone No	OFFICE-90487479

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	TOURAN 1.4L

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3035361900
Cover Note Number	

Driver

Name of Driver	RAYMOND LEE KIEN TIONG
NRIC No	S7919050J
Date Of Birth	03/07/1979
Occupation	INDOOR
Date Of Driving Pass	05/08/2003
Driving Experience	16 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90487479
Fax Number	
Contact Number	OFFICE-90487479
EMail Address	NOEMAIL

Address	BLK 123 RIVERVALE DRIVE #13-113 S(540123)
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer attached report.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC5903Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Assume vehicle B in front of me moved off but did not move. Therefore collided into the rear portion of vehicle B.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:
Repairer Reference: 025033
Date calculated: 23/12/2019 6:01 PM

Full Report
Registration: SJZ9019H
Printed: 23/12/2019 6:01 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	SH Motor	Currency:	SGD
Claim Reference:		Date of Incident:	15/12/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle
 Manufacturer: VW
 Model: TOURAN (1T3)
 Sub Model: TRENDLINE
 Model Sheet Number: 06 CA 01
 Registration: SJZ9019H
 VIN number: WVGZZZ1TZBW017420
 Odometer:

Model Specs

FROM 09/2010	SAFE SECURITY	CLIMATRONIC	RADIO RCD 310
RAIN SENSOR	LIGHT SWITCHING AUTO	ELEC FOLD DR MIRRORS	AUTO DIPPING MIRROR
8 SPEAKER	EQUIP CLOTH CHARLY	HEIGHT ADJ PASS SEAT	3RD SEAT ROW
LEATHER STRG WHEEL	OIL LEVEL GAUGE	FRONT CENTRE ARMREST	SMOKER EQUIPMENT
1.4 LTR 103 KW	7-SPEED DSG	UPHILL TRACTION CONT	WHEELS 6J X 16
HD COOLING	ROOF RAILS	TWO COAT METALLIC	PREPARE OFF VEHICLE

En

Not Authorized
May be 7/12/19
7 days
Fax: 62564315

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
10 83 19 00	R + R ENGINE COVER		2.0	8.40
87 03 17 00	DRAIN + REFILL REFRIGERANT		5.0	21.00
63 29 19 00	R + R FRONT BUMPER COVER		7.0	29.40
63 29 55 50	RENEW FRONT BUMPER COVER (REMOVED)		5.0	21.00
	INCLUDES: CONVERT ATTACHED PARTS			
94 15 55 50	RENEW L/HEADLAMP (REMOVED)		1.0	4.20
94 15 55 50	RENEW R/HEADLAMP (REMOVED)		1.0	4.20
50 55 19 50	R + R LEFT FRONT WING (BUMPER COVER REMOVED)		9.0	37.80
	INCLUDES: WHEEL, W-HOUSE LINER AND CORN-WINDOW REMOVE AND REFIT			
50 55 51 50	L/F WING SEAL (COMPOSITE WORK)		3.0	12.60
50 55 19 50	R + R RIGHT FRONT WING (BUMPER COVER REMOVED)		9.0	37.80

Code	Description	WU	Price SGD
	INCLUDES: WHEEL, W-HOUSE LINER AND CORN-WINDOW REMOVE AND REFIT		
50 55 51 50	R/F WING SEAL (COMPOSITE WORK)	3.0	12.60
55 22 19 00	REMOVE/REFIT BONNET PANEL	7.0	29.40
	INCLUDES: ADJUST BONNET CLEARANCES		
55 22 55 50	RENEW BONNET (BONNET REMOVED)	5.0	21.00
	INCLUDES: R + R ALL PARTS		
55 25 56 50	RENEW BOTH FRONT BONNET HINGES (BONNET REMOVED)	3.0	12.60
50 38 19 50	R + R FRONT LOCK CARRIER (BUMPER COVER REMOVED)	13.0	54.60
	INCLUDES: R + R NOISE CONTROL PAN DOES NOT INCLUDE: ADJUST HEADLAMPS, DRAIN + REFILL REFRIGERANT		
50 38 55 50	RENEW FRONT LOCK CARRIER (REMOVED)	11.0	46.20
	INCLUDES: CONVERT ATTACHED PARTS		
92 60 19 50	R + R WASHER RESERVOIR (BUMPER COVER REMOVED)	2.0	8.40
	INCLUDES: R + R WASHER PUMP		
92 60 55 50	RENEW WASHER RESERVOIR (REMOVED)	1.0	4.20
87 44 19 50)	R + R CONDENSER/EVAPORATOR PIPE (BUMPER COVER REMOVED)	4.0	16.80
	DOES NOT INCLUDE: DRAIN + REFILL REFRIGERANT		
87 43 19 50	R + R COMPRESSOR/CONDENSER PIPE (SOUND PROTECTION PAN REMOVED)	4.0	16.80
	DOES NOT INCLUDE: DRAIN + REFILL REFRIGERANT		
19 40 19 00	R + R OVERFLOW TANK	4.0	16.80
19 70 55 50	RENEW RADIATOR (REMOVED)	3.0	12.60
	INCLUDES: CONVERT ATTACHED PARTS		
19 20 55 73	RENEW COOLING BLOWER HOUSING INCLUDES: R + R ELECTRIC FAN	2.0	8.40
24 25 19 23	R + R AIR CLEANER	4.0	16.80
21 32 19 23)	R + R HOT AIR PANEL	1.0	4.20
94 15 16 00	ADJUST HEADLAMPS	3.0	12.60
1163	L/UPP OUT SIDEMEMBER REPAIR	20.0*	84.00
1164	R/UPP OUT SIDEMEMBER REPAIR	20.0*	84.00
1201	L/F SIDE MEMBER CPL REPAIR	30.0*	126.00
1202	R/F SIDE MEMBER CPL REPAIR	30.0*	126.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		21.20	212.0
Total of Labour			890.40

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	20.0
	L/F WING NEW PART PAINTING	10.0
	R/F WING NEW PART PAINTING	10.0

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
	FRONT BUMPER NEW PART PAINT K1R	12.0	
	L/F SIDE MEMBER CPL SURFACE PAINT	4.0	
	R/F SIDE MEMBER CPL SURFACE PAINT	4.0	
	L/UPP OUT SIDEMEMBER SURFACE PAINT	4.0	
	R/UPP OUT SIDEMEMBER SURFACE PAINT	4.0	
	LEFT FRONT DOOR SURFACE PAINT	8.0	
	RIGHT FRONT DOOR SURFACE PAINT	8.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	63.98
0741	L/F WING NEW PART PAINTING	19.09
0742	R/F WING NEW PART PAINTING	19.09
0283	FRONT BUMPER NEW PART PAINT K1R	60.02
1201	L/F SIDE MEMBER CPL SURFACE PAINT	2.99
1202	R/F SIDE MEMBER CPL SURFACE PAINT	2.99
1163	L/UPP OUT SIDEMEMBER SURFACE PAINT	2.49
1164	R/UPP OUT SIDEMEMBER SURFACE PAINT	2.49
1481	LEFT FRONT DOOR SURFACE PAINT	20.42
1482	RIGHT FRONT DOOR SURFACE PAINT	20.42

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			
Time Paint		84.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	11.40	114.0	478.80

42.00 SGD/h

10 WU/h

Material Cost - Paint

	Price SGD
New Part Painting	102.16
New Part Painting - Plastic K1R	60.02
Surface-/Blend Paint	51.80
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	251.58

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0283	FRONT BUMPER	1T0 807 221 M GRU		Tn	550.00 ✓
0297	L/F AIR GUIDE GRILLE	1T0 853 665 M 9B9		M17	90.00 ✓
0298	R/F AIR GUIDE GRILLE	1T0 853 666 R 9B9		M17	90.00 ✓
0299	FRT CTR COWL GRILLE	1T0 853 677 C 9B9		M17	120.00 ✓

Code	Description	Part Number	Supplier	Price SGD
0319	L/F OUT BUMPER BRKT	1T0 807 183 C		Diy 55.00 ✓
0320	R/F OUT BUMPER BRKT	1T0 807 184 C		Diy 55.00 ✓
0340	FRT BUMPER SUPPORT	1T0 807 109 D		Bz 290.00 ✓
0341	FRT BUMPER FILLING	1T0 807 248 K		Diy 45.00 ✓
0410	GRILLE	1T0 853 651 BQ		CM 240.00 ✓
	PWF			
0471	BONNET	1T0 823 031 Q		Bz 680.00 ✓
0475	LEFT BONNET HINGE	1T0 823 301 F		Diy 80.00 ✓
0476	RIGHT BONNET HINGE	1T0 823 302 F		Diy 80.00 ✓
0481	BONNET INSULATION	1T0 863 831 G		Deform 195.00 ✓
0493	LOWER LOCK	2K5 823 509 E		Bz 95.00 ✓
0500	BONNET REL CABLE	1T2 823 531 E		Jm ✓ Bz 28.00 ✓
0561	LEFT HEADLAMP ASSY	1T2 941 005 H		Bz 325.00 ✓
0562	RIGHT HEADLAMP ASSY	1T2 941 006 H		my Bz 325.00 ✓
0741	L/F WING	1T0 821 021 D		Bz 350.00 ✓
0742	R/F WING	1T0 821 022 D		Bz 350.00 ✓
0841	L/F WHEELHOUSE COVER	1T0 805 911 N		- CM 95.00 ✓
0842	R/F WHEELHOUSE COVER	1T0 805 912 G		✓ CM 95.00 ✓
0930	FRT LOCK CARRIER	1T0 805 588 AF		CM 550.00 ✓
	9B9			
0935	L/LOCK CARRIER STRUT	1T0 805 931 A		CM 45.00 ✓
0936	R/LOCK CARRIER STRUT	1T0 805 932 A		NSP 45.00 ✓
1436	FLUID RESERVOIR	1K0 955 453 S		Bz 105.00 ✓
4465	CONDENSER	1K0 820 411 AK		Pr 380.00 ✓
4481	EVAP/CONDENSER HOSE	1T0 820 741 AL		Pr 450.00 ✓
4482	COMPR/CONDENSER HOSE	1K0 820 721 BQ		Bz 450.00 ✓
7747	L/LWR RADIATOR BRKT	1K0 121 367 F		✓ R 20.00 ✓
7748	R/LWR RADIATOR BRKT	1K0 121 367 F		✓ R 20.00 ✓
7749	L/UPP RADIATOR BRKT	1K0 121 367 P		✓ R 40.00 ✓
7750	R/UPP RADIATOR BRKT	1K0 121 367 P		✓ R 40.00 ✓
7751	UPPER AIR DUCT	1T0 121 330		De 60.00 ✓
7753	L/RADIATOR AIR GUIDE	1T0 121 283 D		CM 40.00 ✓
7754	R/RADIATOR AIR GUIDE	1T0 121 284 D		CM 40.00 ✓
7761	RADIATOR	5K0 121 251 AA		Pr 380.00 ✓
7767	FAN SHROUD	1K0 121 205 AJ		CM 140.00 ✓
	9B9			
7787	EXPANSION TANK	1K0 121 407 A		✓ De Bz 45.00 ✓
7789	L/ELECTRIC FAN	1K0 959 455 FR		CM 320.00 ✓
7790	R/ELECTRIC FAN	1K0 959 455 ET		CM 450.00 ✓
8388	FRT INTAKE AIR GUIDE	1K0 805 962 D		CM 70.00 ✓
	9B9			
8391	AIR FILTER ASSY	1K0 129 607 AC		Diy 290.00 ✓
8745	INTERCOOLER	1K0 145 803 CD		Pr 420.00 ✓
8804	WARM AIR PANEL	03C 253 041 AM		CM 180.00 ✓

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings
Subtotal
Fixed Sundry Parts Price
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during recovery
- Parts prices are subject to confirmation
- Third party survey is not a "Minimum Guaranteed" price
- No illegal modifications are allowed
- Supplementary items must be resurveyed and is subject to final approval & confirmation

0.00
8,813.00
100.00
8,913.00

Extras

Acknowledged by Repairer
Signature:
Date:

Code	Description	Price SGD
1001	ECU diagnostic ECU diagnostic	180.00* 124
1002	Electrical work Electrical work	20/ 40.00*
1003	Air con coolant Air con	✓ 50.00*
1004	Front number plate Number Plate	R, 35.00* ✓
Total Extras		305.00

Final Calculation

	SGD	SGD
Parts	8,813.00	
Fixed Sundry Parts Price	100.00	
Total Parts		8,913.00
Labour Time Base 10 WU/h		
Total 212.0 WU X 42.00 SGD/h	890.40 441	
Total of Labour		890.40
Total Of Extras		305.00
Paint Work Time Base 10 WU/h		
Labour Cost 114.0 WU X 42.00 SGD/h	478.80 478.80	
Material Cost	251.58 251.58	
Total Paint Including Material		730.38
Repair Cost Excludes GST		10,838.78
GST (+7.0%)		758.71
Repair Cost Included GST		11,597.49

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:
Repairer Reference: 025033
Date calculated: 24/12/2019 3:02 PM

Revert

Full Report
Registration: SJZ9019H
Printed: 24/12/2019 3:03 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	15/12/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	VW		
Model:	TOURAN (1T3)		
Sub Model:	TRENDLINE		
Model Sheet Number:	06 CA 01		
Registration:	SJZ9019H		
VIN number:	WVGZZZ1TZW017420		
Odometer:			
Model Specs			
FROM 09/2010	SAFE SECURITY	CLIMATRONIC	RADIO RCD 310
RAIN SENSOR	LIGHT SWITCHING AUTO	ELEC FOLD DR MIRRORS	AUTO DIPPING MIRROR
8 SPEAKER	EQUIP CLOTH CHARLY	HEIGHT ADJ PASS SEAT	3RD SEAT ROW
LEATHER STRG WHEEL	OIL LEVEL GAUGE	FRONT CENTRE ARMREST	SMOKER EQUIPMENT
1.4 LTR 103 KW	7-SPEED DSG	UPHILL TRACTION CONT	WHEELS 6J X 16
HD COOLING	ROOF RAILS	TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
10 83 19 00	R + R ENGINE COVER		2.0	8.40
87 03 17 00	DRAIN + REFILL REFRIGERANT		5.0	21.00
63 29 19 00	R + R FRONT BUMPER COVER		7.0	29.40
63 29 55 50	RENEW FRONT BUMPER COVER (REMOVED)		5.0	21.00
	INCLUDES: CONVERT ATTACHED PARTS			
94 15 55 50	RENEW L/HEADLAMP (REMOVED)		1.0	4.20
94 15 55 50	RENEW R/HEADLAMP (REMOVED)		1.0	4.20
50 55 19 50	R + R LEFT FRONT WING (BUMPER COVER REMOVED)		9.0	37.80
	INCLUDES: WHEEL, W-HOUSE LINER AND CORN-WINDOW REMOVE AND REFIT			
50 55 51 50	L/F WING SEAL (COMPOSITE WORK)		3.0	12.60
50 55 19 50	R + R RIGHT FRONT WING (BUMPER COVER REMOVED)		9.0	37.80
	INCLUDES: WHEEL, W-HOUSE LINER AND CORN-WINDOW REMOVE AND REFIT			
50 55 51 50	R/F WING SEAL (COMPOSITE WORK)		3.0	12.60
55 22 19 00	REMOVE/REFIT BONNET PANEL		7.0	29.40
	INCLUDES: ADJUST BONNET CLEARANCES			
55 22 55 50	RENEW BONNET (BONNET REMOVED)		5.0	21.00
	INCLUDES: R + R ALL PARTS			
55 25 56 50	RENEW BOTH FRONT BONNET HINGES (BONNET REMOVED)		3.0	12.60
50 38 19 50	R + R FRONT LOCK CARRIER (BUMPER COVER REMOVED)		13.0	54.60
	INCLUDES: R + R NOISE CONTROL PAN			
	DOES NOT INCLUDE: ADJUST HEADLAMPS,			

Code	Description	WU	Price SGD
50 38 55 50	DRAIN + REFILL REFRIGERANT RENEW FRONT LOCK CARRIER (REMOVED) INCLUDES: CONVERT ATTACHED PARTS	11.0	46.20
87 44 19 50)	R + R CONDENSER/EVAPORATOR PIPE (BUMPER COVER REMOVED) DOES NOT INCLUDE: DRAIN + REFILL REFRIGERANT	4.0	16.80
87 43 19 50	R + R COMPRESSOR/CONDENSER PIPE (SOUND PROTECTION PAN REMOVED) DOES NOT INCLUDE: DRAIN + REFILL REFRIGERANT	4.0	16.80
19 70 55 50	RENEW RADIATOR (REMOVED) INCLUDES: CONVERT ATTACHED PARTS	3.0	12.60
19 20 55 73	RENEW COOLING BLOWER HOUSING INCLUDES: R + R ELECTRIC FAN	2.0	8.40
24 25 19 23	R + R AIR CLEANER	4.0	16.80
21 32 19 23)	R + R HOT AIR PANEL	1.0	4.20
94 15 16 00	ADJUST HEADLAMPS	3.0	12.60
1163	L/UPP OUT SIDEMEMBER REPAIR	20.0*	84.00
1164	R/UPP OUT SIDEMEMBER REPAIR	20.0*	84.00
1201	L/F SIDE MEMBER CPL REPAIR	30.0*	126.00
1202	R/F SIDE MEMBER CPL REPAIR	30.0*	126.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		20.50	205.0
Total of Labour			861.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	20.0
	L/F WING NEW PART PAINTING	10.0
	R/F WING NEW PART PAINTING	10.0
	FRONT BUMPER NEW PART PAINT K1R	12.0
	L/F SIDE MEMBER CPL SURFACE PAINT	4.0
	R/F SIDE MEMBER CPL SURFACE PAINT	4.0
	L/UPP OUT SIDEMEMBER SURFACE PAINT	4.0
	R/UPP OUT SIDEMEMBER SURFACE PAINT	4.0
	LEFT FRONT DOOR SURFACE PAINT	8.0
	RIGHT FRONT DOOR SURFACE PAINT	8.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	63.98
0741	L/F WING NEW PART PAINTING	19.09
0742	R/F WING NEW PART PAINTING	19.09
0283	FRONT BUMPER NEW PART PAINT K1R	60.02
1201	L/F SIDE MEMBER CPL SURFACE PAINT	2.99
1202	R/F SIDE MEMBER CPL SURFACE PAINT	2.99
1163	L/UPP OUT SIDEMEMBER SURFACE PAINT	2.49
1164	R/UPP OUT SIDEMEMBER SURFACE PAINT	2.49

Paint Material Per Part

Code	Description	Price SGD
1481	LEFT FRONT DOOR SURFACE PAINT	20.42
1482	RIGHT FRONT DOOR SURFACE PAINT	20.42

Labour Cost - Paint

	Factor	42.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			84.0	
	Preparation Main Work Metal		2.50	25.0	105.00
	Preparation Comp. Work Plastic		0.50	5.0	21.00
Total		10 WU/h	11.40	114.0	478.80

Material Cost - Paint

	Price SGD
New Part Painting	102.16
New Part Painting - Plastic K1R	60.02
Surface-/Blend Paint	51.80
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	251.58

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0283	FRONT BUMPER	1T0 807 221 M GRU		550.00
0297	L/F AIR GUIDE GRILLE	1T0 853 665 M 9B9		90.00
0298	R/F AIR GUIDE GRILLE	1T0 853 666 R 9B9		90.00
0299	FRT CTR COWL GRILLE	1T0 853 677 C 9B9		120.00
0319	L/F OUT BUMPER BRKT	1T0 807 183 C		55.00
0320	R/F OUT BUMPER BRKT	1T0 807 184 C		55.00
0340	FRT BUMPER SUPPORT	1T0 807 109 D		290.00
0341	FRT BUMPER FILLING	1T0 807 248 K		45.00
0410	GRILLE	1T0 853 651 BQ PWF		240.00
0471	BONNET	1T0 823 031 Q		680.00
0475	LEFT BONNET HINGE	1T0 823 301 F		80.00
0476	RIGHT BONNET HINGE	1T0 823 302 F		80.00
0481	BONNET INSULATION	1T0 863 831 G		195.00
0493	LOWER LOCK	2K5 823 509 E		95.00
0500	BONNET REL CABLE	1T2 823 531 E		28.00
0561	LEFT HEADLAMP ASSY	1T2 941 005 H		325.00
0562	RIGHT HEADLAMP ASSY	1T2 941 006 H		325.00
0741	L/F WING	1T0 821 021 D		350.00
0742	R/F WING	1T0 821 022 D		350.00
0841	L/F WHEELHOUSE COVER	1T0 805 911 N		95.00
0842	R/F WHEELHOUSE COVER	1T0 805 912 G		95.00

Code	Description	Part Number	Supplier	Price SGD
0930	FRT LOCK CARRIER	1T0 805 588 AF 9B9		550.00
0935	L/LOCK CARRIER STRUT	1T0 805 931 A		45.00
4465	CONDENSER	1K0 820 411 AK		380.00
4481	EVAP/CONDENSER HOSE	1T0 820 741 AL		450.00
4482	COMPR/CONDENSER HOSE	1K0 820 721 BQ		450.00
7747	L/LWR RADIATOR BRKT	1K0 121 367 F		20.00
7748	R/LWR RADIATOR BRKT	1K0 121 367 F		20.00
7749	L/UPP RADIATOR BRKT	1K0 121 367 P		40.00
7750	R/UPP RADIATOR BRKT	1K0 121 367 P		40.00
7751	UPPER AIR DUCT	1T0 121 330		60.00
7753	L/RADIATOR AIR GUIDE	1T0 121 283 D		40.00
7754	R/RADIATOR AIR GUIDE	1T0 121 284 D		40.00
7761	RADIATOR	5K0 121 251 AA		380.00
7767	FAN SHROUD	1K0 121 205 AJ 9B9		140.00
7789	L/ELECTRIC FAN	1K0 959 455 FR		320.00
7790	R/ELECTRIC FAN	1K0 959 455 ET		450.00
8388	FRT INTAKE AIR GUIDE	1K0 805 962 D 9B9		70.00
8391	AIR FILTER ASSY	1K0 129 607 AC		290.00
8745	INTERCOOLER	1K0 145 803 CD		420.00
8804	WARM AIR PANEL	03C 253 041 AM		180.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			8,618.00
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			8,718.00

Extras

Code	Description	Price SGD
1001	ECU diagnostic ECU diagnostic	180.00*
1002	Electrical work Electrical work	20.00*
1003	Air con coolant Air con	50.00*
1004	Front number plate Number Plate	35.00*
	Total Extras	285.00

Final Calculation

	SGD	SGD
Parts	8,618.00	
Fixed Sundry Parts Price	100.00	
Total Parts		8,718.00
Labour Time Base 10 WU/h		
Total 205.0 WU X 42.00 SGD/h	861.00	
Total of Labour		861.00
Total Of Extras		285.00
Paint Work Time Base 10 WU/h		
Labour Cost 114.0 WU X 42.00 SGD/h	478.80	
Material Cost	251.58	
Total Paint Including Material		730.38
Repair Cost Excludes GST		10,594.38
GST (+7.0%)		741.61
Repair Cost Included GST		11,335.99

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:
Repairer Reference: 025033
Date calculated: 23/12/2019 6:01 PM

Full Report
Registration: SJZ9019H
Printed: 23/12/2019 6:01 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	SH Motor	Currency:	SGD
Claim Reference:		Date of Incident:	15/12/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle
 Manufacturer: VW
 Model: TOURAN (1T3)
 Sub Model: TRENDLINE
 Model Sheet Number: 06 CA 01
 Registration: SJZ9019H
 VIN number: WVGZZZ1TZBW017420
 Odometer:

Model Specs

FROM 09/2010	SAFE SECURITY	CLIMATRONIC	RADIO RCD 310
RAIN SENSOR	LIGHT SWITCHING AUTO	ELEC FOLD DR MIRRORS	AUTO DIPPING MIRROR
8 SPEAKER	EQUIP CLOTH CHARLY	HEIGHT ADJ PASS SEAT	3RD SEAT ROW
LEATHER STRG WHEEL	OIL LEVEL GAUGE	FRONT CENTRE ARMREST	SMOKER EQUIPMENT
1.4 LTR 103 KW	7-SPEED DSG	UPHILL TRACTION CONT	WHEELS 6J X 16
HD COOLING	ROOF RAILS	TWO COAT METALLIC	PREPARE OFF VEHICLE



Not Authorized

may be 7/6/01

Today

Fax: 62564315

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
10 83 19 00	R + R ENGINE COVER		2.0	8.40
87 03 17 00	DRAIN + REFILL REFRIGERANT		5.0	21.00
63 29 19 00	R + R FRONT BUMPER COVER		7.0	29.40
63 29 55 50	RENEW FRONT BUMPER COVER (REMOVED)		5.0	21.00
	INCLUDES: CONVERT ATTACHED PARTS			
94 15 55 50	RENEW L/HEADLAMP (REMOVED)		1.0	4.20
94 15 55 50	RENEW R/HEADLAMP (REMOVED)		1.0	4.20
50 55 19 50	R + R LEFT FRONT WING (BUMPER COVER REMOVED)		9.0	37.80
	INCLUDES: WHEEL, W-HOUSE LINER AND CORN- WINDOW REMOVE AND REFIT			
50 55 51 50	L/F WING SEAL (COMPOSITE WORK)		3.0	12.60
50 55 19 50	R + R RIGHT FRONT WING (BUMPER COVER REMOVED)		9.0	37.80

Code	Description	WU	Price SGD
	INCLUDES: WHEEL, W-HOUSE LINER AND CORN-WINDOW REMOVE AND REFIT	3.0	12.60
50 55 51 50	R/F WING SEAL (COMPOSITE WORK)	7.0	29.40
55 22 19 00	REMOVE/REFIT BONNET PANEL		
	INCLUDES: ADJUST BONNET CLEARANCES	5.0	21.00
55 22 55 50	RENEW BONNET (BONNET REMOVED)		
	INCLUDES: R + R ALL PARTS	3.0	12.60
55 25 56 50	RENEW BOTH FRONT BONNET HINGES (BONNET REMOVED)	13.0	54.60
50 38 19 50	R + R FRONT LOCK CARRIER (BUMPER COVER REMOVED)		
	INCLUDES: R + R NOISE CONTROL PAN DOES NOT INCLUDE: ADJUST HEADLAMPS, DRAIN + REFILL REFRIGERANT	11.0	46.20
50 38 55 50	RENEW FRONT LOCK CARRIER (REMOVED)		
	INCLUDES: CONVERT ATTACHED PARTS	2.0	8.40
92 60 19 50	R + R WASHER RESERVOIR (BUMPER COVER REMOVED)		
	INCLUDES: R + R WASHER PUMP	1.0	4.20
92 60 55 50	RENEW WASHER RESERVOIR (REMOVED)	4.0	16.80
87 44 19 50)	R + R CONDENSER/EVAPORATOR PIPE (BUMPER COVER REMOVED)		
	DOES NOT INCLUDE: DRAIN + REFILL REFRIGERANT	4.0	16.80
87 43 19 50	R + R COMPRESSOR/CONDENSER PIPE (SOUND PROTECTION PAN REMOVED)		
	DOES NOT INCLUDE: DRAIN + REFILL REFRIGERANT	4.0	16.80
19 40 19 00	R + R OVERFLOW TANK	3.0	12.60
19 70 55 50	RENEW RADIATOR (REMOVED)		
	INCLUDES: CONVERT ATTACHED PARTS	2.0	8.40
19 20 55 73	RENEW COOLING BLOWER HOUSING		
	INCLUDES: R + R ELECTRIC FAN	4.0	16.80
24 25 19 23	R + R AIR CLEANER	1.0	4.20
21 32 19 23)	R + R HOT AIR PANEL	3.0	12.60
94 15 16 00	ADJUST HEADLAMPS	20.0*	84.00
1163	L/UPP OUT SIDEMEMBER REPAIR	20.0*	84.00
1164	R/UPP OUT SIDEMEMBER REPAIR	30.0*	126.00
1201	L/F SIDE MEMBER CPL REPAIR	30.0*	126.00
1202	R/F SIDE MEMBER CPL REPAIR		

Labour Cost
Panel / Mechanical Labour

Hrs WU
21.20 212.0 890.40

Total of Labour

890.40

Paint

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
	BONNET NEW PART PAINTING	20.0	
	L/F WING NEW PART PAINTING	10.0	
	R/F WING NEW PART PAINTING	10.0	

Paint Work Code	SYSTEM AZT	Time Basis 10 WU/h
Description - TWO COAT METALLIC	WU	Price SGD
FRONT BUMPER NEW PART PAINT K1R	12.0	
L/F SIDE MEMBER CPL SURFACE PAINT	4.0	
R/F SIDE MEMBER CPL SURFACE PAINT	4.0	
L/UPP OUT SIDEMEMBER SURFACE PAINT	4.0	
R/UPP OUT SIDEMEMBER SURFACE PAINT	4.0	
LEFT FRONT DOOR SURFACE PAINT	8.0	
RIGHT FRONT DOOR SURFACE PAINT	8.0	

Paint Material Per Part

Code	Description	Price SGD
171	BONNET NEW PART PAINTING	63.98
141	L/F WING NEW PART PAINTING	19.09
142	R/F WING NEW PART PAINTING	19.09
183	FRONT BUMPER NEW PART PAINT K1R	60.02
101	L/F SIDE MEMBER CPL SURFACE PAINT	2.99
102	R/F SIDE MEMBER CPL SURFACE PAINT	2.99
163	L/UPP OUT SIDEMEMBER SURFACE PAINT	2.49
164	R/UPP OUT SIDEMEMBER SURFACE PAINT	2.49
181	LEFT FRONT DOOR SURFACE PAINT	20.42
182	RIGHT FRONT DOOR SURFACE PAINT	20.42

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			84.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.50	5.0	21.00
Total	10 WU/h	11.40	114.0	478.80

Material Cost - Paint

	Price SGD
New Part Painting	102.16
New Part Painting - Plastic K1R	60.02
Surface-/Blend Paint	51.80
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	251.58

Paint Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
183	FRONT BUMPER	1T0 807 221 M			550.00 ✓
		GRU			
197	L/F AIR GUIDE GRILLE	1T0 853 665 M			90.00 ✓
		9B9			
198	R/F AIR GUIDE GRILLE	1T0 853 666 R			90.00 ✓
		9B9			
199	FRT CTR COWL GRILLE	1T0 853 677 C			120.00 ✓
		9B9			

Code	Description	Part Number	Supplier	Price SGD
0319	L/F OUT BUMPER BRKT	1T0 807 183 C		Dis 55.00 ✓
0320	R/F OUT BUMPER BRKT	1T0 807 184 C		Dis 55.00 ✓
0340	FRT BUMPER SUPPORT	1T0 807 109 D		Dis 290.00 ✓
0341	FRT BUMPER FILLING	1T0 807 248 K		Dis 45.00 ✓
0410	GRILLE	1T0 853 651 BQ		CM 240.00 ✓
		PWF		
0471	BONNET	1T0 823 031 Q		Dis 680.00 ✓
0475	LEFT BONNET HINGE	1T0 823 301 F		Dis 80.00 ✓
0476	RIGHT BONNET HINGE	1T0 823 302 F		Dis 80.00 ✓
0481	BONNET INSULATION	1T0 863 831 G		Return 195.00 ✓
0493	LOWER LOCK	2K5 823 509 E		Dis 95.00 ✓
0500	BONNET REL CABLE	1T2 823 531 E		28.00 ✓
0561	LEFT HEADLAMP ASSY	1T2 941 005 H		Dis 325.00 ✓
0562	RIGHT HEADLAMP ASSY	1T2 941 006 H		Dis 325.00 ✓
0741	L/F WING	1T0 821 021 D		Dis 350.00 ✓
0742	R/F WING	1T0 821 022 D		Dis 350.00 ✓
0841	L/F WHEELHOUSE COVER	1T0 805 911 N		95.00 ✓
0842	R/F WHEELHOUSE COVER	1T0 805 912 G		95.00 ✓
0930	FRT LOCK CARRIER	1T0 805 588 AF		CM 550.00 ✓
		9B9		
0935	L/LOCK CARRIER STRUT	1T0 805 931 A		45.00 ✓
0936	R/LOCK CARRIER STRUT	1T0 805 932 A		NSP 45.00 ✓
1436	FLUID RESERVOIR	1K0 955 453 S		Dis 105.00 ✓
1465	CONDENSER	1K0 820 411 AK		380.00 ✓
1481	EVAP/CONDENSER HOSE	1T0 820 741 AL		450.00 ✓
1482	COMPR/CONDENSER HOSE	1K0 820 721 BQ		450.00 ✓
1747	L/LWR RADIATOR BRKT	1K0 121 367 F		20.00 ✓
1748	R/LWR RADIATOR BRKT	1K0 121 367 F		20.00 ✓
1749	L/UPP RADIATOR BRKT	1K0 121 367 P		40.00 ✓
1750	R/UPP RADIATOR BRKT	1K0 121 367 P		40.00 ✓
1751	UPPER AIR DUCT	1T0 121 330		Dis 60.00 ✓
1753	L/RADIATOR AIR GUIDE	1T0 121 283 D		40.00 ✓
1754	R/RADIATOR AIR GUIDE	1T0 121 284 D		40.00 ✓
1761	RADIATOR	5K0 121 251 AA		380.00 ✓
1767	FAN SHROUD	1K0 121 205 AJ		CM 140.00 ✓
		9B9		
1787	EXPANSION TANK	1K0 121 407 A		Dis 45.00 ✓
1789	L/ELECTRIC FAN	1K0 959 455 FR		320.00 ✓
1790	R/ELECTRIC FAN	1K0 959 455 ET		430.00 ✓
3388	FRT INTAKE AIR GUIDE	1K0 805 962 D		70.00 ✓
		9B9		
3391	AIR FILTER ASSY	1K0 129 607 AC		Dis 290.00 ✓
3745	INTERCOOLER	1K0 145 803 CD		420.00 ✓
3804	WARM AIR PANEL	03C 253 041 AM		180.00 ✓

: OEM Parts
 1: Non-OEM Parts
 1: Used parts

Savings
Subtotal
Fixed Sundry Parts Price

0.00
 8,813.00
 100.00

Total

8,913.00

Extras

Code	Description	Price SGD
1001	ECU diagnostic ECU diagnostic	180.00*
1002	Electrical work Electrical work	20 40.00*
1003	Air con coolant Air con	✓ 50.00*
1004	Front number plate Number Plate	R 35.00*
	Total Extras	305.00

Final Calculation

	SGD	SGD
Parts	8,813.00	
Fixed Sundry Parts Price	100.00	
Total Parts		8,913.00
Labour Time Base 10 WU/h	890.40	
Total 212.0 WU X 42.00 SGD/h		890.40
Total of Labour		305.00
Total Of Extras		
Paint Work Time Base 10 WU/h	478.80	
Labour Cost 114.0 WU X 42.00 SGD/h	251.58	
Material Cost		730.38
Total Paint Including Material		10,838.78
Repair Cost Excludes GST		758.78
GST (+7.0%)		11,597.46
Repair Cost Included GST		

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:
Repairer Reference: 025033
Date calculated: 22/01/2020 11:11 AM

Full Report
Registration: SJZ9019H
Printed: 22/01/2020 11:12 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	15/12/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	VW
Model:	TOURAN (1T3)
Sub Model:	TRENDLINE
Model Sheet Number:	06 CA 01
Registration:	SJZ9019H
VIN number:	WVGZZZ1TZW017420
Odometer:	

Model Specs

FROM 09/2010	SAFE SECURITY	CLIMATRONIC	RADIO RCD 310
RAIN SENSOR	LIGHT SWITCHING AUTO	ELEC FOLD DR MIRRORS	AUTO DIPPING MIRROR
8 SPEAKER	EQUIP CLOTH CHARLY	HEIGHT ADJ PASS SEAT	3RD SEAT ROW
LEATHER STRG WHEEL	OIL LEVEL GAUGE	FRONT CENTRE ARMREST	SMOKER EQUIPMENT
1.4 LTR 103 KW	7-SPEED DSG	UPHILL TRACTION CONT	WHEELS 6J X 16
HD COOLING	ROOF RAILS	TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
10 83 19 00	R + R ENGINE COVER		2.0	8.40
87 03 17 00	DRAIN + REFILL REFRIGERANT		5.0	21.00
63 29 19 00	R + R FRONT BUMPER COVER		7.0	29.40
63 29 55 50	RENEW FRONT BUMPER COVER (REMOVED)		5.0	21.00
	INCLUDES: CONVERT ATTACHED PARTS			
94 15 55 50	RENEW L/HEADLAMP (REMOVED)		1.0	4.20
94 15 55 50	RENEW R/HEADLAMP (REMOVED)		1.0	4.20
50 55 19 50	R + R LEFT FRONT WING (BUMPER COVER REMOVED)		9.0	37.80
	INCLUDES: WHEEL, W-HOUSE LINER AND CORN- WINDOW REMOVE AND REFIT			
50 55 51 50	L/F WING SEAL (COMPOSITE WORK)		3.0	12.60
50 55 19 50	R + R RIGHT FRONT WING (BUMPER COVER REMOVED)		9.0	37.80
	INCLUDES: WHEEL, W-HOUSE LINER AND CORN- WINDOW REMOVE AND REFIT			
50 55 51 50	R/F WING SEAL (COMPOSITE WORK)		3.0	12.60
55 22 19 00	REMOVE/REFIT BONNET PANEL		7.0	29.40
	INCLUDES: ADJUST BONNET CLEARANCES			
55 22 55 50	RENEW BONNET (BONNET REMOVED)		5.0	21.00
	INCLUDES: R + R ALL PARTS			
55 25 56 50	RENEW BOTH FRONT BONNET HINGES (BONNET REMOVED)		3.0	12.60
50 38 19 50	R + R FRONT LOCK CARRIER (BUMPER COVER REMOVED)		13.0	54.60
	INCLUDES: R + R NOISE CONTROL PAN DOES NOT INCLUDE: ADJUST HEADLAMPS,			

Code	Description	WU	Price SGD
50 38 55 50	DRAIN + REFILL REFRIGERANT RENEW FRONT LOCK CARRIER (REMOVED) INCLUDES: CONVERT ATTACHED PARTS	11.0	46.20
87 44 19 50)	R + R CONDENSER/EVAPORATOR PIPE (BUMPER COVER REMOVED) DOES NOT INCLUDE: DRAIN + REFILL REFRIGERANT	4.0	16.80
19 40 19 00	R + R OVERFLOW TANK	4.0	16.80
19 70 55 50	RENEW RADIATOR (REMOVED) INCLUDES: CONVERT ATTACHED PARTS	3.0	12.60
19 20 55 73	RENEW COOLING BLOWER HOUSING INCLUDES: R + R ELECTRIC FAN	2.0	8.40
24 25 19 23	R + R AIR CLEANER	4.0	16.80
21 32 19 23)	R + R HOT AIR PANEL	1.0	4.20
94 15 16 00	ADJUST HEADLAMPS	3.0	12.60
1163	L/UPP OUT SIDEMEMBER REPAIR		
1164	R/UPP OUT SIDEMEMBER REPAIR		
1201	L/F SIDE MEMBER CPL REPAIR		
1202	R/F SIDE MEMBER CPL REPAIR		
Labour Cost		Hrs	WU
Panel / Mechanical Labour		10.50	105.0
Total of Labour			441.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	20.0
	L/F WING NEW PART PAINTING	10.0
	R/F WING NEW PART PAINTING	10.0
	FRONT BUMPER NEW PART PAINT K1R	12.0
	L/F SIDE MEMBER CPL SURFACE PAINT	4.0
	R/F SIDE MEMBER CPL SURFACE PAINT	4.0
	L/UPP OUT SIDEMEMBER SURFACE PAINT	4.0
	R/UPP OUT SIDEMEMBER SURFACE PAINT	4.0
	LEFT FRONT DOOR SURFACE PAINT	8.0
	RIGHT FRONT DOOR SURFACE PAINT	8.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	63.98
0741	L/F WING NEW PART PAINTING	19.09
0742	R/F WING NEW PART PAINTING	19.09
0283	FRONT BUMPER NEW PART PAINT K1R	60.02
1201	L/F SIDE MEMBER CPL SURFACE PAINT	2.99
1202	R/F SIDE MEMBER CPL SURFACE PAINT	2.99
1163	L/UPP OUT SIDEMEMBER SURFACE PAINT	2.49
1164	R/UPP OUT SIDEMEMBER SURFACE PAINT	2.49
1481	LEFT FRONT DOOR SURFACE PAINT	20.42
1482	RIGHT FRONT DOOR SURFACE PAINT	20.42

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	42.00 SGD/h			
Time Paint			84.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.50	5.0	21.00
Total	10 WU/h	11.40	114.0	478.80

Material Cost - Paint		Price SGD
New Part Painting		102.16
New Part Painting - Plastic K1R		60.02
Surface-/Blend Paint		51.80
Material-constant Metal Preparation		28.60
Material-constant Plastic		9.00
Total		251.58

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
8391	AIR FILTER ASSY	1K0 129 607 AC		290.00
0471	BONNET	1T0 823 031 Q		680.00
0481	BONNET INSULATION	1T0 863 831 G		195.00
0500	BONNET REL CABLE	1T2 823 531 E		28.00
4465	CONDENSER	1K0 820 411 AK		380.00
4481	EVAP/CONDENSER HOSE	1T0 820 741 AL		450.00
7787	EXPANSION TANK	1K0 121 407 F		45.00
7767	FAN SHROUD	1K0 121 205 AJ		140.00
		9B9		
0283	FRONT BUMPER	1T0 807 221 M		550.00
		GRU		
0341	FRT BUMPER FILLING	1T0 807 248 K		45.00
0340	FRT BUMPER SUPPORT	1T0 807 109 D		290.00
0299	FRT CTR COWL GRILLE	1T0 853 677 C		120.00
		9B9		
8388	FRT INTAKE AIR GUIDE	1K0 805 962 D		70.00
		9B9		
0930	FRT LOCK CARRIER	1T0 805 588 AF		550.00
		9B9		
0410	GRILLE	1T0 853 651 BQ		240.00
		PWF		
8745	INTERCOOLER	1K0 145 803 CD		420.00
7789	L/ELECTRIC FAN	1K0 959 455 FR		320.00
0297	L/F AIR GUIDE GRILLE	1T0 853 665 M		90.00
		9B9		
0319	L/F OUT BUMPER BRKT	1T0 807 183 C		55.00
0841	L/F WHEELHOUSE	1T0 805 911 N		95.00
	COVER			
0741	L/F WING	1T0 821 021 D		350.00
0935	L/LOCK CARRIER STRUT	1T0 805 931 A		45.00
7753	L/RADIATOR AIR GUIDE	1T0 121 283 D		40.00
0475	LEFT BONNET HINGE	1T0 823 301 F		80.00
0561	LEFT HEADLAMP ASSY	1T2 941 005 H		325.00
0493	LOWER LOCK	2K5 823 509 E		95.00
7790	R/ELECTRIC FAN	1K0 959 455 ET		450.00

Code	Description	Part Number	Supplier	Price SGD
0298	R/F AIR GUIDE GRILLE	1T0 853 666 R 9B9		90.00
0320	R/F OUT BUMPER BRKT	1T0 807 184 C		55.00
0842	R/F WHEELHOUSE COVER	1T0 805 912 G		95.00
0742	R/F WING	1T0 821 022 D		350.00
7754	R/RADIATOR AIR GUIDE	1T0 121 284 D		40.00
7761	RADIATOR	5K0 121 251 AA		380.00
0476	RIGHT BONNET HINGE	1T0 823 302 F		80.00
0562	RIGHT HEADLAMP ASSY	1T2 941 006 H		325.00
7751	UPPER AIR DUCT	1T0 121 330		60.00
8804	WARM AIR PANEL	03C 253 041 AM		180.00

f: OEM Parts	Savings	0.00
n: Non-OEM Parts	Subtotal	8,093.00
u: Used parts	Fixed Sundry Parts Price	100.00
	Total	8,193.00

Extras

Code	Description	Price SGD
1001	ECU diagnostic ECU diagnostic	120.00*
1002	Electrical work Electrical work	20.00*
1003	Air con coolant Air con	50.00*
1004	Front number plate Number Plate	35.00*
1163	[I]: L/UPP OUT SIDEM EMBER:	0.00*
	Total Extras	225.00

Final Calculation

	SGD	SGD
Parts	8,093.00	
Fixed Sundry Parts Price	100.00	
Total Parts		8,193.00
Labour Time Base 10 WU/h		
Total 105.0 WU X 42.00 SGD/h	441.00	
Total of Labour		441.00
Total Of Extras		225.00
Paint Work Time Base 10 WU/h		
Labour Cost 114.0 WU X 42.00 SGD/h	478.80	
Material Cost	251.58	
Total Paint Including Material		730.38
Repair Cost Excludes GST		9,589.38
GST (+7.0%)		671.26
Repair Cost Included GST		10,260.64

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 23 January 2020 12:03 PM
To: Doris; SUR
Subject: RE: vehicle no : SJZ 9019H-Final

Dear Doris,

Noted with thanks.

Will offer in merimen shortly.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Doris <doris@sh-motor.com>
Sent: Thursday, 23 January 2020 11:51 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: vehicle no : SJZ 9019H-Final

Dear Veron

Noted....Thank...lump sum cost \$7,650.00

Thank

Doris

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Wednesday, 22 January 2020 11:28 AM
To: Doris; SUR
Subject: RE: vehicle no : SJZ 9019H-Final

Dear Doris,

Offer Lump Sum \$7650/- @ 7 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Doris <doris@sh-motor.com>
Sent: Tuesday, 21 January 2020 2:31 PM
To: SUR <sur@lkkauto.com>
Subject: vehicle no : SJZ 9019H-Final

Hi

Forward vehicle no : SJZ 9019 H for final lump sum repair

Thank

Doris

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Dec 2019 Sendback Est	23 Dec 2019 18:11 \$10,838.78	24 Dec 2019 11:08 Edit Adj Rpt	\$7,650.00 Edit Estimates	\$7,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: RAYMOND LEE KIEN TIONG , ID: S79190503, Tel: +6590487479, Email: NOEMAIL									
Vehicle Reg. No.: SJZ9019H		Date of Loss: 15/12/2019 14:00 - :59 [107 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM19D206029/SJZ9019H/TKL		Policy/Cover Note No.: DMPCSN3035361900 (Comprehensive)							
		Excess: \$50.00							
Repairer: S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 06/01/2020]									
Driver/Custodian: RAYMOND LEE KIEN TIONG (40 / Male) , NRIC: S79190503, Tel: +6590487479 Email: NOEMAIL									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (27/12/2019): Alert - Adj Mandate Approved (\$59000.00) - SJZ9019H - Claim Handler: Tan Kah Leo...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJZ9019H (SNM19D206029/SJZ9019H/TKL)

OD

Dec 15 2019 2:00PM

[RAYMOND LEE KIEN TIONG]

S & H Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	23/12/19 18:11	Repairer Estimates	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/12/19 15:36	Adjuster Immediate Advice	Load HTM	
2	27/12/19 09:49	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/12/19 09:24	General View	Load PDF	
2	20/01/20 11:48	Reinspection Photo	Load PDF	
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/12/19 15:27	MARK ESTIMATE	Load PDF	
2	24/12/19 15:28	AUDATEX	Load PDF	

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	17/12/19 12:04	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	17/12/19 11:52	Accident Photo	Load JPG	☒
2	17/12/19 11:52	Accident Photo	Load JPG	☒
3	17/12/19 11:52	Accident Photo	Load JPG	☒
4	17/12/19 11:52	Accident Photo	Load JPG	☒
5	17/12/19 11:52	Accident Photo	Load JPG	☒
6	17/12/19 11:52	Accident Photo	Load JPG	☒
7	17/12/19 11:52	Accident Photo	Load JPG	☒
8	17/12/19 11:52	Accident Photo	Load JPG	☒
9	17/12/19 11:52	Accident Photo	Load JPG	☒
10	17/12/19 11:52	Accident Photo	Load JPG	☒
11	17/12/19 11:52	Accident Photo	Load JPG	☒
12	17/12/19 11:52	Accident Photo	Load JPG	☒
13	17/12/19 11:52	Accident Photo	Load JPG	☒
14	17/12/19 11:52	Accident Photo	Load JPG	☒
15	17/12/19 11:52	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print

Assessment Reports			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	17/12/19 11:45	Sketch Plan	 Load TIF	
2	17/12/19 11:45	Sketch Plan #2	 Load TIF	
3	17/12/19 11:45	Identification Card	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119022557/KVF3E2

Date: 04/02/2020

REFERENCE

Insured/Claimant:	RAYMOND LEE KIEN TIONG	Policy No:	DMPCSN3035361900	Claim No:	SNM19D206029/SJZ9019H/TKL
Date of Loss:	15/12/2019	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ9019H	Engine No:	CAV226685
Make & Model:	VOLKSWAGEN TOURAN, 1.4 TSI (A)	Chassis No:	WVGZZZ1TZBW017420
Reg. Date:	04/01/2011 (Man. Year: 2010)	Odometer:	163902 km
Colour:	Metallic Grey		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	S\$23,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Continental 7 mm	Rear Left Side:	Michelin 3 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Michelin 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,813.00	8,093.00	720.00	8.17
Miscellaneous Items	405.00	325.00	80.00	19.75
Paintwork Materials	251.58	251.58	0.00	0.00
Labour	890.40	441.00	449.40	50.47
Paintwork Labour	478.80	478.80	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,838.78	9,589.38	1,249.40	11.53
Approved Total (Overridden) (S\$)		7,650.00		
(S\$)	10,838.78	7,650.00	3,188.78	29.42
+ GST 7.00/7.00% (S\$)	758.71	535.50	223.21	29.42
Nett Amount (S\$)	11,597.49	8,185.50	3,411.99	29.42

INSPECTION

Date of Assignment:	24/12/2019 Present Location:	S & H Motor Pte Ltd (Sin Ming)
Date Inspected:	24/12/2019 Inspected At:	S & H Motor Pte Ltd (Sin Ming)
		160 Sin Ming Drive #07-02, Sin Ming
		AutoCity
		Singapore 575722
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 Feb 2020)	
Parts:	N/A	VOLKSWAGEN TOURAN 1.4 TSI (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ9019H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare parts		8,813.00 F	*8,093.00 F
					Total Parts (S\$)	8,813.00
						8,093.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Materials</u>				
1	1	paintwork material	251.58	251.58
<u>Miscellaneous Items</u>				
2	1	Misc	405.00	325.00
Sub Total (S\$)			656.58	576.58

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Labour for paintwork	New	478.80	478.80
<u>Labour Items</u>				
2	Labour for parts/mechanical	New	890.40	441.00
Gross Labour Cost (S\$)			1,369.20	919.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >