



# 友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LKK

DATE: 03/01/2020 OUR REF: UAPL1331  
REPAIR ESTIMATE TO THE MERCEDES BENZ C180 NO: SKF1896M  
NETT ITEM:-

- 1 FRONT BONNET ASSY X NN
- 1 FRONT BONNET MERCEDES EMBLEM X NN
- 2 FRONT HEADLAMP ASSY / CRA
- 1 FRONT GRILLE ASSY
- 1 FRONT GRILLE STAY X NN
- 1 FRONT BUMPER FACE / PR
- 1 FRONT BUMPER REINFORCEMENT / DD
- 1 FRONT BUMPER REINFORCEMENT SPONGE / CRA
- 1 FRONT BUMPER NUMBER GARNISH / CRA
- 1 FRONT BUMPER CENTRE LOWER GARNISH X NN
- 10 FRONT BUMPER CLIPS / NEC
- 2 FRONT SIDE HOLDER BRACKET X NN
- 1 REAR BOOT ASSY x repair
- 1 REAR BOOT EMBLEM / NEC
- 1 REAR BOOT C180 EMBLEM / NEC
- 1 REAR BOOT C&C EMBLEM / NEC
- 1 REAR BOOT KOMPRESSOR EMBLEM / NEC
- 1 REAR BOOT LOCK ASSY X NN
- 1 REAR BOOT CATCH X NN
- 1 REAR BOOT WEATHERSTRIP X NN
- 2 REAR TAILLAMP ASSY X NN
- 1 REAR BUMPER ASSY / RE
- 1 REAR BUMPER CENTRE GARNISH X NN
- 1 REAR BUMPER CENTRE MOUNTING (CHROME) / CUT
- 2 REAR BUMPER SIDE MOUNTING (CHROME) / NEC
- 1 REAR BUMPER DIFFUSER X NN
- 1 REAR BUMPER CENTRE GUIDE X NN
- 2 REAR BUMPER SIDE GULDE / CRA
- 1 REAR BUMPER INNER SPONGE / BT
- 1 REAR BUMPER REINFORCEMENT
- 1 REAR END PANEL ASSY X Repair.

\$	2,179.00	
\$	68.00	
\$	2,872.00	2490
\$	763.00	695
\$	18.00	
\$	1,638.00	1325
\$	766.00	406
\$	212.00	121
\$	225.00	82
\$	312.00	
\$	50.00	
\$	180.00	
\$	2,051.00	
\$	53.00	✓
\$	74.00	✓
\$	38.00	✓
\$	74.00	✓
\$	483.00	
\$	68.00	
\$	256.00	
\$	1,136.00	
\$	1,508.00	1460
\$	788.00	
\$	211.00	185
\$	308.00	220
\$	458.00	
\$	132.00	
\$	164.00	✓
\$	221.00	
\$	975.00	615.9
\$	1,157.00	
\$	19,435.00	
\$	1,943.50	
\$	17,491.50	

LESS 10%.....

8052.9

7649.9  
10%: 6084.91

7247.61



# 友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

## SPECIAL NETT:-

1 SET REVERSE SENSOR 4PC  
1 FRONT NUMBER PLATE ASSY

✓ DM  
✓ S&R

\$ 380.00 200  
\$ 50.00 40

## LABOUR CHARGES:-

TO SPRAY UNDERCOATING IN REPAIR.

\$ 220.00 X NN

TO DISM/REWIRE DAMAGED PORTION

\$ 250.00 30

TO DISM/RENEW REAR REVERSE SENSOR

\$ 100.00 40

TO PANEL BEAT DAMAGED PROTION, PARTS & RENEW PARTS

\$ 1,300.00 600

TO PUTTY AND RESPRAY DAMAGED PROTION

\$ 1,200.00 600  
\$ 20,991.50

supplementary labour: \$250

~~8194.91~~ 9007.61

20% ~~6550~~ 7200

6 X Days.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: