



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LKK

DATE: 03/01/2020

OUR REF: UAPL1331

REPAIR ESTIMATE TO THE MERCEDES BENZ C180 NO: SKF1896M

NETT ITEM:-

- 1 FRONT BONNET ASSY X
- 1 FRONT BONNET MERCEDES EMBLEM X {nn
- 2 FRONT HEADLAMP ASSY - CRA
- 1 FRONT GRILLE ASSY X nn
- 1 FRONT GRILLE STAY X nn
- 1 FRONT BUMPER FACE - PR
- 1 FRONT BUMPER REINFORCEMENT - DD
- 1 FRONT BUMPER REINFORCEMENT SPONGE - CRA
- 1 FRONT BUMPER NUMBER GARNISH - CRA
- 1 FRONT BUMPER CENTRE LOWER GARNISH X nn
- 10 FRONT BUMPER CLIPS - RCL
- 2 FRONT SIDE HOLDER BRACKET
- 1 REAR BOOT ASSY
- 1 REAR BOOT EMBLEM
- 1 REAR BOOT C180 EMBLEM
- 1 REAR BOOT C&C EMBLEM
- 1 REAR BOOT KOMPRESSOR EMBLEM
- 1 REAR BOOT LOCK ASSY
- 1 REAR BOOT CATCH
- 1 REAR BOOT WEATHERSTRIP
- 2 REAR TAILLAMP ASSY
- 1 REAR BUMPER ASSY - RCL
- 1 REAR BUMPER CENTRE GARNISH X nn
- 1 REAR BUMPER CENTRE MOUNTING (CHROME) - cut
- 2 REAR BUMPER SIDE MOUNTING (CHROME) - RCL
- 1 REAR BUMPER DIFFUSER
- 1 REAR BUMPER CENTRE GUIDE {X nn
- 2 REAR BUMPER SIDE GULDE
- 1 REAR BUMPER INNER SPONGE
- 1 REAR BUMPER REINFORCEMENT - BT
- 1 REAR END PANEL ASSY X Repair.

\$	2,179.00
\$	68.00
\$	2,872.00
\$	763.00
\$	18.00
\$	1,639.00
\$	766.00
\$	212.00
\$	225.00
\$	312.00
\$	50.00
\$	180.00
\$	2,051.00
\$	53.00
\$	74.00
\$	38.00
\$	74.00
\$	483.00
\$	68.00
\$	256.00
\$	1,136.00
\$	1,506.00
\$	788.00
\$	211.00
\$	306.00
\$	458.00
\$	132.00
\$	164.00
\$	221.00
\$	975.00
\$	1,157.00
\$	19,435.00
\$	1,943.50
\$	17,491.50

LESS 10%.....

7649.9

10%: 6884.91



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

SPECIAL NETT:-

1 SET REVERSE SENSOR 4PC
1 FRONT NUMBER PLATE ASSY

XNN
/scr.

\$ 380.00
\$ 50.00 40

LABOUR CHARGES:-

TO SPRAY UNDERCOATING IN REPAIR.

\$ 220.00 XNN

TO DISM/REWIRE DAMAGED PORTION

\$ 250.00 30

TO DISM/RENEW REAR REVERSE SENSOR

\$ 100.00 40

TO PANEL BEAT DAMAGED PROTION, PARTS & RENEW PARTS

\$ 1,300.00 600

TO PUTTY AND RESPRAY DAMAGED PROTION

\$ 1,200.00 600
\$ 20,991.50

[Signature]
1/4/2020

1270

8194.91

2% 6550

5 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: