



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SJA 637 P
HONDA CIVIC

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR WINDSCREEN MOULDING X		
2	BOOTLID X Repair.		
3	BOOTLID LOGO (HONDA) /		
4	BOOTLID EMBLEM (CIVIC) /		
5	BOOTLID EMBLEM (1.6) /		
6	BOOTLID EMBLEM (i.VTEC) /		
7	BOOTLID HANDLE X		
8	BOOTLID LOCK SWITCH X		
9	BOOTLID CARPLATE LAMP (L+R) X		
10	BOOTLID LAMP (L+R) X		
11	BOOTLID INNER TRIM X		
12	BOOTLID LOCK X		
13	BOOTLID LOCK COVER X		
14	BOOTLID LOCK CATCH X		
15	BOOTLID HINGE (L+R) X		
16	BOOTLID HINGE COVER (L+R) X		
17	BOOTLID STOPPER (L+R) X		
18	BOOTLID WEATHERSTRIP ?		
19	TAIL LAMP (L+R) X		
20	TAIL LAMP PANEL (L+R) X		
21	REAR BUMPER /		
22	REAR BUMPER RETAINER (L+R) /		
23	REAR BUMPER REINFORCEMENT BAR X ?		
24	REAR BUMPER BRACKET (L+R) ?		
25	REAR BUMPER BEAM X		
26	REAR BUMPER SPONGE ?		
27	REAR BUMPER UNDERCOVER X		
28	REAR FENDER (L+R) X		
29	REAR FENDER INNER TRIM (L+R) X		
30	REAR FENDER COWLING (L+R) X		
31	REAR FENDER MUDFLAP (L+R) X		
32	REAR FENDER AIR VENT (L+R) X		
33	REAR QUARTER PANEL (L+R) X		
34	END PANEL ?		
35	END PANEL TOP GARNISH ?		
36	SPAREWHEEL PANEL X		
37	SPAREWHEEL PANEL TOP BOARD X ?		
38	SPAREWHEEL PANEL TOP BOARD TOP MAT X		
39	SPAREWHEEL PANEL TOOLBOX (L+R) X		
40	EXHAUST PIPE X		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1
1
2

41	EXHAUST GASKET	X		1	
42	EXHAUST BRACKET (L+R)	X		2	
43	EXHAUST HEAT SHIELD	X		1	
			SUBTOTAL		\$ -
			LESS 20%		\$ -
			PARTS TOTAL		\$ -
			SPECIAL NETT	QTY	PRICE
1	REAR WINDSCREEN SEALANT	X		1	\$ 120.00
2	BOOTLID INNER TRIM CLIPS	X		10	\$ 100.00
3	BOOTLID EMBLEM (HONDA)	/	20	1	\$ 300.00
4	REVERSE CAMERA	/ DM	250	1	\$ 800.00
5	REAR CARPLATE	X		1	\$ 120.00
6	REAR CARPLATE FRAME	X		1	\$ 120.00
7	REAR BUMPER CLIPS	/ M6L		10	\$ 100.00
8	REAR BUMPER REVERSE SENSOR SET	0 ?	200	2	\$ 300.00
9	REAR FENDER SEALANT	X		1	\$ 120.00
10	REAR FENDER INNER TRIM CLIPS	X		20	\$ 200.00
11	REAR FENDER COWLING CLIPS	X		20	\$ 200.00
12	REAR FENDER MUDFLAP CLIPS	X		4	\$ 80.00
13	REAR QUARTER PANEL SEALANT	X		1	\$ 120.00
14	END PANEL SEALANT	?		1	\$ 120.00
15	END PANEL TOP GARNISH CLIPS	?		10	\$ 100.00
16	SPAREWHEEL PANEL SEALANT	X		1	\$ 120.00
17	SPARE TYRE	X		1	\$ 700.00
18	SPARE RIM	X		1	\$ 1,000.00
			SPECIAL NETT TOTAL		\$ 4,720.00
			LABOUR	QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN		400-600	1	\$ 3,600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA		600	1	\$ 2,400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA		?	1	\$ 250.00
4	TO RNR REAR WINDSCREEN		X	1	\$ 400.00
5	TO RNR REAR BOOT MECHANISM		40	1	\$ 400.00
6	TO RNR UPHOLSTERY,GARNISH AND ATTACHMENT PARTS		60	1	\$ 400.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.		40	1	\$ 150.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS		X	1	\$ 250.00
9	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION		30	1	\$ 150.00
10	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.		X	1	\$ 400.00
11	TO DO WATER LEAK TEST .		X	1	\$ 80.00
12	TO RNR FUEL TANK TO ASSIST WORK LOAD		X	1	\$ 250.00
			TOTAL		\$ 8,730.00
			GRAND TOTAL COST		\$ 13,450.00