



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24  
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com  
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:  
MAKE & MODEL:  
MILEAGE:  
TYRE:  
CHASSIS NUM:

SJA 637 P  
HONDA CIVIC

Guo Qiang@lkkauto.com

| ATTN: | NO | DESCRIPTION - PARTS                         | QTY | PRICE       |
|-------|----|---------------------------------------------|-----|-------------|
|       | 1  | REAR WINDSCREEN MOULDING X NN \$406.90.     |     |             |
|       | 2  | BOOTLID X Repair. \$1,329.70                |     |             |
|       | 3  | BOOTLID LOGO (HONDA) / NEC 39.6 \$109.70    |     |             |
|       | 4  | BOOTLID EMBLEM (CIVIC) / NEC 39.6 \$86.40   |     |             |
|       | 5  | BOOTLID EMBLEM (1.6) / NEC 20.9 \$81.90.    |     |             |
|       | 6  | BOOTLID EMBLEM (i.VTEC) / NEC 39.6 \$87.90. |     |             |
|       | 7  | BOOTLID HANDLE X NN \$418.10                |     |             |
|       | 8  | BOOTLID LOCK SWITCH X NN \$319.70.          |     |             |
|       | 9  | BOOTLID CARPLATE LAMP (L+R) X NN \$226.40   |     |             |
|       | 10 | BOOTLID LAMP (L+R) X NN                     | 2   | \$897.40    |
|       | 11 | BOOTLID INNER TRIM X NN                     | 1   | \$617.10.   |
|       | 12 | BOOTLID LOCK X NN                           | 1   | \$418.40    |
|       | 13 | BOOTLID LOCK COVER X NN                     | 1   | \$199.40.   |
|       | 14 | BOOTLID LOCK CATCH X NN                     | 1   | \$74.90.    |
|       | 15 | BOOTLID HINGE (L+R) X NN                    | 2   | \$242.60.   |
|       | 16 | BOOTLID HINGE COVER (L+R) X NN              | 2   | \$310.40.   |
|       | 17 | BOOTLID STOPPER (L+R) X NN                  | 2   | \$79.80.    |
|       | 18 | BOOTLID WEATHERSTRIP R Twi 104.5            | 1   | \$319.60.   |
|       | 19 | TAIL LAMP (L+R) X NN                        | 2   | \$1,219.00. |
|       | 20 | TAIL LAMP PANEL (L+R) X NN                  | 2   | \$894.20.   |
|       | 21 | REAR BUMPER / 22 638                        | 1   | \$1,190.60. |
|       | 22 | REAR BUMPER RETAINER (L+R) / De 46.2        | 2   | \$296.40    |
|       | 23 | REAR BUMPER REINFORCEMENT BAR X NN          | 1   | NIL.        |
|       | 24 | REAR BUMPER BRACKET (L+R) X NN              | 2   | \$319.20.   |
|       | 25 | REAR BUMPER BEAM X NN                       | 1   | NIL.        |
|       | 26 | REAR BUMPER SPONGE X NN                     | 1   | NIL.        |
|       | 27 | REAR BUMPER UNDERCOVER X NN                 | 1   | \$442.90.   |
|       | 28 | REAR FENDER (L+R) X NN                      | 2   | \$2,649.80. |
|       | 29 | REAR FENDER INNER TRIM (L+R) X NN           | 2   | \$1,294.40  |
|       | 30 | REAR FENDER COWLING (L+R) X NN              | 2   | \$684.60.   |
|       | 31 | REAR FENDER MUDFLAP (L+R) X NN              | 2   | \$219.40.   |
|       | 32 | REAR FENDER AIR VENT (L+R) X NN             | 2   | \$206.20.   |
|       | 33 | REAR QUARTER PANEL (L+R) X NN               | 2   | \$896.40.   |
|       | 34 | END PANEL X Repair. 1                       | 1   | \$826.70.   |
|       | 35 | END PANEL TOP GARNISH R De 71.5             | 1   | \$294.40    |
|       | 36 | SPAREWHEEL PANEL X NN                       | 1   | \$1,671.80  |
|       | 37 | SPAREWHEEL PANEL TOP BOARD X NN             | 1   | \$796.10    |
|       | 38 | SPAREWHEEL PANEL TOP BOARD TOP MAT X NN     | 1   | \$456.70    |
|       | 39 | SPAREWHEEL PANEL TOOLBOX (L+R) X NN         | 2   | \$408.40    |
|       | 40 | EXHAUST PIPE X NN                           | 1   | \$1,296.10. |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

1

Signature:

1

Date:

1

|    |                                                            |                |        |                  |        |                    |
|----|------------------------------------------------------------|----------------|--------|------------------|--------|--------------------|
| 41 | EXHAUST GASKET                                             | X              | NN     |                  | 1      | \$ 76.40.          |
| 42 | EXHAUST BRACKET (L+R)                                      | X              | NN     |                  | 2      | \$ 176.20.         |
| 43 | EXHAUST HEAT SHIELD                                        | X              | NN     |                  | 1      | \$ 231.10.         |
|    |                                                            |                |        | P = \$2,227      | 999.9  |                    |
|    |                                                            |                |        | -20% = \$1781.50 | 799.92 | SUBTOTAL           |
|    |                                                            |                |        |                  |        | \$ -               |
|    |                                                            |                |        |                  |        | LESS 20%           |
|    |                                                            |                |        |                  |        | \$ -               |
|    |                                                            |                |        |                  |        | PARTS TOTAL        |
|    |                                                            |                |        |                  |        | \$ -               |
|    | SPECIAL NETT                                               |                |        |                  | QTY    | PRICE              |
| 1  | REAR WINDSCREEN SEALANT                                    | X              | NN     |                  | 1      | \$ 120.00          |
| 2  | BOOTLID INNER TRIM CLIPS                                   | X              | NN     |                  | 10     | \$ 100.00          |
| 3  | BOOTLID EMBLEM (HONDA)                                     | X              | Repeat | <del>250</del>   | 1      | \$ 300.00          |
| 4  | REVERSE CAMERA                                             | /              | DM     | 250              | 1      | \$ 800.00          |
| 5  | REAR CARPLATE                                              | X              | NN     |                  | 1      | \$ 120.00          |
| 6  | REAR CARPLATE FRAME                                        | X              | NN     |                  | 1      | \$ 120.00          |
| 7  | REAR BUMPER CLIPS                                          | /              | NEC    | 20               | 10     | \$ 100.00          |
| 8  | REAR BUMPER REVERSE SENSOR SET                             | <del>250</del> | NN     | 250              | 2      | \$ 300.00          |
| 9  | REAR FENDER SEALANT                                        | X              | NN     |                  | 1      | \$ 120.00          |
| 10 | REAR FENDER INNER TRIM CLIPS                               | X              | NN     |                  | 20     | \$ 200.00          |
| 11 | REAR FENDER COWLING CLIPS                                  | X              | NN     |                  | 20     | \$ 200.00          |
| 12 | REAR FENDER MUDFLAP CLIPS                                  | X              | NN     |                  | 4      | \$ 80.00           |
| 13 | REAR QUARTER PANEL SEALANT                                 | X              | NN     |                  | 1      | \$ 120.00          |
| 14 | END PANEL SEALANT                                          | X              | NN     |                  | 1      | \$ 120.00          |
| 15 | END PANEL TOP GARNISH CLIPS                                | X              | NN     |                  | 10     | \$ 100.00          |
| 16 | SPAREWHEEL PANEL SEALANT                                   | X              | NN     |                  | 1      | \$ 120.00          |
| 17 | SPARE TYRE                                                 | X              | NN     |                  | 1      | \$ 700.00          |
| 18 | SPARE RIM                                                  | X              | NN     | S/N = \$470.     | 270    | \$ 1,000.00        |
|    |                                                            |                |        |                  |        |                    |
|    |                                                            |                |        |                  |        | SPECIAL NETT TOTAL |
|    |                                                            |                |        |                  |        | \$ 4,720.00        |
|    | LABOUR                                                     |                |        |                  | QTY    | PRICE              |
| 1  | TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN      |                |        | <del>4000</del>  | 1      | \$ 3,600.00        |
| 2  | TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA                |                |        | 600              | 1      | \$ 2,400.00        |
| 3  | TO RUST PROOF ACCIDENT AFFECTED AREA                       | NN             | X      |                  | 1      | \$ 250.00          |
| 4  | TO RNR REAR WINDSCREEN                                     | NN             | X      |                  | 1      | \$ 400.00          |
| 5  | TO RNR REAR BOOT MECHANISM                                 |                |        | 40               | 1      | \$ 400.00          |
| 6  | TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS            |                |        | 60               | 1      | \$ 400.00          |
| 7  | TO RNR REVERSE SENSOR & CHECK FUNCTION.                    |                |        | 40               | 1      | \$ 150.00          |
| 8  | TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS                 | NN             | X      |                  | 1      | \$ 250.00          |
| 9  | TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION              |                |        | 30               | 1      | \$ 150.00          |
| 10 | TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE. | NN             | X      |                  | 1      | \$ 400.00          |
| 11 | TO DO WATER LEAK TEST.                                     | NN             | X      |                  | 1      | \$ 80.00           |
| 12 | TO RNR FUEL TANK TO ASSIST WORK LOAD                       | NN             | X      |                  | 1      | \$ 250.00          |
|    |                                                            |                |        | 1270             |        |                    |
|    |                                                            |                |        |                  |        | TOTAL              |
|    |                                                            |                |        |                  |        | \$ 8,730.00        |
|    |                                                            |                |        |                  |        | GRAND TOTAL COST   |
|    |                                                            |                |        |                  |        | \$ 13,450.00       |

4 Days

Unsprung Repair

After repair photos.

Gu. Qiang - 82880282

24/12/19.

LABOUR = \$1270

TOTAL = \$3,521.60

-20% = \$2850.

2339.92

-20%: 1850

