

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 24021

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1514/2019/NS
Date : 26-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured Veh No : SKA 2019 Z

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Ong Kah Lock
Address : 985 Bukit Timah Road
#04-02
Singapore 589627
Telephone : HP +65 97336982
Type of Claim : Own Damage Claims
Policy No. : 1700089391-01
Vehicle No : **SCX 1236 T**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : Dec-17
Engine No : CVN 045463
Chassis No : WAUZZZF47JA025059
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Dec-19
Place of Accident : 91 Tampines Link Carpark Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCX 1236 T

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function.	S/N \$	360.00	/
2	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N \$	600.00	/
3	To install rear windscreen solar film.	S/N \$	400.00	/
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	/
SUB TOTAL LABOUR CHARGES		:	\$ 2,760.00	✓

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCX 1236 T

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00	/
6	To dismantle rear bumper, rear lid. Cut out and weld rhs rear fender. To renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 5,600.00	2500 3000
7	To respray rear bumper, rhs rear fender, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 4,800.00	1650 2200 2500
8	To carry out diagnostic checks.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 14,752.00	6792

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCX 1236 T

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	REAR BUMPER / <i>Re</i>	\$	2,015.00	1612
2	REAR BUMPER FIXING PARTS <i>X NN</i>	\$	66.00	X
3	REAR BUMPER SECURING STRIP <i>- Mc</i>	\$	203.00	X
4	REAR BUMPER SPOILER <i>X NN</i>	\$	227.00	X
5	REAR LIGHT REFLECTOR - RH <i>X NN</i>	\$	38.00	X
6	REAR BUMPER GUIDE SECTION RH <i>X NN</i>	\$	41.00	X
7	REAR BUMPER GUIDE SECTION - LH / RH <i>X NN</i>	2 \$	40.00	X
8	SIDE PANEL - RH <i>- Mc</i>	\$	2,443.00	1954.4
9	REAR WINDSCREEN <i>-</i>	\$	1,049.00	839.2
10	SIDE WINDOW - RH <i>- Mc</i>	\$	561.00	448.4
11	PRIMER <i>-</i>	\$	19.00	14.88
12	LED TAIL LIGHT - RH OUTER <i>- Ser</i>	\$	931.00	744.8
13	TAIL LIGHT TRIM - RH OUTER <i>X NN</i>	\$	27.00	X
14	REAR WHEEL HOUSING LINER - RH <i>X NN</i>	\$	223.00	X
15	WHEEL HOUSING LINER ATTACHMENT PARTS <i>X NN</i>	\$	82.00	X
16	ACRYLIC SEALANT <i>-</i>	S/N \$	180.00	✓
17	CAVITY WAX <i>-</i>	S/N \$	140.00	✓
18	STONE CHIP <i>-</i>	S/N \$	180.00	✓
19	METAL FILLER SEALANT <i>-</i>	S/N \$	280.00	✓
20	REAR WINDSCREEN SEALANT <i>-</i>	S/N \$	200.00	✓
21	1/4 GLASS SEALANT <i>-</i>	S/N \$	100.00	✓
22	SUNDRIES <i>✓</i> <i>Nec</i>	\$	300.00	8.48
TOTAL SPARE PARTS CHARGES		:	\$ 9,345.00	6702.16
TOTAL LABOUR CHARGES		:	\$ 14,752.00	
GRAND TOTAL		:	\$ 24,097.00	16254.16

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

12 Days.

Gua Qiong - 82880282

before paint photos.

27/12/19.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant