

1 AUTOMOTIVE PTE LTD

AutoHub

Ave 2

01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

sales@n51.com.sg

any Reg. No. : 200616038C

Registration No. : 200616038C

HAMSTER CAR RENTAL PTE LTD
BLK 8 BURN ROAD #15-13 TRIVEX
SINGAPORE 369977

Contact : 86089649 , 84513653

ESTIMATE

Repair Code : CLM15878

Date in : 23/12/2019

Vehicle Num. : SLF7321D

Model : HONDA VEZEL 1.5X HYBRID CVT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31210200/LEB5910211

REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET <i>Not in</i>	2	30.00	60.00 +
REAR NUMBER PLATE <i>Not in</i>	1	25.00	25.00 +
REAR NUMBER PLATE HOLDER <i>Not in</i>	1	50.00	50.00 +
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET <i>Not in</i>	1	50.00	50.00 30
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>Not in</i>	1	40.00	40.00 +
REAR TAILGATE SPOILER CLIPS - SET <i>Not in</i>	1	50.00	50.00 +
REAR TAILGATE WINDSCREEN SEALANT <i>Not in</i>	1	60.00	60.00 ✓
REAR TAILLAMP CLIPS L/R - SET <i>Not in</i>	2	30.00	60.00 +
Subtotal before discount			825.00
Percentage discount 0%			0.00
Sub-total 2			825.00
Parts-total			6,877.88

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

~~100.00~~ 50

To remove, reinstall tailgate windscreen

~~150.00~~ 120

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

~~140.00~~ 60

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

~~1,000.00~~ 80

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

~~100.00~~ 80

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

~~1,000.00~~ 80

*** This is a computer-generated document which requires no signature. ***