

INS. CASE OWNER:

CC4 / LPC19012588, Kabinz

LKK:
IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

NELM/19

Date / Time :

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : GBA 8165B

Name of Insured :

Insured Tel No. : HP:

Excess Sec II : S\$ D.O.A. : NELM/19

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

GBG 7417A

INSRS:
WSP: Tony
Tel: Luck
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
13/3/2020	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☐
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☐
	Towing Invoice	☐
	LTA / GIA :	☒
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☒
	LOD	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

5/3/2020

Confirm with: Candy

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost: (w/hrs)

S\$ 6667.60

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 600.00

(\$ 100 x 6 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LOU ☐

[Tick only one]

GIA/LTA Search

S\$ 7.45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 7275.05

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 7275.05

Name 1:

Tang Luck Auto Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$400

COPY SENT 16/3/2020

ASS. REC. BY:

REF: LPC /

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Tony Luck

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1A1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBG 747A Yr Regn: 10, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mer Vito 114 CDI c.c 2143Colour: White / Red A/C: Insured / Std / NI / NASp. Reading: 63.447 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDF 447 60323350245Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size: F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 84 mmL/Bal. 9 mmL/Bal. 94 mmD.O.A. 28/11/19D.O.I. 24/12/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass toP/P - \$6231.40 (Red \$2403.90 / 281)

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

2)

Transportation:

Add Fee: ☐ : Site Insp (\$

) S + RS. \$

☐ : Interview (\$

) F. & S.

☐ : Tech Invs (\$

) Others

☐ : Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19022588/Kdb3

Date: 26.12.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


GBG7417A

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24.12.2019 at the premises of M/s Tong Luck Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	8,635.30
Revised Estimate Amount	: S\$	4,620.40
"Check" Items Amount	: S\$	2,983.20
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Rear Portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 4 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 24 December 2019 9:54 AM
To: Operation / Yu Ching; assignments@lkkauto.com; Nivitha (LKK Auto)
Cc: MT_Claim_SG
Subject: RE: ACCIDENT INVOLVING VEHICLE NO.: GBG7417A & GBA8165B ON 28/11/2019
ALONG SELETAR WEST LINK TOWARDS SELETAR AFTER CTE Our Ref:
19/19/20/VC06/022816 [External General]
Attachments: GBG7417A - NOA.PDF

10:11 am 24/12/19
P: Candy
V: IN
S: Kenneth

Lonpac External - General

Without Prejudice


Dear Yu Ching

Our Insured has not reported the accident. If you still want us to arrange survey, please liaise with LKK Auto Consultants Pte Ltd.

Dear Nivitha

FYA.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Operation / Yu Ching [mailto:operation@tlauto.com.sg]
Sent: Monday, 23 December 2019 12:05 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG
Subject: ACCIDENT INVOLVING VEHICLE NO.: GBG7417A & GBA8165B ON 28/11/2019 ALONG SELETAR WEST LINK TOWARDS SELETAR AFTER CTE

Dear Gerald,

We have our client's instruction to notify you the above accident

Please find attached documents for your information and necessary action

The vehicle is now garage at our workshop

Kindly let us have your surveyor list and arrange for the PRS survey of our client's vehicle at an earlier date

Thanks & regards,
Yu Ching



Tong Luck Auto Pte Ltd

160 Sin Ming Drive

#07-01/06 Sin Ming Autocity

Singapore 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTO CITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GBA8165B

CLAIM TYPE : THIRD PARTY

TP INS. CO. : LONPAC INSURANCE BHD

ACCIDENT DATE : 28/11/2019

TP VEH REG NO : GBA8165B

ESTIMATE

NO : QUOT201912-000058(00)

DATE : 20/12/2019

POLICY NO : 939985730

VEH REG NO : GBG7417A

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323350245

ENGINE NO : 65195034265215

REG. DATE : 2017

*Not Authorized
Presuming B4 panel
4 days*

Estimate Repair Cost to Vehicle No : GBG7417A

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
NET PRICE			
1 Tailgate	1	2,195.00	2,195.00 ✓
2 Tailgate lock	1	230.00	230.00 X
3 Tailgate trimboard clips	15	12.00	180.00 ✓
4 Tailgate centre logo	1	45.00	45.00 ✓
5 Tailgate 'VITO' emblem	1	50.00	50.00 ✓
6 Tailgate '114 CDI' emblem	1	60.00	60.00 ✓
7 Tailgate 'C & C' emblem	1	38.00	38.00 ✓
8 Rear end panel (outer)	1	358.00	358.00 ?
9 Rear bumper	1	1,470.00	1,470.00 ✓
10 Rear bumper reinforcement	1	290.00	290.00 ?
11 Rear bumper reverse sensor	1	183.00	183.00 ✓
12 Rear bumper clips	15	9.00	135.00 ✓
			5,417.00
		Less 10%	541.70
			4,875.30
SPECIAL NET			
13 Rear windscreen sealant	1	60.00	60.00 ✓
14 Tailgate "70km/h" sticker	1	25.00	25.00 15.00
15 Tailgate '6 pax sticker	1	25.00	25.00 15.00
			110.00
LABOUR			
16 To remove and refit rear windscreen glass	1	150.00	150.00 120.00
17 To remove and refit rear bumper sensor	1	100.00	100.00 60.00
18 To check and rectify wiring system	1	80.00	80.00 20.00
19 To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	900.00	900.00 ?
20 To putty and spray paint on affected areas	1	800.00	800.00 400.00
21 To apply rust proofing on replaced and repaired panels	1	120.00	120.00 30.00
22 To supply art works and spray barcode on tailgate	1	1,500.00	1,500.00 ?
			3,650.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GBA8165B
CLAIM TYPE : THIRD PARTY
TP INS. CO. : LONPAC INSURANCE BHD
ACCIDENT DATE : 28/11/2019
TP VEH REG NO : GBA8165B

ESTIMATE

NO : QUOT201912-000058(00)
DATE : 20/12/2019
POLICY NO : 999985730
VEH REG NO : GBG7417A
MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR
CHASSIS NO : WDF44760323350245
ENGINE NO : 66195034265215
REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBG7417A

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 8,535.30
		ADD GST @ 7%	604.47
		GRAND TOTAL	S\$ 9,239.77

SINGAPORE DOLLAR NINE THOUSAND TWO HUNDRED THIRTY-NINE AND CENTS SEVENTY-SEVEN ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118
ATTN : ACCOUNTS DEPT

FAX :

YOUR REF NO : GBA8165B
CLAIM TYPE : THIRD PARTY
TP INS. CO. : LONPAC INSURANCE BHD
ACCIDENT DATE : 28/11/2019
TP VEH REG NO : GBA8165B

ESTIMATE

NO : QUOT201912-000058(00)
DATE : 20/12/2019
POLICY NO : 999995730
VEH REG NO : GBG7417A
MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR
CHASSIS NO : WDF44760323350245
ENGINE NO : 65195034265215
REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBG7417A

Description	Quantity	Unit Price	Amount
		SS	SS

NET PRICE

1 Tailgate	1	2,195.00	2,195.00 ✓
2 Tailgate lock <i>Reuse</i>	1	230.00	230.00 X
3 Tailgate trimboard clips	15	12.00	180.00 ✓
4 Tailgate centre logo	1	45.00	45.00 ✓
5 Tailgate 'VITO' emblem	1	50.00	50.00 ✓
6 Tailgate '114 CDI' emblem	1	60.00	60.00 ✓
7 Tailgate 'C & C' emblem	1	38.00	38.00 ✓
8 Rear end panel (outer)	1	358.00	358.00 R ✓
9 Rear bumper	1	1,470.00	1,470.00 Bu ✓
10 Rear bumper reinforcement	1	290.00	290.00 CR ✓
11 Rear bumper reverse sensor	1	183.00	183.00 CR ✓
12 Rear bumper clips	15	9.00	135.00 ✓
			5,417.00
			Less 10%
			4,875.30

SPECIAL NET

13 Rear windscreen sealant	1	60.00	60.00 CR ✓
14 Tailgate "70km/h" sticker	1	25.00	25.00 CR ✓
15 Tailgate '6 pax sticker	1	25.00	25.00 CR ✓
			110.00

LABOUR

16 To remove and refit rear windscreen glass	1	150.00	150.00 120 ✓
17 To remove and refit rear bumper sensor	1	100.00	100.00 60 ✓
18 To check and rectify wiring system	1	80.00	80.00 20 ✓
19 To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	900.00	900.00 300 ✓
20 To putty and spray paint on affected areas	1	800.00	800.00 400 ✓
21 To apply rust proofing on replaced and repaired panels	1	120.00	120.00 30 ✓
22 To supply art works and spray barcode on tailgate	1	1,500.00	1,500.00 2 ✓
			3,650.00

1980



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GBA8165B

CLAIM TYPE : THIRD PARTY

TP INS. CO. : LONPAC INSURANCE BHD

ACCIDENT DATE : 28/11/2019

TP VEH REG NO : GBA8165B

ESTIMATE

NO : QUOT201912-000058(00)

DATE : 20/12/2019

POLICY NO : 999995730

VEH REG NO : GBG7417A

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323350245

ENGINE NO : 65195034265215

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBG7417A

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 8,635.30
		ADD GST @ 7%	604.47
		GRAND TOTAL	S\$ 9,239.77

SINGAPORE DOLLAR NINE THOUSAND TWO HUNDRED THIRTY-NINE AND CENTS SEVENTY-SEVEN ONLY

\$ 6,231.40 ✓ ok
7% 436.20
\$ 6,667.60

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

JE-Graphics PTE LTD

48 Toh Guan Road East
#08-123 EnterpriseHub
Singapore 608586
Tel: 6316-7246 Fax: 6316-7248
E-MAIL: sales@jegraphics.com.sg
GST REG NO.: 200504725D
CO REG NO.: 200504725D

TO: TONG LUCK AUTO PTE LTD

TAX INVOICE : 20200106

ATTN : Terence Tan
TEL/FAX : 9623 5378

DATE : 03/01/2020
P/O :
D/O :
TERMS : CASH
SALESMAN CODE : PN
PAGE NO. : 001

NO.	DESCRIPTION	QTY UOM	UNIT-PRICE	AMOUNT
			SGD	SGD
	GRAPHIC/BARCODE REINSTATEMENT ON GBG7417A MERC VITO	1.000 LOT	850.00	850.00
	TO REINSTATE GRAPHIC / BARCODE WORK ON REAR DOOR			
	JE REF: JE/2019/12093			

SUB-TOTAL 950.00


ADD 7.00% GST 59.50
TOTAL 909.50

SINGAPORE DOLLARS: NINE HUNDRED & NINE AND CENTS FIFTY ONLY

Cheque should be crossed and made payable to JE-Graphics PTE LTD.
1.5% interest shall be charged for all overdue invoices. Discrepancies if any, should be verified within 7 days from date hereof. Deposit are not refundable & transferable.

E. & O.E

JE-Graphics PTE LT





TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GBA8165B

CLAIM TYPE : THIRD PARTY

TP INS. CO. : LONPAC INSURANCE BHD

ACCIDENT DATE : 28/11/2019

TP VEH REG NO : GBA8165B

ESTIMATE

NO : QUOT201912-000058(00)

DATE : 20/12/2019

POLICY NO : 999995730

VEH REG NO : GBG7417A

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323350245

ENGINE NO : 65195034265215

REG. DATE : 2017

*Not Authorized
Personnel
4 days*

Estimate Repair Cost to Vehicle No : GBG7417A

Description	Quantity	Unit Price	Amount
		SG	SG
NET PRICE			
1 Tailgate	1	2,195.00	2,195.00 ✓
2 Tailgate lock	1	230.00	230.00 X
3 Tailgate trimboard clips	15	12.00	180.00 ✓
4 Tailgate centre logo	1	45.00	45.00 ✓
5 Tailgate 'VITO' emblem	1	50.00	50.00 ✓
6 Tailgate '114 CDI' emblem	1	60.00	60.00 ✓
7 Tailgate 'C & C' emblem	1	38.00	38.00 ✓
8 Rear end panel (outer)	1	358.00	358.00 ?
9 Rear bumper	1	1,470.00	1,470.00 ✓
10 Rear bumper reinforcement	1	290.00	290.00 ?
11 Rear bumper reverse sensor	1	183.00	366.00 ✓
12 Rear bumper clips	15	9.00	135.00 ✓
			5,417.00
		Less 10%	541.70
			4,875.30
SPECIAL NET			
13 Rear windscreen sealant	1	60.00	60.00 405n
14 Tailgate "70km/h" sticker	1	25.00	25.00 155n
15 Tailgate '6 pax sticker	1	25.00	25.00 155n
			110.00
LABOUR			
16 To remove and refit rear windscreen glass	1	150.00	150.00 120l
17 To remove and refit rear bumper sensor	1	100.00	100.00 60l
18 To check and rectify wiring system	1	80.00	80.00 20l
19 To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	900.00	900.00 ?
20 To putty and spray paint on affected areas	1	800.00	800.00 400l
21 To apply rust proofing on replaced and repaired panels	1	120.00	120.00 30l
22 To supply art works and spray barcode on tailgate	1	1,500.00	1,500.00 ?
			3,650.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary detail(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature: _____
Date: _____



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GBA8165B

CLAIM TYPE : THIRD PARTY

TP INS. CO. : LONPAC INSURANCE BHD

ACCIDENT DATE : 28/11/2019

TP VEH REG NO : GBA8165B

ESTIMATE

NO : QUOT201912-000058(00)

DATE : 20/12/2019

POLICY NO : 999995730

VEH REG NO : **GBG7417A**

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323350245

ENGINE NO : 65195034265215

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBG7417A

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 8,635.30
		ADD GST @ 7%	604.47
		GRAND TOTAL	S\$ 9,239.77

SINGAPORE DOLLAR NINE THOUSAND TWO HUNDRED THIRTY-NINE AND CENTS SEVENTY-SEVEN ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC19022588/Kda3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 17-03-2020	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 8165B	Veh. Inspected	GBG 7417A	
Policy No.	Z/19/VC06/103770	Coverage (\$)	0.00	
Claim No.	19/19/20/VC06/022816	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	24/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES VITO 114 CDI	c.c	2143	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WDF44760323350245	Colour	WHITE / RED	
Odometer	63447	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MICHELIN	9 mm	
L/H Front Tyre	205/65 R16	MICHELIN	9 mm	
R/H Rear Tyre	205/65 R16	MICHELIN	4 mm	
L/H Rear Tyre	205/65 R16	MICHELIN	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/11/2019	Inspection Date	24/12/2019	
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 7417A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE (N)	BENT	2,195.00	2,195.00
1	TAILGATE LOCK (N)	TO REPAIR SEE LABOUR	230.00	-
15	TAILGATE TRIMBOARD CLIPS @\$12.00 (N)	NECESSARY	180.00	180.00
1	TAILGATE CENTRE LOGO (N)	NECESSARY	45.00	45.00
1	TAILGATE "VITO" EMBLEM (N)	NECESSARY	50.00	50.00
1	TAILGATE "114 CDI" EMBLEM (N)	NECESSARY	60.00	60.00
1	TAILGATE "C & C" EMBLEM (N)	NECESSARY	38.00	38.00
1	REAR END PANEL (OUTER)(N)	TO REPAIR SEE LABOUR	358.00	-
1	REAR BUMPER (N)	BUCKLED	1,470.00	1,470.00
1	REAR BUMPER REINFORCEMENT (N)	CRACKED	290.00	290.00
2	REAR BUMPER REVERSE SENSOR @\$183.00 (N)	MISSING (1 PC ONLY)	366.00	183.00
15	REAR BUMPER CLIPS @\$9.00 (N)	NECESSARY	135.00	135.00
	LESS 10% DISCOUNT		-541.70	-464.60
			4,875.30	4,181.40
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	TAILGATE "70KM/H" STICKER (SN)	NECESSARY	25.00	15.00
1	TAILGATE "8 PAX" STICKER (SN)	NECESSARY	25.00	15.00
			110.00	70.00
LABOUR				
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		150.00	120.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		100.00	60.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	20.00
	TO PANEL BEAT AND STRAIGHTEN REAR FLOORBOARD PANEL,REAR CHASSIS FRAME.TO CUT AND WELD REAR END PANEL,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY.TO REFIT AND ADJUST THE SAME.INCLUSIVE OF THE REPAIR OF TAILGATE LOCK AND REAR END PANEL.		900.00	500.00
	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS.		800.00	400.00

Report Ref No. CC4/LPC19022588/Kda3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUST PROOFING ON REPLACED AND REPAIRED PANELS.		120.00	30.00
	TO SUPPLY ART WORKS AND SPRAY BARCODE ON TAILGATE.		1,500.00	850.00
			3,650.00	1,980.00
GRAND TOTAL			8,635.30	6,231.40
RECOMMENDED COST OF REPAIRS				6,231.40

Report Ref No. CC4/LPC19022588/Kda3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.