



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GBA8165B

CLAIM TYPE : THIRD PARTY

TP INS. CO. : LONPAC INSURANCE BHD

ACCIDENT DATE : 28/11/2019

TP VEH REG NO : GBA8165B

ESTIMATE

NO : QUOT201912-000058(00)

DATE : 20/12/2019

POLICY NO : 999995730

VEH REG NO : GBG7417A

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323350245

ENGINE NO : 65195034265215

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBG7417A

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Tailgate	1	2,195.00	2,195.00 ✓
2 Tailgate lock	1	230.00	230.00 X
3 Tailgate trimboard clips	15	12.00	180.00 ✓
4 Tailgate centre logo	1	45.00	45.00 ✓
5 Tailgate 'VITO' emblem	1	50.00	50.00 ✓
6 Tailgate '114 CDI' emblem	1	60.00	60.00 ✓
7 Tailgate 'C & C' emblem	1	38.00	38.00 ✓
8 Rear end panel (outer)	1	358.00	358.00 ?
9 Rear bumper	1	1,470.00	1,470.00 ✓
10 Rear bumper reinforcement	1	290.00	290.00 ?
11 Rear bumper reverse sensor	2	183.00	366.00 ✓
12 Rear bumper clips	15	9.00	135.00 ✓
			5,417.00
		Less 10%	541.70
			4,875.30
SPECIAL NET			
13 Rear windscreen sealant	1	60.00	60.00 405n
14 Tailgate "70km/h" sticker	1	25.00	25.00 155n
15 Tailgate '6 pax sticker	1	25.00	25.00 155n
			110.00
LABOUR			
16 To remove and refit rear windscreen glass	1	150.00	150.00 120n
17 To remove and refit rear bumper sensor	1	100.00	100.00 60n
18 To check and rectify wiring system	1	80.00	80.00 20n
19 To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	900.00	900.00 ?
20 To putty and spray paint on affected areas	1	800.00	800.00 400n
21 To apply rust proofing on replaced and repaired panels	1	120.00	120.00 30n
22 To supply art works and spray barcode on tailgate	1	1,500.00	1,500.00 ?
			3,650.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GBA8165B

CLAIM TYPE : THIRD PARTY

TP INS. CO. : LONPAC INSURANCE BHD

ACCIDENT DATE : 28/11/2019

TP VEH REG NO : GBA8165B

ESTIMATE

NO : QUOT201912-000058(00)

DATE : 20/12/2019

POLICY NO : 999995730

VEH REG NO : **GBG7417A**

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323350245

ENGINE NO : 65195034265215

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBG7417A

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
		TOTAL	S\$ 8,635.30
		ADD GST @ 7%	604.47
		GRAND TOTAL	<u>S\$ 9,239.77</u>

SINGAPORE DOLLAR NINE THOUSAND TWO HUNDRED THIRTY-NINE AND CENTS SEVENTY-SEVEN ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE