



ESTIMATE

DATE OF ACCIDENT : 17/12/2019
VEHICLE : SJW4221M
MAKE & MODEL : TOYOTA SIENTA
INSURANCE : FIRST CAPITAL
SURVEYOR : LKK AUTO

PARTS		CONDITION	AMOUNT
1.	DOOR – FRONT LEFT / Bmc		\$ 855
2.	DOOR – REAR LEFT x Repair		\$ 912
3.	DOOR HANDLE – FRONT LEFT 2 ?		\$ 332
4.	DOOR VISOR – FRONT LEFT / MC.		\$ 120
5.	DOOR HINGE – FRONT LEFT (UPPER) / 1/2 BT.		\$ 86
6.	DOOR HINGE – FRONT LEFT (LOWER) / 1/2 BT.		\$ 86
7.	DOOR GARNISH – REAR LEFT / Scr.		\$105
8.	DOOR RAILING – REAR LEFT ? 1/2 1/2 .		\$ 480
9.	SIDE MIRROR - LEFT / Dis		\$ 665
10.	SIDE MIRROR COVER - LEFT / Cut .		\$ 76
11.	1/4 GLASS / Scr		\$ 120
12.	1/4 GLASS FRAME /		\$ 85
13.	1/4 GLASS WEATHER STRIP / 1/2 Scr		\$ 45



JACK CARS

DRIVE WITH ASSURANCE

14.	FRONT FENDER - LEFT X Repair.		\$ 305
15.	REAR FENDER - LEFT / Dis.		\$ 990
16.	REAR FENDER GARNISH - LEFT / Cut		\$ 420
17.	REAR FENDER INNER VENT COVER - LEFT / Re.		\$ 40
18.	REAR FENDER BRACKET - LEFT R / Cut		\$ 86
19.	REAR BUMPER / Re.		\$ 315
20.	REAR BUMPER GARNISH - LEFT / TN		\$ 115
21.	REAR BUMPER GARNISH - CENTRE X NN		\$ 160
22.	REAR BUMPER BRACKET - LEFT D / CFA		\$ 86
23.	FUEL PUMP COVER / BT.		\$ 95
24.	MUDGUARD - REAR LEFT / Re.		\$ 180
25.	TAIL LAMP - OUTER LEFT / mis Dis		\$ 300
26.	TAIL LAMP - INNER LEFT X		\$ 210
27.	CROSSMEMBER - REAR X		\$ 1900
28.	LOWER ARM - REAR LEFT X		\$ 200
29.	LOWER KNUCKLE - REAR LEFT X { NN		\$ 320
30.	BEARING - REAR LEFT / MCL.		\$ 475
31.	ABSORBER - REAR LEFT R ?		\$ 200
		Disc - 25%	
	SPECIAL NETT		
1.	BUMPER CLIPS / MCL.		\$ 100



JACK CARS

DRIVE WITH ASSURANCE

2.	PARKING SENSOR X NN		\$ 250
3.	RIM - REAR / Cut	250.	\$ 350
	LABOUR		
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	1200 1000	\$ 2500
2.	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	1000	\$ 3000
3.	TO CHECK LIGHTING SYSTEM, WIRING & REWIRE	30	\$ 250
4.	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	80	\$ 120
5.	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	60	\$ 180
6.	ANTI RUST TREATMENT	60	\$ 120
7.	WHEEL BALANCING & ALIGNMENT	60.	\$ 100
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____	PARTS -25 %:	\$ 7,773
		SPECIAL NETT :	\$ 700
		LABOUR :	\$ 6,270
		TOTAL :	\$ 14,743
		7% GST :	\$ 1,032.01
		GRAND TOTAL :	\$ 15,775.01

8 Days.

Quo Qiang - 82880282

26/12/19.

P/P, before paint photos