



JACK CARS

DRIVE WITH ASSURANCE

ESTIMATE

DATE OF ACCIDENT : 17/12/2019
VEHICLE : SJW4221M
MAKE & MODEL : TOYOTA SIENTA
INSURANCE : FIRST CAPITAL
SURVEYOR : LKK AUTO

PARTS		CONDITION	AMOUNT	
1.	DOOR – FRONT LEFT / Bmc		\$ 855	✓
2.	DOOR – REAR LEFT x Repair		\$ 912	
3.	DOOR HANDLE – FRONT LEFT x ? NN		\$ 332	
4.	DOOR VISOR – FRONT LEFT / MC.		\$ 120	✓
5.	DOOR HINGE – FRONT LEFT (UPPER) / 4BT.		\$ 86	✓
6.	DOOR HINGE – FRONT LEFT (LOWER) / 4BT.		\$ 86	✓
7.	DOOR GARNISH – REAR LEFT / Scr.		\$105	✓
8.	DOOR RAILING – REAR LEFT x NN 1/4 1/4		\$ 480	
9.	SIDE MIRROR - LEFT / Dis		\$ 665	✓
10.	SIDE MIRROR COVER - LEFT / Cut.		\$ 76	✓
11.	1/4 GLASS / Scr		\$ 120	✓
12.	1/4 GLASS FRAME /		\$ 85	✓
13.	1/4 GLASS WEATHER STRIP / 4 Scr		\$ 45	✓



14.	FRONT FENDER - LEFT <i>X Repair.</i>		\$ 305	
15.	REAR FENDER - LEFT <i>/ Dis.</i>		\$ 990	✓
16.	REAR FENDER GARNISH - LEFT <i>/ Cut</i>		\$ 420	✓
17.	REAR FENDER INNER VENT COVER - LEFT <i>/ Re.</i>		\$ 40	✓
18.	REAR FENDER BRACKET - LEFT <i>Re / Cut</i>		\$ 86	✓
19.	REAR BUMPER <i>/ Re.</i>		\$ 315	✓
20.	REAR BUMPER GARNISH - LEFT <i>/ TN</i>		\$ 115	✓
21.	REAR BUMPER GARNISH - CENTRE <i>X NN</i>		\$ 160	
22.	REAR BUMPER BRACKET - LEFT <i>Re / CFA</i>		\$ 86	✓
23.	FUEL PUMP COVER <i>/ BT.</i>		\$ 95	✓
24.	MUDGUARD - REAR LEFT <i>/ Re.</i>		\$ 180	✓
25.	TAIL LAMP - OUTER LEFT <i>/ mis. Dis</i>		\$ 300	✓
26.	TAIL LAMP - INNER LEFT <i>X NN</i>		\$ 210	
27.	CROSSMEMBER - REAR <i>X ✓ BT</i>		\$ 1900	✓
28.	LOWER ARM - REAR LEFT <i>X</i>		\$ 200	
29.	LOWER KNUCKLE - REAR LEFT <i>X { NN</i>		\$ 320	
30.	BEARING - REAR LEFT <i>/ MCL.</i>		\$ 475	✓
31.	ABSORBER - REAR LEFT <i>Re ✓ BT</i>	7445	\$ 200	✓
		<i>Disc - 25%</i>	5583.75	
	SPECIAL NETT			
1.	BUMPER CLIPS <i>/ MCL.</i>		\$ 100	30



JACK CARS

DRIVE WITH ASSURANCE

2.	PARKING SENSOR X NN		\$ 250
3.	RIM - REAR / Cut	250.	\$ 350
			280
LABOUR			
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	1200 1000	\$ 2500
2.	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	1000	\$ 3000
3.	TO CHECK LIGHTING SYSTEM, WIRING & REWIRE	30	\$ 250
4.	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	80	\$ 120
5.	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	60	\$ 180
6.	ANTI RUST TREATMENT	60	\$ 120
7.	WHEEL BALANCING & ALIGNMENT	60.	\$ 100
8.	To remove and reinstall undercarrige	250	✓
		PARTS -25 %:	\$ 7,773
		SPECIAL NETT :	\$ 700
		LABOUR :	\$ 6,270
		TOTAL :	\$ 14,743
		7% GST :	\$ 1,032.01
		GRAND TOTAL :	\$ 15,775.01

2740

8 Days.

Quo Qiang - 82880282

8603.75

26/12/19.

P/P, before paint photos