

Bifrost Auto Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201929175W

Vehicle No: SKJ3882T
 Model: Mazda 6 2.5L
 Chassis No: JM6GJ1031F0146680
 Year of manufacture: 2014

NO.	DESCRIPTION	QTY	U/P	AMT
#	List Items			
1	Front bumper ✓ cut	1		
2	Front bumper retainer RH X (svc)	1		
3	Front bumper retainer LH ✓ CRU	1		
4	Front bumper sponge X (svc)	1		
5	Front bumper parking sensor X (svc)	2		
6	Fog lamp LH ?	1		
7	Fog lamp garnish LH ?	1		
8	Front bumper under cover X (svc)	1		
9	Head lamp LH ✓ SCR	1		
10	Head lamp lower bracket LH ?	1		
11	Front fender LH ✓ BT	1		
12	Front fender inner shield LH ?	1		
13	Front wheel rim LH ✓ SCR	1		
14	Front absorber LH ?	1		
17	Front absorber top mounting LH X (svc)	1		
18	Front knuckle arm LH ?	1		
19	Front knuckle bearing LH ?	1		
20	Front lower arm LH X	1		

0.00

Special Nett Items

21	225/55/17 Michelin tyre LH X (old change)	1		250.00
22	Front bumper clip set ✓ new	1		50.00 30
23	Front fender inner shield clip set ✓ new	1		50.00 25
				<u>350.00</u>

Labour & Miscellaneous Charge

24	To R&R front bumper parking sensor ✓	1		100.00 20
25	To conduct head lamp focus ✓	1		100.00 20
26	To check wiring and lighting system ✓	1		80.00 30
27	To supply under coating / putty on parts replaced X	1		80.00
28	To perform anti rust treatment on affected areas X	1		60.00
29	To conduct all wheel alignment before and after report	1		180.00 60 ?
30	To R&R front LH wheel rim , tyre and balancing X	1		50.00
31	To R&R front LH under-carriage damaged parts - photo	1		350.00 ?
32	To press front LH knuckle bearing assy	1		100.00 3
33	To repair , replace and realign damaged areas ✓	1		800.00 450

34	To spray painting on affected areas ✓	1	800.00 400
35	Sundries X	1	50.00

			=====
			2750.00

List Items Subtotal _____
Special Nett Items Subtotal _____
Labour Items Subtotal _____
Total =====

*L/S repair
without prejudice
resurvey offer part
4 Long
23/12/19
4:20pm
Hoch ANW
HCC
853/11893
Hoch ANW@lkkAuto.com*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: