

Bifrost Auto Pte Ltd  
 No. 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875  
 Tel: +65 6452 4457 | Fax: +65 6452 4584  
 Co. Reg. No.: 201929175W

Vehicle No: SKJ3882T  
 Model: Mazda 6 2.5L  
 Chassis No: JM6GJ1031F0146680  
 Year of manufacture: 2014

NO.	DESCRIPTION	QTY	U/P	AMT
1	Front bumper ✓ <i>ent</i>	1	1496.70	1211.90 ✓
2	Front bumper retainer RH X (svc)	1	112.30	
3	Front bumper retainer LH ✓ <i>CRU</i>	1	112.30	
4	Front bumper sponge X (svc)	1	158.70	87.30 ✓
5	Front bumper parking sensor X (svc)	2	500.00	
6	Fog lamp LH ✓ <i>CRU</i>	1	327.60	
7	Fog lamp garnish LH ✓ <i>CRU</i>	1	105.60	
8	Front bumper under cover X (svc)	1	182.30	
9	Head lamp LH ✓ <i>SCR</i>	1	1570.80	1250.70 ✓
10	Head lamp lower bracket LH X (capture)	1	-	
11	Front fender LH ✓ <i>st</i>	1	1155.70	580.80 ✓
12	Front fender inner shield LH ✓ <i>CRU</i>	1	482.30	232.80 ✓
13	Front wheel rim LH ✓ <i>SCR</i>	1	1750.00	1277.20 ✓
14	Front absorber LH ✓ <i>CRU</i>	1	582.50	471.90 ✓
17	Front absorber top mounting LH X (svc)	1	238.60	
18	Front knuckle arm LH ✓ <i>CRU</i>	1	695.30	400.30 ✓
19	Front knuckle bearing LH ✓ <i>CRU</i>	1	235.00	
20	Front lower arm LH X	1	572.40	

Special Nett Items			0.00
21	225/55/17 Michelin tyre LH X (capture) NN	1	250.00
22	Front bumper clip set ✓ <i>me</i>	1	50.00 30 ✓
23	Front fender inner shield clip set ✓ <i>me</i>	1	50.00 25 ✓
			<u>350.00</u>

Labour & Miscellaneous Charge			
24	To R&R front bumper parking sensor ✓	1	100.00 70 ✓
25	To conduct head lamp focus ✓	1	100.00 70 ✓
26	To check wiring and lighting system ✓	1	80.00 30 ✓
27	To supply under coating / putty on parts replaced X	1	80.00
28	To perform anti rust treatment on affected areas X	1	60.00
29	To conduct all wheel alignment before and after repair	1	180.00 60 ✓
30	To R&R front LH wheel rim, tyre and balancing X	1	50.00
31	To R&R front LH under-carriage damaged parts - photo	1	350.00 3 150 ✓
32	To press front LH knuckle bearing assy	1	100.00
33	To repair, replace and realign damaged areas ✓	1	800.00 450 ✓

34 To spray painting on affected areas ✓  
 35 Sundries X

1 ~~800.00~~ 400 ✓  
 1 ~~50.00~~

2750.00

List Items Subtotal  
 Special Nett Items Subtotal  
 Labour Items Subtotal  
 Total

L/S repair  
 without prejudice  
 message after part  
 4 day  
 23/12/14

4:20pm  
 Hock ANW  
 ALG  
 85311883  
 Hock ANW@lkkAuto.com

Resurvey take.  
 3:15pm  
 Hock ANW  
 ALG  
 85311883  
 24/12/14

parts = 8513.80 - 20% AAA  
 = 6811

S/N = 55

Labour = 1130

PT+L = 7996.00 - 20% L/S  
 = \$6400

parts 6181.10

parts less 20%

4944.88

spe net 55

labour 1130

6129.88

L/S less 20%

4903.90

total

L/S part → \$4900

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: