



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI19022595/Uka3s2

36 ROBINSON ROAD  
#16-01 CITY HOUSES SINGAPORE 068877

Date : 08-07-2020



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHA 983M	<b>Veh. Inspected</b>	SLG 6155T
<b>Policy No.</b>	D-18088937MFSH	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D19008054MFSH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	MERINA CHIA SAN SAN	<b>Assign Date</b>	24/12/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	AUDI A6 (A)	<b>c.c</b>	1984
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2008
<b>Chassis No.</b>	WAUZZZ4F38N119625	<b>Colour</b>	GREY
<b>Odometer</b>	189398	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	225/50 R17	YOKOHAMA	6 mm
<b>L/H Front Tyre</b>	225/50 R17	YOKOHAMA	6 mm
<b>R/H Rear Tyre</b>	225/50 R17	YOKOHAMA	6 mm
<b>L/H Rear Tyre</b>	225/50 R17	YOKOHAMA	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	21/12/2019	<b>Inspection Date</b>	26/12/2019
<b>Survey held at</b>	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>10 Working Days</b>
-------------------------------------	------------------------