

For /

ASSIGNMENT

Form _____ Date _____

Estimated Cost _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No. 526 61557

at Workshop no. 124

of _____

Insured SHA 983M

Policy No. _____

Claims No. _____

Sum Insured _____ Excess _____

(Client's Record)

Make of Veh. _____

Van No. SLG 6457 Cr. Page: 5 08
 Type: M. Cab / M. Cystle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA /
 Make: Audi A6 cc 1984
 Colour: Grey A/C: Insured / Stk / NI / NA
 Sp. Reading: 189398 T. Radio: Insured / Stk / NI / NA
 Engine No.
 C.No: WAUZZZ4F38N119625
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brakes: Good / Jammed / Leaked / Burnt or
 Mod: Nil / Leaked / STD / Oil / or
 Tyre Size: F 225/50 R17

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bid. or Market Value	280k		
IDAC Accident Report	Consistent?	Yes or No	
GIA / PR Seen	Consistent?	Yes or No	
Est Repairs	10 days	Res.	Yes or No
Lum Sum	20 %	3 Val.	Yes or No

BS / DUN / EXHOVA / GY / PS / LZA / MIC / CHTSU / PW / SJNH /
TOYO / TOKI or

Front	6	mm	Back	6	mm
R/Bal	6	mm	R/Bal	6	mm
L/Bal	8	mm	L/Bal	6	mm
D.O.A	21/12/19		D.O.E	26/12/19	

Survey held at _____

CA / REV / REP. / 24 HRS
Date: Person Contacted: Vehicle: IN / OUT

Des. of Damages : Fnt / Rear / O/S / W/S / U/C / Roofing or
Rear & L.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/16/81	10/16/81 2023
house 6.1A	10/16/81 2023 3yrs south.
not 14887	

8/1/20 1/5 of 14,800 confid with Alen
(ced \$ 59,319.10 / 80%)

Date/Time: File Pass to? ☐ : Prel. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee: ☐ Site Insp (\$☐ Interview (5)

□ Tech. Invs (\$)

☐ Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

FASTTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50
SINGAPORE 417883

FAST Auto Consultants hereto notify
the Repairer of the following:
• To remove surface after spray painting
• To display damaged parts during recovery
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No direct modification(s) is allowed
• Supplementary (parts) must be recovered and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

VEHICLE NO: SL661587

QTY	PARTICULAR
1 PCS	BOOTLID 2665.15
1 PCS	BOOTLID REAR LOGO
1 PCS	BOOTLID 'A6' EMBLEM 88.20
1 PCS	BOOTLID '2.0T' EMBLEM 80.50
1 PCS	BOOTLID INNER LOCK
1 PCS	BOOTLID LOCK STRIKER
1 PCS	BOOTLID WEATHERSTRIP 215.45
2 PCS	BOOTLID REFLECTORS @\$1005.00
1 PCS	BOOTLID INNER TRIM
1 SET	BOOTLID INNER TRIM CLIPS
2 PCS	BOOTLID LICENCE PLATE LAMPS @\$95.00
1 PCS	REAR BUMPER 2005.35
1 PCS	REAR BUMPER LOWER SKIRTING 345.00
1 PCS	REAR BUMPER SPONGE
1 PCS	REAR BUMPER REINFORCEMENT 715.00
2 PCS	REAR BUMPER BRACKETS @\$145.00
2 PCS	REAR BUMPER SIDE HOLDERS @\$135.00
4 PCS	REAR BUMPER PDC SENSORS @\$313.75 208 x 2 = 416
1 PCS	REAR BUMPER PDC SENSOR WIRE
1 PCS	REAR BUMPER TOW COVER
1 PCS	REAR BUMPER TOP RETAINER
1 PCS	REAR END PANEL
1 PCS	REAR END PANEL EXTENSION LOWER 266.15
1 PCS	REAR END PANEL TOP GARNISH
2 PCS	TAILLAMPS @\$1205.00 750 x 2 = 1500
1 PCS	REAR END PANEL INNER MEMBER 415.00
1 PCS	REAR EXHAUST N/S
1 PCS	REAR EXHAUST O/S
1 PCS	REAR EXHAUST HEATSHIELD
1 PCS	REAR FLOOR PANEL
1 PCS	REAR FLOOR PANEL TOP BOARD
2 PCS	REAR FENDERS @\$3650.00
2 PCS	REAR FENDER INNER TRIMS @\$366.20
3 PCS	FRONT SEAT BELTS @\$920.00
1 SET	HEADREST REPAIR KIT
1 PCS	BATTERY CABLE
1 PCS	BONNET
1 PCS	BONNET LOCK
1 PCS	BONNET SEAL

not Affected
26/12/19
10 day. d/s \$14,800/

Bodywork	\$3,066.20	✓
211	\$100.85	✓
211	\$102.30	✓
211	\$108.00	✓
111	\$315.50	✓
117	\$105.20	X
111	\$266.20	✓
117	\$2,010.00	X
117	\$488.25	X
111	\$50.00	X
117	\$190.00	✓
111	\$2,005.00	✓
111	\$100.00	✓
117	\$210.30	X
111	\$225.00	✓
111	\$290.00	X
015/01	\$220.00	4pc 135
117	\$1,285.00	3pc
117	\$285.60	X
117	\$45.00	X
111	\$165.00	X
Bodywork	\$580.60	✓
Bodywork	\$315.00	✓
111	\$295.00	✓
111	\$2,410.00	✓
111	\$495.00	✓
111	\$1,685.00	X
111	\$1,595.00	X
117	\$185.00	X
111	\$1,150.00	X
111	\$825.30	X
111	\$7,300.00	X
117	\$732.40	X
117	\$1,840.00	X
111	\$245.00	X
117	\$252.00	X
111	\$3,145.00	X
111	\$185.50	X
117	\$88.00	X

(52)

1 PCS	BONNET INSULATOR	17	\$260.55	X
1 SET	BONNET INSULATOR CLIPS	17	\$50.00	X
2 PCS	BONNET HINGES @\$115.00	17	\$230.00	X
1 PCS	FRONT BUMPER 2005-35	D.S	\$2,655.00	
2 PCS	FRONT SIDE REATINERS @\$105.00	17	\$210.00	X
1 PCS	FRONT BUMPER SPONGE	17	\$205.00	X
1 PCS	FRONT BUMPER REINFORCEMENT 755.20	17	\$965.00	X
2 PCS	FRONT BUMPER REINFORCEMENT STAYS @\$145.00	17	\$290.00	X
1 PCS	FRONT GRILLE 1155.00	CM	\$1,258.00	
1 PCS	FRONT GRILLE LOGO	17	\$100.85	
2 PCS	FRONT PDC SENSORS @\$315.00 208 x 2 = 416	3/4" 17	\$638.00	X
2 PCS	HEADLAMP ASSYS @\$6800.0 2 455-35 x 2 = 4910.70	CM	\$13,600.00	X
1 PCS	FRONT SUPPORT PANEL	SU	\$1,055.00	X
1 PCS	AIR CON CONDENSER 735.00	17	\$1,205.00	X
1 PCS	RADIATOR	SU	\$1,350.00	X
1 PCS	RADIATOR FAN ASSY	17	\$1,385.00	X
1 PCS	HORN UNIT	17	\$110.00	X
1 PCS	TURBO COOLER	17	\$820.00	X
			\$64,249.10	
	S.NETT			
1 PCS	REAR LICENCE PLATE W/HOLDER	17	\$50.00	X
1 PCS	REAR END PANEL SEALANT	17	\$50.00	X
1 PCS	REAR WINDSCREEN SEALANT	17	\$50.00	X
1 SET	REAR EXHAUST CHROME	17	\$280.00	X
1 PCS	REAR FLOOR PANEL INSULATOR	17	\$50.00	X
1 PCS	FRONT LICENCE PLATE	17	\$50.00	X
1 PCS	RADIATOR COOLANT	17	\$50.00	X
1 BOT	LABOUR CHRAGES:			
	TO CHECK WIRING		\$80.00	30
	TO DISMANTLE & REPLACING PDC SENSOR		\$100.00	50
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTREY		\$150.00	80
	TO DISMANTLE & REFIX REAR EXHAUST		\$150.00	80
	TO DISMANTLE & REFIX REAR WINDSCREEN	17	\$150.00	X
	TO TRANSFER BOOTLID MECHANISM		\$150.00	60
	TO SPRAY RUST PROOFING		\$150.00	80
	TO RESET AIR BAG PROGRAMME	17	\$380.00	X
	TO REFILL AIR CON GAS		\$150.00	100
	TO MOUNT VEHICLE ON CAR O-LINER	17	\$380.00	X
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED		\$3,800.00	1400
	REPLACING PARTS		\$3,500.00	1700
	TO PUTTY & SPRAY PAINTING		\$74,119.10	
	TOTAL		\$74,119.10	

2016-18
1833