

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50
SINGAPORE 417883

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE NO: SLG 61557

QTY	PARTICULAR
1 PCS	BOOTLID 2665.15
1 PCS	BOOTLID REAR LOGO
1 PCS	BOOTLID 'A6' EMBLEM 88.20
1 PCS	BOOTLID '2.0T' EMBLEM 80.50
1 PCS	BOOTLID INNER LOCK
1 PCS	BOOTLID LOCK STRIKER
1 PCS	BOOTLID WEATHERSTRIP 215.45
2 PCS	BOOTLID REFLECTORS @\$1005.00
1 PCS	BOOTLID INNER TRIM
1 SET	BOOTLID INNER TRIM CLIPS
2 PCS	BOOTLID LICENCE PLATE LAMPS @\$95.00
1 PCS	REAR BUMPER 2005.35
1 PCS	REAR BUMPER LOWER SKIRTING 345.00
1 PCS	REAR BUMPER SPONGE
1 PCS	REAR BUMPER REINFORCEMENT 715.00
2 PCS	REAR BUMPER BRACKETS @\$145.00
2 PCS	REAR BUMPER SIDE HOLDERS @\$135.00
4 PCS	REAR BUMPER PDC SENSORS @\$313.75 208 x 2 = 416
1 PCS	REAR BUMPER PDC SENSOR WIRE
1 PCS	REAR BUMPER TOW COVER
1 PCS	REAR BUMPER TOP RETAINER
1 PCS	REAR END PANEL
1 PCS	REAR END PANEL EXTENSION LOWER 266.15
1 PCS	REAR END PANEL TOP GARNISH
2 PCS	TAILLAMPS @\$1205.00 750 x 2 = 1500
1 PCS	REAR END PANEL INNER MEMBER 415.00
1 PCS	REAR EXHAUST N/S
1 PCS	REAR EXHAUST O/S
1 PCS	REAR EXHAUST HEATSHIELD
1 PCS	REAR FLOOR PANEL
1 PCS	REAR FLOOR PANEL TOP BOARD
2 PCS	REAR FENDERS @\$3650.00
2 PCS	REAR FENDER INNER TRIMS @\$366.20
3 PCS	FRONT SEATBELTS @\$920.00
1 SET	HEADREST REPAIR KIT
1 PCS	BATTERY CABLE
1 PCS	BONNET
1 PCS	BONNET LOCK
1 PCS	BONNET SEAL

not Approved
26/12/19
10 day. 2/5 \$14,800/

Bodywork	\$3,966.20	/
nu	\$100.85	/
nu	\$102.30	/
nu	\$88.50	/
1w1	\$315.50	/
11	\$105.20	X
1w1	\$266.20	/
NT	\$2,010.00	X
11	\$488.25	X
11	\$50.00	X
11	\$190.00	X
11	\$2,665.00	/
11	\$695.00	/
NT	\$210.30	X
11	\$935.00	/
NS	\$290.00	X
015del	\$270.00	1pc
Shut	\$1,255.00	2pc
11	\$285.60	X
11	\$45.00	X
NS	\$165.00	X
Bodywork	\$580.60	/
Bodywork	\$315.00	/
1w1	\$295.00	/
9m	\$2,410.00	/
3-600	\$495.00	/
R	\$1,685.00	X
R	\$1,595.00	X
11	\$185.00	X
R	\$1,150.00	X
11	\$825.30	X
R	\$7,300.00	X
11	\$732.40	X
11	\$1,840.00	X
11	\$245.00	X
11	\$252.00	X
R	\$3,145.00	X
SUL	\$185.00	X
11	\$88.00	X

(52)

1 PCS	BONNET INSULATOR	17	\$260.55	X
1 SET	BONNET INSULATOR CLIPS	17	\$50.00	X
2 PCS	BONNET HINGES @\$115.00	17	\$230.00	X
1 PCS	FRONT BUMPER	D.S	\$2,655.00	✓
2 PCS	FRONT SIDE REATINERS @\$105.00	17	\$210.00	X
1 PCS	FRONT BUMPER SPONGE	17	\$205.00	X
1 PCS	FRONT BUMPER REINFORCEMENT	Bul	\$955.00	✓
2 PCS	FRONT BUMPER REINFORCEMENT STAYS @\$145.00	17	\$290.00	X
1 PCS	FRONT GRILLE	CM	\$1,255.00	✓
1 PCS	FRONT GRILLE LOGO	17	\$100.85	✓
2 PCS	FRONT PDC SENSORS @\$315.00	8/10/11	\$630.00	✓
2 PCS	HEADLAMP ASSYS @\$6800.0	CM	\$13,600.00	✓
1 PCS	FRONT SUPPORT PANEL	SUL	\$1,055.00	X
1 PCS	AIR CON CONDENSER	Bul/12/11	\$1,265.00	✓
1 PCS	RADIATOR	SUL	\$1,350.00	X
1 PCS	RADIATOR FAN ASSY	17	\$1,385.00	X
1 PCS	HORN UNIT	17	\$110.00	X
1 PCS	TURBO COOLER	17	\$820.00	X
			\$64,249.10	
	S.NETT			
1 PCS	REAR LICENCE PLATE W/HOLDER	17	\$50.00	X
1 PCS	REAR END PANEL SEALANT	17	\$50.00	✓
1 PCS	REAR WINDSCREEN SEALANT	17	\$50.00	X
1 SET	REAR EXHAUST CHROME	17	\$200.00	IPC 80
1 PCS	REAR FLOOR PANEL INSULATOR	17	\$280.00	X
1 PCS	FRONT LICENCE PLATE	Bul	\$50.00	15
1 BOT	RADIATOR COOLANT	17	\$50.00	X
	LABOUR CHRAGES:			
	TO CHECK WIRING		\$80.00	30
	TO DISMANTLE & REPLACING PDC SENSOR		\$100.00	50
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTREY		\$150.00	80
	TO DISMANTLE & REFIX REAR EXHAUST		\$150.00	80
	TO DISMANTLE & REFIX REAR WINDSCREEN	17	\$150.00	X
	TO TRANSFER BOOTLID MECHANISM		\$150.00	60
	TO SPRAY RUST PROOFING		\$150.00	80
	TO RESET AIR BAG PROGRAMME	17	\$380.00	X
	TO REFILL AIR CON GAS		\$150.00	100
	TO MOUNT VEHICLE ON CAR O-LINER	17	\$380.00	X
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED		\$3,800.00	1400
	REPLACING PARTS			
	TO PUTTY & SPRAY PAINTING		\$3,500.00	1700
	TOTAL		\$74,119.10	

2021/6/8
18332