COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHC 8556A

MAKE :

23/12/2019 13:32

	PARTS DESCRIPTION	QTY	UNIT PRICE	F	MOUNT	
	REAR BUMPERCUL			\$	458.60	
	REAR BUMPER CLIPS NEC			\$	22.00	H.
	TAIL LAMP ASSY (LOWER) (LH) X MV			\$	548.40	
	REAR FENDER, RH BUC			\$	836.70	
	REAR FENDER SHEILD (RH)	n		\$	134.20	
	REAR TYRE RIM ,RH SCY			\$	1,555.00	
	rear Right ROOK & BUC Right Rocker pinel X(R) SUB TOTAL LESS 25%					
	SUB TOTAL			\$	3,554.90	
	RIGHT ROCKET POPULITY LESS 25%			\$	888.73	
	DISCOUNTED TOTAL			\$	2,666.18	
	REAR DOOR COMFORTS & APPS STICKER YOU			\$	80.00	NE
	the Repairer of the following:			Ψ	00.00	111
	10 resurvey before/after spray painting					
	U ID DISDIAY damaged next at a					
	Parts prices are subject to confirmation Third party survey is one a Mality.					
	Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed					
	Supplementary item(s) must be resurveyed and is subject to final approval from the surveyed and is subject to final approval.					
	is subject to final approval from Insurance Company		(10.			
	Acknowledged by Repairer	Dan	(The 10 No	1		
	Signature:		19 12	nke	3	
	Date:	2 A	III, OTher	05		
	LABOUR CHARGE	0	(LEV) 210Mi 119 OLEVA mar & We)			
	Panel Beating	mas	28(H)	\$	850.00	\$5
	Spray Painting Charge	- 50	2	\$	700.00	1
	Wiring Charge	880	1e.S		50.00	4
	Tuff Kote	1	paray	\$	50.00	
	Remove/Refix Cushion & Upholstery Rear	AVG	pair says		150.00	80
	Remove/Refix Rear Windscreen Glass	/	photo.	\$		
		1018) grand	\$	120.00	
	Remove/Refix Reverse Sensor	(1/a	1 stol.	\$	80.00	
	Rear Wheel Alignment		/ ph	\$	80.00	X
	Transfer of door		()			\$
	TOTAL LABOUR			\$	2,080.00	
MY MA						
14.1	ESTIMATE TOTAL			\$	4,826.18	
	attech Warrait shows					
	tial estimate based on a visual inspection of the above vehic	le The fi	nal ranair quantum	will		