



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

INV No. AC2104538

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV Date 29/06/2021
Reference CC6/EQI19022611/Aga3q2
Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SKB 1032K
Insured Veh. SGU 2846U
Claim No. DM20HO00026/SG
Policy No. DMPPHQ19-007671
Accident Date 17/12/2019
Inspection Date 23/12/2019

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Ref: CC6/EQI19022611/Aga3q2 Date: 29/06/2021 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGU 2846U	Veh. Inspected	SKB 1032K	
Policy No.	DMPPHQ19-007671	Coverage (\$)	0.00	
Claim No.	DM20HO00026/SG	Excess (\$)	0.00	
Assign From		Assign Date	23/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 120I	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WBAUD32020P224248	Colour	BLACK	
Odometer	110874 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R17	GREEN MAX	6 mm	
L/H Front Tyre	215/50 R17	GREEN MAX	6 mm	
R/H Rear Tyre	215/50 R17	GREEN MAX	6 mm	
L/H Rear Tyre	215/50 R17	GREEN MAX	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/12/2019	Inspection Date	23/12/2019	
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 1032K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,265.00	1,265.00
2	REAR BUMPER SIDE HOLDER @\$66.00	NECESSARY	132.00	132.00
1	REAR BUMPER LOWER LIP	DEFORMED	358.00	358.00
1	REAR BUMPER LOWER RH SIDE COVER	DEFORMED	177.00	177.00
1	REAR BUMPER LOWER CENTRE COVER	DEFORMED	189.00	189.00
1	SET REAR BUMPER CLIPS	NECESSARY	66.00	30.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	528.00	-
2	REAR BUMPER BRACKET @\$66.00	NOT NECESSARY	132.00	-
1	REAR END PANEL	NOT NECESSARY	616.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	110.00	-
2	REAR BUMPER PLATE LAMP @\$40.70	NOT NECESSARY	81.40	-
1	REAR TAILGATE	NOT NECESSARY	1,320.00	-
1	REAR TAILGATE UPPER LOCK	NOT NECESSARY	170.50	-
	LESS 5% DISCOUNT		-257.25	-107.55
			4,887.65	2,043.45
<u>SPECIAL NETT ITEMS</u>				
4	REAR REVERSE SENSOR @\$434.50 (SN)	DAMAGED (2 PCS ONLY)	1,738.00	560.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	FRONT NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
			1,838.00	560.00
<u>LABOUR</u>				
	REMOVE & REINSTALL REVERSE SENSOR .		150.00	60.00
	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT .		1,200.00	300.00
	RESPRAY PAINTING.		1,000.00	300.00
1	TO PERFORM DIAGNOSTIC TEST.		150.00	80.00
	WIRING .		100.00	30.00
			2,600.00	770.00
GRAND TOTAL			9,325.65	3,373.45

Report Ref No. CC6/EQI19022611/Aga3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,700.00
---	--	--	----------

Report Ref No. CC6/EQ119022611/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKB 1032K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKB 1032K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

