



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2005559
INV Date 13/08/2020
Reference CC4/LPC19022612/R1ea3s2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SLR 4564B
Insured Veh. GBF 1405D
Claim No. 19/19/20/VC05/022812
Policy No. Z19VC05002680
Accident Date 23/12/2019
Inspection Date 24/12/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19022612/R1ea3s2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 13-08-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 1405D	Veh. Inspected	SLR 4564B
Policy No.	Z19VC05002680	Coverage (\$)	0.00
Claim No.	19/19/20/VC05/022812	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	23/12/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA3 SEDAN 1.5 AT	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0154312	Colour	WHITE
Odometer	185767	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/12/2019	Inspection Date	24/12/2019
Survey held at	74 KIAN TECK ROAD		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 4564B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,175.00	-
2	REAR BUMPER TOW COVER @ \$40.00	SERVICEABLE	80.00	-
10	REAR BUMPER CLIPS @ \$4.00	NECESSARY	40.00	40.00
	REAR BUMPER RIVET @ \$5.00	NOT NECESSARY	20.00	-
1	REAR REINFORCEMENT	SERVICEABLE	545.00	-
	LESS 20% DISCOUNT		-372.00	-8.00
			1,488.00	32.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
			280.00	-
	<u>LABOUR</u>			
	TO REMOVE & REPLACED REAR REVERSE SENSOR.		100.00	60.00
	TO APPLY RUST PROOFING & TUFF COATING TREATMENT.	NOT NECESSARY	100.00	-
	TO KNOCKING & PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		600.00	150.00
	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.		600.00	200.00
			1,400.00	410.00
	GRAND TOTAL		3,168.00	442.00
	RECOMMENDED COST OF REPAIRS			442.00

Report Ref No. CC4/LPC19022612/R1ea3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 4564B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 4564B

RE-INSPECTION

