



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
74 KIAN TECK ROAD
SINGAPORE 628800

Officer in Charge : CHIN XIAN CHERN
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax No. :

Quotation No. : QO19/12-1236	Quotation Date : 24/12/2019	Terms : 30 DAYS
Vehicle No. : SLR4564B	Chassis No. : JM6BN22A8H0154312	Third Party Insurer : LONPAC
Model : MAZDA 3		Date of Accident : 23/12/2019
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER <i>Repair</i>	1	1,175.0000	1,175.00
2	REAR BUMPER TOW COVER <i>X</i>	2	40.0000	80.00
3	REAR BUMPER CLIPS <i>new</i>	10	4.0000	40.00
4	REAR BUMPER RIVET <i>new</i>	4	5.0000	20.00
5	REAR REINFORCEMENT <i>X</i>	1	545.0000	545.00
6	LESS 20%	1	-372.0000	-372.00
7	REAR REVERSE SENSOR <i>X</i>	1	280.0000	280.00
8	TO REMOVE&REPLACED REAR REVERSE SENSOR	1	100.0000	60 100.00
9	TO APPLY RUSTPROOFING&TUFFCOATING TREATMENT <i>X</i>	1	100.0000	100.00
10	TO KNOCKING&PANEL BEATING	1	600.0000	150 600.00
11	TO PUTTY&SPRAY PAINT ON THE AFFECTED AREAS	1	600.0000	200 600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parue
Hp 90010068
2 days
P/P
24/12/19
Resurvey before paint

Sub Total	3,168.00
GST(7.00%)	221.76
Total (SGD)	3,389.76

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800