

ASS. REC. BY: Steve

REF: ATG

CC3/MA19022647/Exd302

ok

ASSIGNMENT

From: _____

Date: 26/12/19

Veh No: SDR 2092

Yr Regn: 25/8/18

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SDR 209-2

Make: Audi Q5

C.C. 1984

at Workshop m/s Premium

Colour: Black

A/C: Insured / Std / NI / NA

of 281 Alexandra Road

Sp. Reading: 94857

T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. 1800100375-01

C/No: W44222FYXJ 2139439

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____

Excess: 500

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: 10 am

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R19

R: _____

(Policy Condition)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

Remark: The veh had commenced its repair at the time of inspection.



TOYO / YOKO or Continental

Bal. or Market Value: _____

Front

Rear

IDAC Accident Rpt: _____

Consistent? : Yes or No

R/Bal. 5 mm

R/Bal. 5 mm

GIA / PR Seen: _____

Consistent? : Yes or No

L/Bal. 5 mm

L/Bal. 5 mm

Est. Repairs: 5 days

Res.: Yes or No

D.O.A. 23/12/19

D.O.I. 26/12/19

Lum Sum: _____

%

3 Val.: Yes or No

*Survey held at Premium

CA / ☒ REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MR-179K</u>
<u>26/12/19</u>	<u>Revert via merimen</u>
<u>27/12/19</u>	<u>Recd approved \$9752 from Kok Chong by merimen</u>
<u>27/12/19</u>	<u>Informed Troy C/A ex \$500 by email</u>
<u>18/3/20</u>	<u>Final fig \$14,880.72 (Red 20,175.28, 5710) confirmed by email</u>

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair: 5

1)

☐

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$)

Survey Fee: 200

Transportation: _____

☐

: Interview (\$)

\$ + RS. SI

☐

: Tech. Invs (\$)

Photos

☐

: Weekend (\$)

Others

Report Format: _____

Lump Sum / L.B.I. (\$)

TOTAL

211

REF: STK

REF: ALG 003/ALG19022647/Exd3

Muimun

ASSIGNMENT

Date: 06/12/19
 Estimated Cost:
 To inspect Vehicle No: SDR 2092 SDR 2092
 at Workshop no: Premium
 of: 281 Alexandra Road
 Insured:
 Policy No:
 Claims No:
 Sum Insured: 15A
 (Client's Record)
 Make of Veh: 10 am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. Repairs: days Res: Yes or No
 Lest Sum: % J Val: Yes or No

CA / (REV) / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SDR 2902 Yr Regn: 25/8/18
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Audi Q5 C.C. 1984
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 94857 T/Radio: Insured / Std / NI / NA
 Eng. No:
 C.No: W4U22ZFXXJ 2137439
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 235/55R19
 R:
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental
 Front: Rear:
 R/Bal: 5 mm R/Bal: 5 mm
 L/Bal: 5 mm L/Bal: 5 mm
 D.O.A: 23/12/19 D.O.I: 26/12/19
 Survey held at: Premium
 Des. of Damages: Fit / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MP-179K

SDR 2092 - NAI/INCORUIC676/GK

DATA: 26/12/2018

Date/Time File Path to?

☐ Preli. Report

☐ Final Report

Date/Time File Return to?

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp. (5)
☐ Interview (5)
☐ Tech. Insp. (5)
☐ Witnessed (5)

Survey Fee:

Transportation:

3 + FC: 14

Flake:

Open:

TOTAL

Report Format:

Survey Code / 123456

View Received Message

This mail is associated with :

***SDR209Z (3788004045SG)**

OD

Dec 23 2019 12:00PM

[PANG LU THING SHANE (FENG RUXIN SHANE)]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 18/03/2020 14:06 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$14880.72) - SDR209Z - Claim Handler: Nadaraja, Deeban

Approved:14880.72:Re-inspection during dismantle for checked items and supplementary require with CLEAR photos upload in Merimen, and re-seek mandate. Before paint photos for Front Bumper required.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nadaraja, Deeban

Date: 16 Mar 2020

Preliminary Advice

Vehicle No	: SDR209Z	Accident Date	: 23/12/2019
Make	: AUDI Q5	Policy No.	:
Assignment Date	: 26/12/2019	Excess	: S\$500.00
Date of Inspection	: 26/12/2019	Est. Duration of Repair	: 5.00
Inspection At	: 281 ALEXANDRA ROAD		
	REPAIRER : PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	35,056.00
Revised Amount	:S\$	14,880.72
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,880.72

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	179,000.00
COE / PARF Rebate	:S\$	70,995.00
Salvage Value	:S\$	
Margin for Repair	:S\$	108,005.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 27 December 2019 5:33 PM
To: Claims; SUR
Cc: (boojohnny@gmail.com); (nora.khai@premiumauto.com.sg)
Subject: RE: OD CLAIMS FOR SDR 209 Z-DOA: 23/12/2019

Dear TRoy,

As instructed by our client, please proceed to repair the **insured vehicle SDR 209Z, (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

NOTE: Before paint photos for Front Bumper required.

AIG OIC Nadaraja, Deeban [Deebanalnadaraja.Nadaraja@aig.com]

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Friday, 27 December 2019 8:36 AM
To: 'Claims' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OD CLAIMS FOR SDR 209 Z-DOA: 23/12/2019

Dear TRoy,

Pending approval from AIG.

Once approved will send you email.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 26 December 2019 12:01 PM
To: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIMS FOR SDR 209 z

Dear all,

Survey was just carried up by surveyor this morning, herein attached the estimate repair with marking for your next action.

Kindly assist and advise the mentioned claims for approval and who is the case handler for this.

Thanks

Best Regards,
T Roy Goh
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Monday, 23 December 2019 6:51 PM
To: 'SUR'; 'assignments'
Cc: 'Claims'
Subject: OD CLAIMS FOR SDR 209 z

Dear All,

Please assist to register own policy claims for the above mentioned vehicle.

Attached is the GIA report, DL, Insurance certificate for your reference.

Kindly arrange the survey on 26 of Dec@10am, owner waiting.

Address : 281 Alexandra Road Singapore 159938

Thank you.

Best Regards,
George Wong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

281 Alexandra Road Singapore 159938

p. +65 6366 2323, option 1

e. Claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom 281 Alexandra Road Singapore 159938 p. +65 68362223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

View Received Message

This mail is associated with :

***SDR209Z (3788004045SG)**

OD

Dec 23 2019 12:55PM

[PANG LU THING SHANE (FENG RUXIN SHANE)]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 27/12/2019 17:05 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$9752.00) - SDR209Z - Claim Handler: Nadaraja, Deeban

Approved:9752.00:Re-inspection during dismantle for checked items and supplementary require with CLEAR photos upload in Merimen, and re-seek mandate. Before paint photos for Front Bumper required.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 26 Dec 2019

Preliminary Advice

Vehicle No	: SDR209Z	Accident Date	: 23/12/2019
Make	: AUDI Q5	Policy No.	: 1800100375-01
Assignment Date	: 26/12/2019	Excess	: S\$0.00
Date of Inspection	: 26/12/2019	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	35,056.00
Revised Amount	:S\$	9,752.00
Check Items (Estimated)	:S\$	4,496.00
Total	:S\$	14,248.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	179,000.00
COE / PARF Rebate	:S\$	70,995.00
Salvage Value	:S\$	
Margin for Repair	:S\$	108,005.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Alvin 26/12/19

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 24068

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1512/2019/NS
Date : 24-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Pang Lu Thing Shane (Fern Ruxin Shane)
Address : 25 Cheng Soon Garden
Singapore 599802
Telephone : HP +65 97603480
Type of Claim : Own Damage Claims
Policy No. : 1800100375-01
Vehicle No : **SDR 209 Z**
Model Code : Audi Q5 SPORT 2.0 TFSI qu
Model / Year : 25-08-18
Engine No : DAX 033166
Chassis No : WAUZZZFVXJ2139439
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Dec-19
Place of Accident : Corner OF Alexandra Road & Hyderabad Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDR 209 Z

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 /	✓
2	To dismantle and renew front bumper and both headlights. Re-organise crash management components. Reinstall all parts removed. 500	\$ 2,400.00 500 T50	
3	To respray front bumper, front bumper lower spoiler, bonnet and both front wheel arch trims. 550XJ	\$ 3,500.00 1650 ✓	
4	To carry out diagnostic checks.	S/N \$ 192.00 /	✓
TOTAL LABOUR CHARGES		: \$ 6,572.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDR 209 Z

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER / <i>MM</i>	\$	2,364.00	1891.20
2	FRONT BUMPER FIXING PARTS <i>X MM</i>	\$	244.00	
3	FRONT BUMPER SECURING STRIP - LH / RH <i>? X MM</i>	2 \$	68.00	
4	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>? X MM</i>	2 \$	202.00	
5	FRONT BUMPER GRILLE - CENTRE <i>X MM</i>	\$	129.00	
6	FRONT BUMPER FRONT SPOILER <i>X MM</i>	\$	685.00	
7	FRONT BUMPER UNDERRUN BAR <i>X MM</i>	\$	431.00	
8	FRONT BUMPER CLOSING ELEMENT <i>X MM</i>	\$	156.00	
9	RADIATOR GRILLE / <i>GR</i>	\$	3,258.00	2666.40
10	QUATTRO INSCRIPTION <i>X MM</i>	\$	87.00	
11	RADIATOR GRILLE STRIKER PLATE <i>? GR</i>	\$	222.00	177.20
12	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>? X MM</i>	2 \$	1,038.00	
13	FRONT BUMPER END CAP - LH / RH <i>X MM</i>	2 \$	166.00	
14	LOCKING CLIP / <i>ML</i>	4 \$	15.00	11.52
15	FRONT BUMPER CARRIER <i>? X MM</i>	\$	831.00	
16	FRONT BUMPER FOAM FILLER PIECE <i>? GR</i>	\$	259.00	207.20
17	FOAM FILLER PIECE COVER <i>? X MM</i>	\$	116.00	
18	FRONT BUMPER GUIDE SECTION - LH / RH <i>? X MM</i>	2 \$	68.00	
19	CAUTION SIGN STICKER <i>? X MM</i>	NEC \$	13.00	
20	AIRCON STICKER <i>? X MM</i>	NEC \$	18.00	
SUB TOTAL SPARE PARTS		:	\$	10,370.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDR 209 Z

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
21	HORN - LH LOW TONE X NAI	\$	178.00	
22	HORN - RH HIGH TONE X NAI	\$	178.00	
23	FRONT PARKING AID SENSOR - INNER (RH) ? X NAI	2 \$	462.00	
24	FRONT PARKING AID SENSOR - OUTER (RH) ? X NAI	2 \$	462.00	
25	FRONT PARKING AID SEAL RING X NAI	4 \$	12.00	
26	HEADLIGHT MOUNTING - LH / RH ? ✓ GR	2 \$	214.00	171.20
27	LED HEADLIGHT - (LH) RH ? ✓ CUT	1 ✓ \$	14,454.00	5781.60
28	LIFT CYLINDER - LH / RH X NAI	2 \$	256.00	
29	HEADLIGHT HOSE X NAI	\$	113.00	
30	FRONT WHEEL COVER - LH / RH / NAI	2 \$	1,154.00	922.40
31	RADIATOR AIR GUIDE - UPPER ? X NAI	\$	43.00	
32	RADIATOR AIR GUIDE - CENTRE ? X NAI	\$	37.00	
33	RADIATOR AIR GUIDE - LOWER ? X NAI	\$	43.00	
34	RADIATOR AIR GUIDE - LH / RH ? X NAI	2 \$	100.00	
35	EXTERNAL TEMPERATURE SENSOR X NAI	\$	54.00	
36	EXTERNAL TEMPERATURE SENSOR BRACKET X NAI	\$	14.00	
37	FRONT NO PLATE / DT	S/N \$	40.00	40
38	SUNDRIES ? X NAI	\$	300.00	

TOTAL SPARE PARTS

: \$ 28,484.00

TOTAL LABOUR CHARGES

: \$ 6,572.00

GRAND TOTAL

: \$ 35,056.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

5
21/12/19

Telefax

Name

:

Steve (LKK)

Surveyed Date

:

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

26/12/19, 10.15 am

OD - Not Authorised (Rand)

EXCESS - ?

5 days

P/P

Ry BCL Sry

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 24068

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1512/2019/NS
Date : 24-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Pang Lu Thing Shane (Fern Ruxin Shane)
Address : 25 Cheng Soon Garden
Singapore 599802
Telephone : HP +65 97603480
Type of Claim : Own Damage Claims
Policy No. : 1800100375-01
Vehicle No : **SDR 209 Z**
Model Code : Audi Q5 SPORT 2.0 TFSI qu
Model / Year : 25-08-18
Engine No : DAX 033166
Chassis No : WAUZZZFVXJ2139439
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Dec-19
Place of Accident : Corner OF Alexandra Road & Hyderabad Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDR 209 Z

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 /	
2	To dismantle and renew front bumper and both headlights. Re-organise crash management components. Reinstall all parts removed. <i>500</i>	\$ 2,400.00 <i>500</i>	<i>750</i>
3	To respray front bumper, front bumper lower spoiler, bonnet and both front wheel arch trims. <i>500XJ</i>	\$ 3,500.00 <i>1650</i>	
4	To carry out diagnostic checks.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: <u>\$ 6,572.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDR 209 Z

		Damaged Parts & Prices	
S/N	Parts Description	S/Nett	Remarks
1	FRONT BUMPER / <i>DR</i>	\$	2,364.00
2	FRONT BUMPER FIXING PARTS X	\$	244.00
3	FRONT BUMPER SECURING STRIP - LH / RH ?	2 \$	68.00
4	FRONT BUMPER CLOSING ELEMENT - LH / RH ?	2 \$	202.00
5	FRONT BUMPER GRILLE - CENTRE X	\$	129.00
6	FRONT BUMPER FRONT SPOILER X	\$	685.00
7	FRONT BUMPER UNDERRUN BAR X	\$	431.00
8	FRONT BUMPER CLOSING ELEMENT X	\$	156.00
9	RADIATOR GRILLE / <i>DR</i>	\$	3,258.00
10	QUATTRO INSCRIPTION / <i>MC</i>	\$	87.00
11	RADIATOR GRILLE STRIKER PLATE ? / <i>DR</i>	\$	222.00
12	FRONT BUMPER AIR GUIDE GRILLE - LH / RH ?	2 \$	1,038.00
13	FRONT BUMPER END CAP - LH / RH X	2 \$	166.00
14	LOCKING CLIP / <i>MC</i>	4 \$	15.00
15	FRONT BUMPER CARRIER ?	\$	831.00
16	FRONT BUMPER FOAM FILLER PIECE ? / <i>DR</i>	\$	259.00
17	FOAM FILLER PIECE COVER ?	\$	116.00
18	FRONT BUMPER GUIDE SECTION - LH / RH ?	2 \$	68.00
19	CAUTION SIGN STICKER ?	NEC \$	13.00
20	AIRCON STICKER ?	NEC \$	18.00
SUB TOTAL SPARE PARTS		: \$	10,370.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDR 209 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	HORN - LH LOW TONE X	\$	178.00
22	HORN - RH HIGH TONE X	\$	178.00
23	FRONT PARKING AID SENSOR - INNER (LH) ?	2 \$	462.00
24	FRONT PARKING AID SENSOR - OUTER (RH) ?	2 \$	462.00
25	FRONT PARKING AID SEAL RING / NK	4 \$	12.00
26	HEADLIGHT MOUNTING - LH / RH ? / DR	2 \$	214.00
27	LED HEADLIGHT (LH) RH X / CUT	2 \$	14,454.00
28	LIFT CYLINDER - LH / RH X	2 \$	256.00
29	HEADLIGHT HOSE X	\$	113.00
30	FRONT WHEEL COVER - LH / RH / NK	2 \$	1,154.00
31	RADIATOR AIR GUIDE - UPPER ?	\$	43.00
32	RADIATOR AIR GUIDE - CENTRE ?	\$	37.00
33	RADIATOR AIR GUIDE - LOWER ?	\$	43.00
34	RADIATOR AIR GUIDE - LH / RH ?	2 \$	100.00
35	EXTERNAL TEMPERATURE SENSOR X	\$	54.00
36	EXTERNAL TEMPERATURE SENSOR BRACKET X	\$	14.00
37	GT FRONT NO PLATE / BT	S/N \$	40.00
38	SUNDRIES ?	\$	300.00
TOTAL SPARE PARTS		:	\$ 28,484.00
TOTAL LABOUR CHARGES		:	\$ 6,572.00
GRAND TOTAL		:	\$ 35,056.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Steve (LKK)

:

:

:

:

:

26/12/14, 10.15 am

OD - Not Authorised (Lend)

Excess - ?

5 rky

P/P

By BCL sy

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 24068

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1512/2019/NS
Date : 24-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Steve

5 days - ok - jb - 10 Mar 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Pang Lu Thing Shane (Fern Ruxin Shane)
Address : 25 Cheng Soon Garden
Singapore 599802
Telephone : HP +65 97603480
Type of Claim : Own Damage Claims
Policy No. : 1800100375-01
Vehicle No : **SDR 209 Z**
Model Code : Audi Q5 SPORT 2.0 TFSI qu
Model / Year : 25/8/2018
Engine No : DAX 033166
Chassis No : WAUZZZFVXJ2139439
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Dec-19
Place of Accident : Corner OF Alexandra Road & Hyderabad Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDR 209 Z

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$ 480.00
2	To dismantle and renew front bumper and both headlights. Re-organise crash management components. Reinstall all parts removed. (LHS Headlamp replaced)	\$	2,400.00	\$ 750.00
3	To respray front bumper, front bumper lower spoiler, bonnet and both front wheel arch trims.	\$	3,500.00	\$ 1,650.00
4	To carry out diagnostic checks.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 6,572.00	\$ 3,072.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDR 209 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,364.00	\$ 1,891.20
2	FRONT BUMPER FIXING PARTS	\$ 244.00	
3	FRONT BUMPER SECURING STRIP - LH / RH	2 \$ 68.00	
4	FRONT BUMPER CLOSING ELEMENT - LH / RH	2 \$ 202.00	
5	FRONT BUMPER GRILLE - CENTRE	\$ 129.00	
6	FRONT BUMPER FRONT SPOILER	\$ 685.00	
7	FRONT BUMPER UNDERRUN BAR	\$ 431.00	
8	FRONT BUMPER CLOSING ELEMENT	\$ 156.00	
9	RADIATOR GRILLE	\$ 3,258.00	\$ 2,606.40
10	QUATTRO INSCRIPTION	\$ 87.00	
11	RADIATOR GRILLE STRIKER PLATE	\$ 222.00	\$ 177.20
12	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 1,038.00	
13	FRONT BUMPER END CAP - LH / RH	2 \$ 166.00	
14	LOCKING CLIP	4 \$ 15.00	\$ 11.52
15	FRONT BUMPER CARRIER	\$ 831.00	
16	FRONT BUMPER FOAM FILLER PIECE	\$ 259.00	\$ 207.20
17	FOAM FILLER PIECE COVER	\$ 116.00	
18	FRONT BUMPER GUIDE SECTION - LH / RH	2 \$ 68.00	
19	CAUTION SIGN STICKER	NEC \$ 13.00	
20	AIRCON STICKER	NEC \$ 18.00	
SUB TOTAL SPARE PARTS		: \$ 10,370.00	\$ 4,893.52

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDR 209 Z

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remarks
				\$ 4,893.52
21	HORN - LH LOW TONE		\$ 178.00	
22	HORN - RH HIGH TONE		\$ 178.00	
23	FRONT PARKING AID SENSOR - INNER	2	\$ 462.00	
24	FRONT PARKING AID SENSOR - OUTER	2	\$ 462.00	
25	FRONT PARKING AID SEAL RING	4	\$ 12.00	
26	HEADLIGHT MOUNTING - LH / RH	2	\$ 214.00	\$ 171.20
27	LED HEADLIGHT - LH / RH	2	\$ 14,454.00	\$ 5,781.60
28	LIFT CYLINDER - LH / RH	2	\$ 256.00	
29	HEADLIGHT HOSE		\$ 113.00	
30	FRONT WHEEL COVER - LH / RH	2	\$ 1,154.00	\$ 922.40
31	RADIATOR AIR GUIDE - UPPER		\$ 43.00	
32	RADIATOR AIR GUIDE - CENTRE		\$ 37.00	
33	RADIATOR AIR GUIDE - LOWER		\$ 43.00	
34	RADIATOR AIR GUIDE - LH / RH	2	\$ 100.00	
35	EXTERNAL TEMPERATURE SENSOR		\$ 54.00	
36	EXTERNAL TEMPERATURE SENSOR BRACKET		\$ 14.00	
37	FRONT NO PLATE	S/N	\$ 40.00	\$ 40.00
38	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS			\$ 28,484.00	\$ 11,808.72
TOTAL LABOUR CHARGES			\$ 6,572.00	\$ 3,072.00
GRAND TOTAL			\$ 35,056.00	\$ 14,880.72

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 18 March 2020 2:22 PM
To: Boo seng yak; Steve Chen (LKK Auto); SUR; Carrine Leong; Chang Chee Sing; jiayee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SDR209Z - OD AIG - SURVEYED 26 DEC 19

Dear Mr Boo,

Confirm repair cost of \$14,880.72 before excess \$500 and GST @ 5 days.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Wednesday, 11 March 2020 3:29 PM
To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg
Subject: FINAL REVISION - SDR209Z - OD AIG - SURVEYED 26 DEC 19

Hi Steve and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$14,880.72 @ 5 days.

Your early closure is well appreciated.

Best regards - jb