

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 27 Dec 2019

Preliminary Advice

Vehicle No	: YN6485A	Accident Date	: 14/12/2019
Make	: ISUZU FVR34SUQDC	Policy No.	: DMCVSN1662721903
Assignment Date	: 26/12/2019	Excess	: S\$1,000.00
Date of Inspection	: 26/12/2019	Est. Duration of Repair	: -
Inspection At	: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	120.00 (Towing)
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	TOTAL LOSS
Total	:S\$	TOTAL LOSS
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	51,000.00
COE / PARF Rebate	:S\$	16,243.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,757.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :