

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

26/12/2019

Accident date: 24/12/2019

Estimated repair cost for vehicle no: SLS898J HONDA CIVIC TURBO 1.5 A '17
MRHFC1660HT000353

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid			
2	1	Rear Boot Lid Civic Logo		\$650.40	531.26
3	1	Rear Boot Lid I-Vtec Lgo		\$35.30	
4	1	Rear Boot Lid Honda Logo		\$36.20	
5	1	Rear Boot Lid Inner Lock		\$36.20	
6	1	Rear Boot Lid Center Garnish		\$151.80	
7	1	Rear Boot Lid Inner Rubber		\$258.70	
8	2	Rear Boot Lid Side Reflector		\$115.00	
9	1	Rear Boot Lid Inner Trim Board	\$240.90	\$481.80	
10	10	Rear Boot Lid Inner Trim Board Clip		\$178.50	
11	2	Rear Tail Lamp	\$6.50	\$65.00	
12	1	Rear Bumper	\$380.80	\$761.60	614.80
13	8	Rear Bumper Clip		\$817.20	617.20
14	2	Rear Bumper Side Reflector Cover	\$6.50	\$52.00	30
15	1	Rear Bumper Lower Spoiler	\$60.40	\$120.80	100
16	2	Rear Bumper Reverse Sensor (Special Nett)	\$168.50	\$268.20	145.20
17	1	Rear Bumper Reinforcement		\$674.00	337.00
18	2	Rear Bumper Side Body Kit (sp)		\$196.40	
19	1	Rear End Panel	\$300.00	\$600.00	300.00
20	1	Rear End Panel Top Garnish		\$500.20	350
21	1	Rear Spare Tyre Panel Top Cover		\$125.80	98.40
22	1	Rear Fender Inner Trim Board	\$296.20	\$197.10	
				\$592.40	158

3305.1

- 20%

P = 2,644.08

N = 637

Subtotal :- \$6,914.60

Labour charges

To remove & refit cushion	\$150.00 60
To remove & refit reverse sensor	\$150.00 60
To remove & refit rear body kit	\$200.00 80
To check wiring	\$60.00 30
Tuff kote	\$150.00 40
Panel beating	\$900.00 800
Spray painting	\$1,000.00 800

Subtotal :- \$2,610.00 1876
Total:- \$9,524.60 1870

Repair day - 6 days

Lump Sum Repair

After spray photo

Sun Pm (Lkk)

26/02/2019

TP Without prejudice

Sunpin@lkkauto.com

P = 2,644.08

N = 637

L = 1,870

5,151.08

- 20%

4,120.86

L/S

\$ 4,100

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer