

CHOO MOTOR SPRAY PAINTER  
 1 KAKI BUKIT AVE 6 #01-39 AUTOBAY  
 SPORE 417883

*Not Authorized*  
*26/12/19*  
*Hohy*

*1/5 \$3050/*

SJN 3956E

1PC	BONNET			<i>re</i>	\$1,028.20 X
1PC	FRONT BUMPER	<i>638.00</i>		<i>Defcon</i>	\$788.50 ✓
1PC	FRONT BUMPER SIDE HOLDER N/S	<i>32.50</i>		<i>sent</i>	\$66.50 ✓
1PC	FRONT BUMPER REINFORCEMENT			<i>17</i>	\$319.20 X
1SET	FRONT BUMPER CLIPS			<i>re</i>	\$38.00 ✓
1PC	FRONT BUMPER FOG LAMP N/S			<i>17</i>	\$295.00 X
1PC	FRONT FENDER N/S	<i>586.00</i>		<i>Body</i>	\$815.10 ✓
1PC	FRONT FENDER INNER SHIELD N/S	<i>188.20</i>		<i>Torn</i>	\$292.30 ✓
1SET	FRONT FENDER INNER SHIELD CLIPS N/S			<i>re</i>	\$38.00 ✓
1PC	FRONT FENDER INNER PANEL N/S			<i>re</i>	\$665.10 X
1PC	FRONT SHOCK ABSORBER N/S			<i>su</i>	\$588.20 X
1PC	FRONT LOWER ARM N/S			<i>su</i>	\$495.30 X
1PC	FRONT KNUCKLE ARM N/S	<i>495.20</i>		<i>sent</i>	\$615.20 ✓
1PC	FRONT KNUCKLE ARM BEARING N/S	<i>215.30</i>	<i>(202</i>	<i>page</i>	\$288.50 ✓
1PC	FRONT DRIVE SHAFT N/S			<i>17</i>	\$1,288.20 X
					\$7,621.30
1SET	HEADLAMP STICKER N/S			<i>re</i>	\$180.00 <i>150 s-n</i>
1PC	FRONT SPORT RIM N/S			<i>em/br</i>	\$950.00 <i>650 s-n</i>
1PC	FRONT TYRE N/S			<i>17</i>	\$200.00 X
	TO CHECK WIRING				\$80.00 <i>20</i>
	TO SPRAY RUST PROOFING				\$50.00 <i>30</i>
	TO CONDUCT WHEEL ALIGNMENT				\$120.00 <i>60</i>
	TO DISMANTLE & REPLACING FRINT UNDER CARRIAGE				\$180.00 <i>120</i>
	TO REFILL AIR CON GAS			<i>17</i>	\$120.00 X
	LABOUR FOR PANEL BEATING & REPLACING PARTS				\$680.00 <i>400</i>
	TO PUTTY & SPRAY PAINTING				\$980.00 <i>600</i>
	<b>TOTAL</b>				<b>\$11,161.30</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To disclose damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Final resurvey is on a "Without Prejudice" basis
- Any modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*P-2231-2*  
*178496*  
*3814.96*  
*3051*