

ASS. REC. BY:

REF: C8/SMO/19022673/K9d3n2

Special Instructions:

Survey: Kenneth

ASSIGNMENT (Office)

From (Person): Anne Teo of SMO Date/Time: 26/12/19 @ 9.54am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLW 52162 Insured: GBA 2831B

at Workshop in/s: Autoexcel Tel: 9382 5367

of 160 Sin Ming Drive # 06-01

Policy No: Claim No: CMTD1905965/7HE

Sum Insured: Excess:

Make of Veh: D.O.A. 23/12/19
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11am @ 26/12/19 Person Contacted: Ryan Vehicle IN/OUT

Date/Time	Action/Instruction
	SLW 52162 - X
	GBA 2831B - NA/INL 18012486/24
27/12/2019 @ 11:22am	Sent Email preli advice via email.
20th 11 Dec 8 64od email & confirm (Red \$17512.05, 73%)	

ASS. REC. BY:

REF: SMO

ASSIGNMENT

From:

Date:

26/12/19

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No:

SLW 52162

at Workshop m/s

Autoexcel

of 160 Sin Ming Drive #06-01

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLW 52162

Yr Regn:

07, 17

Type: ☒ Car ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Polo C.C.

1197

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

3668P

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WVW 8886R7144 059220

Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ BurntSteering: ☒ Inoper / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inoper / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/45R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.A.

23/12/19

26/12/19

Survey held at

Des. of Damages: Frt / ☒ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 21 JAN 2020

Date/Time, File Pass to:

☐

: Prel. Report

1) 21/1 JAN 2020

☐

: Final Report

Date/Time, File Return to:

2)

Days Of Repair:

6

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Insp (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos:

Others:

TOTAL

450

Report Format:

7P

Lump Sum / L.R. /

6400



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1905965/THE

Date: 27/12/2019

Our Ref: CS/SMO19022673/Kqd3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE P

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SLW 5216Z

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 26/12/2019 at the premises of M/s Autoexcel Engineering and have the following to report: -

Workshop Estimate Amount	: S\$ 23,912.05
Revised Estimate Amount	: S\$ 5,793.00
"Check" Items Amount	: S\$ 8,272.10
Market Value	: S\$
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the rear portion and parts.



Repair days: 6

Comments/ Present Status:

Damages Consistent.

Yours faithfully

Taufikh

Automotive Assessor

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 26 December 2019 9:54 AM
To: Autoexcel Engineering ; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Ye, Yong Kang Melvin; Henry, Irene James; Choo, Thelma
Subject: CMTD1905965/THE - LKK/ GBA2831B & SLW5216Z ACC ON 23.12.19
Attachments: SLW5216Z - GIA.PDF

Our Reference : CMTD1905965/THE
Your Reference: SLW5216Z

Date: 26.12.2019

Without Prejudice
EMAIL ONLY

OUR Email: motorsurvey@sompo.com.sg

Attention:

AUTOEXCEL ENGINEERING PTE LTD

Dear Sharon,

ACCIDENT INVOLVING GBA2831B & SLW5216Z ON 23.12.2019

We refer to your email reply of today.

We will appoint Mr. Kenneth Kong of LKK Auto Consultants to conduct the survey.

Hi LKK Auto,

Please refer to the email below and make the arrangement to survey for **SLW5216Z** on a without prejudice basis and revert with your report upon completion of survey to my colleague, Ms. Thelma.

Thank You.

Our office will be closed on Christmas, New Year's Eve and New Year Day. Business will resume on 26th December 2019 and 2nd January 2020 respectively.
We wish you a Merry Christmas and a Happy New Year!

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Autoexcel Engineering <aeexcel@singnet.com.sg>

Sent: Thursday, December 26, 2019 9:46 AM

To: Teo, Grace <grace.teo@sompo.com.sg>; Choo, Thelma <thelma.choo@sompo.com.sg>

Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: RE: CMTD1905965/THE - PRI/ GBA2831B & SLW5216Z ACC ON 23.12.19

Importance: High

Dear Sirs,

We wish to appoint LKK Auto Consultants - Kenneth Kong

Thank you

Best Regards

Ryan Soh

93825367

From: Teo, Grace <grace.teo@sompo.com.sg>

Sent: Thursday, December 26, 2019 9:38 AM

To: Autoexcel Engineering (aeexcel@singnet.com.sg) <aeexcel@singnet.com.sg>; Choo, Thelma <thelma.choo@sompo.com.sg>

Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: CMTD1905965/THE - PRI/ GBA2831B & SLW5216Z ACC ON 23.12.19

Importance: High

Our Reference : CMTD1905965/THE

Your Reference: SLW5216Z

Without Prejudice

EMAIL ONLY

Date: 26.12.2019

Attention:**AUTOEXCEL ENGINEERING PTE LTD**

Dear Sharon,

ACCIDENT INVOLVING GBA2831B & SLW5216Z ON 23.12.2019

We refer to your Notice of Accident dated 26.12.2019.

Please be informed that Ms. Thelma Choo the handler of this case who can be contacted at 63224 681/thelma.choo@sompo.com.sg.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Our office will be closed on Christmas, New Year's Eve and New Year Day. Business will resume on 26th December 2019 and 2nd January 2020 respectively.
We wish you a Merry Christmas and a Happy New Year!

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  **App Store** or  **Google Play**

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Autoexcel Engineering <aeexcel@singnet.com.sg>
Sent: Tuesday, December 24, 2019 12:52 PM
To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>
Subject: PRE REPAIR SURVEY FOR SLW 5216Z
Importance: High

Dear Officer,

Please help us arrange for pre repair survey.

Our vehicle – SLW 5216Z

Accident date – 23/12/2019

Your insure – GBA 2831B

Location – AUTOEXCEL ENGINEERING PTE LTD
160 SIN MING DRIVE # 06-01
SIN MING AUTOCITY (S) 575722

Please also let us have the list of surveyor to appoint.

Kindly note that vehicle is already in our workshop.

Thank you

Regards
Sharon Tan
93824978

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 27 December 2019 11:22 AM
To: Admin-D (LKKAuto); 'Teo, Grace'; assignments
Cc: 'Ye, Yong Kang Melvin'; 'Henry, Irene James'; 'Choo, Thelma'; SUR
Subject: RE: CMTD1905965/THE - LKK/ GBA2831B & SLW5216Z ACC ON 23.12.19
Attachments: PRELI ADVISED OF SLW 5216Z.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLW 5216Z**
Number of days (estimated) : 6 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 26 December 2019 10:11 AM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; 'Choo, Thelma' <thelma.choo@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1905965/THE - LKK/ GBA2831B & SLW5216Z ACC ON 23.12.19

Dear Sir/Mdm,

Thank you for the assignment.

Wishes you a Merry Christmas & Happy New Year 2020



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Thursday, 26 December 2019 9:54 AM
To: Autoexcel Engineering <aeexcel@singnet.com.sg>; 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; 'assignments@lkkauto.com' <assignments@lkkauto.com>

Autoexcel Engineering

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, December 26, 2019 9:54 AM
To: Autoexcel Engineering ; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Ye, Yong Kang Melvin; Henry, Irene James; Choo, Thelma
Subject: CMTD1905965/THE - LKK/ GBA2831B & SLW5216Z ACC ON 23.12.19
Attachments: SLW5216Z - GIA.PDF

Our Reference : CMTD1905965/THE
Your Reference: SLW5216Z

Without Prejudice
EMAIL ONLY

Date: 26.12.2019

OUR Email: motorsurvey@sompo.com.sg

Attention:

AUTOEXCEL ENGINEERING PTE LTD

Dear Sharon,

ACCIDENT INVOLVING GBA2831B & SLW5216Z ON 23.12.2019

We refer to your email reply of today.

We will appoint Mr. Kenneth Kong of LKK Auto Consultants to conduct the survey.

Hi LKK Auto,

Please refer to the email below and make the arrangement to survey for **SLW5216Z** on a without prejudice basis and revert with your report upon completion of survey to my colleague, Ms. Thelma.

Thank You.

Our office will be closed on Christmas, New Year's Eve and New Year Day. Business will resume on 26th December 2019 and 2nd January 2020 respectively.
We wish you a Merry Christmas and a Happy New Year!

Best Regards,
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 877Z

Vehicle Details

Vehicle No.: SLW5216Z
Vehicle to be Exported: Yes
Intended Deregistration Date: 24 Dec 2019
Vehicle Make: VOLKSWAGEN
Vehicle Model: POLO GP 1.2 TSI A/T 6C13EZ SR LED
Primary Colour: Red
Manufacturing Year: 2017
Engine No.: CJZD49739
Chassis No.: WWWZZZ6RZHU059220
Maximum Power Output: 66.0 kW (88 bhp)
Open Market Value: \$17,608.00
Original Registration Date: 31 Jul 2017
First Registration Date: 31 Jul 2017
Transfer Count: 1
Actual ARF Paid: \$7,608.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 30 Jul 2027
PARF Rebate Amount: \$5,706.00

Intended COE Rebate Details

COE Expiry Date: 30 Jul 2027
COE Category: E - Open - all except motorcycle
COE Period(Years): 10
QP Paid: \$50,101.00
COE Rebate Amount: \$33,439.00
Total Rebate Amount: \$39,145.00

The information contained herein is correct as at 24 Dec 2019

OK

AUTOEXCEL ENGINEERING PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

Not Withheld
Recovery After Paint
:- 6 days
11 hrs 86400

Date : 24/09/2019

QUOTATION -THIRD PARTY CLAIM

SOMPO INSURANCE SINGAPORE PTE LTD

Attn: Motor Claim Department . Officer In Charge

Claim : Third Party Claim
Veh. No : SLW 5216 Z
Model : VW POLO
Insured Ins: LIBERTY INSURANCE

Accident on : 23/12/2019

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : GBA 2831 B		
1	TAILGATE 1601.32 B	\$ 2,485.00	✓
1	TAILGATE LOCK 356.00	\$ 680.00	✓
1	TAILGATE LOCK LOWER SWITCH	\$ 445.00	x
1	TAILGATE TRIM BOARD	\$ 840.00	x
1	TAILGATE CENTER LOGO WITH HANDLE	\$ 78.00	x
1	TAILGATE POLO EMBLEM	\$ 68.00	✓
1	TAILGATE A180 EMBLEM	\$ 68.00	✓
1	TAILGATE TSI EMBLEM	\$ 68.00	✓
1	TAILGATE W/SCREEN MOULDING 124.00	\$ 240.00	✓
1	TAILGATE WEATHERSTRIP 189.20	\$ 250.00	✓
1	REAR W/SCREEN 859.56	\$ 1,800.00	✓
1	REAR WIPER MOTOR 632.50	\$ 840.50	✓
2	TAILLAMPS 485.50	\$ 1,680.00	✓
2	TAILLAMPS SIDE CLIPS	\$ 40.00	x
2	TAILLAMP PANELS	\$ 480.00	x
2	TAILLAMP LOWER BRACKETS	\$ 440.00	x
2	REAR No.PLATE LAMPS	\$ 460.00	x
1	END PANEL 517.33	\$ 680.00	✓
1	END PANEL TOP GARNISH	\$ 385.00	x
1	FLOOR PANEL	\$ 780.50	x
1	FLOOR PANEL TOP BOARD	\$ 688.00	x
1	REAR BUMPER 1063.75	\$ 1,685.00	✓
2	REAR BUMPER SIDE RETAINERS	\$ 480.00	✓ 240
1	REAR BUMPER SPONGE	\$ 336.00	x
1	REAR BUMPER REINFORCEMENT 455	\$ 722.50	✓
2	REAR BUMPER BRACKETS	\$ 460.00	x
2	REAR BUMPER SCREWS	\$ 80.00	x
8	REAR BUMPER CLIPS	\$ 36.00	✓
2	REAR BUMPER REFLECTORS 128.00	\$ 560.00	✓
2	REAR BUMPER SENSORS	\$ 480.00	2 own
1set	REAR BUMPER SENSOR CABLE	\$ 385.00	x
2	REAR FENDERS	REPAIR	
1	REAR EXHAUST	\$ 1,978.00	x
1	REAR EXHAUST MOUNTING	\$ 226.00	x
		\$ 20,924.50	
	Less 10 %	\$ 2,092.45	
		\$ 18,832.05	

	S/NETT PARTS		
2T	REAR W/SCREEN SEALANT <i>mm</i>	\$ 140.00	<i>401</i>
1SET	REAR NO.PLATE WITH FRAME	<i>SCM</i> \$ 220.00	<i>451</i>
	TOTAL S/NETT	\$ 360.00	
	TOTAL PARTS :	\$ 19,192.05	
QTY	LABOUR	AMOUNT	SURVEYOR
	Balance b/f	\$ 19,192.05	
	Labour charges, to do cutting, welding, replace, repair accident damage area	\$ 1,200.00	<i>601</i>
	Transfer tailgate parts to another tailgate	\$ 100.00	<i>601</i>
	Replace rear w/screen	\$ 140.00	<i>1201</i>
	To check rear wiring system, electrical door control, reset diagnose sensors, decoding reprogramme after repair <i>mm</i>	\$ 500.00	<i>X</i>
	To replace malfunction reverse camera & setting	\$ 200.00	<i>501</i>
	Remove reffix, replace rear car seat, garnish, trim board, upholstery etc for accident repair	\$ 500.00	<i>601</i>
	To replace rear exhaust	\$ <i>mm</i> 250.00	<i>X</i>
	To do anti rust	\$ 150.00	<i>601</i>
	To do sealant, seal gap, water proofing on cutting, welding affected area	\$ 280.00	<i>301</i>
	To do spray painting on inner outer, accident affected area	\$ 1,400.00	<i>6001</i>
	TOTAL LABOUR :	\$ 4,720.00	
	Total Parts & Labour :	\$ 23,912.05	

LKK Auto Consultants hereby notify the Repairer of the following:

- To reserves labor after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- The illegal modification is allowed
- Supplementary items must be surveyed and approved by the relevant insurance company

Authorised by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO19022673/Kqd3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 30-01-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 2831B	Veh. Inspected	SLW 5216Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1905965/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	26/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN POLO (A)	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WVWZZZ6RZHU059220	Colour	RED	
Odometer	36689	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R16	PIRELLI	8 mm	
L/H Front Tyre	215/45 R16	PIRELLI	8 mm	
R/H Rear Tyre	215/45 R16	PIRELLI	8 mm	
L/H Rear Tyre	215/45 R16	PIRELLI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/12/2019	Inspection Date	26/12/2019	
Survey held at	AUTOEXCEL ENGINEERING PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 5216Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	BENT	2,485.00	1,601.32
1	TAILGATE LOCK	DENTED	680.00	356.00
1	TAILGATE LOCK LOWER SWITCH	SERVICEABLE	445.00	-
1	TAILGATE TRIM BOARD	SERVICEABLE	840.00	-
1	TAILGATE CENTER LOGO WITH HANDLE	SERVICEABLE	78.00	-
1	TAILGATE POLO EMBLEM	NECESSARY	68.00	68.00
1	TAILGATE A180 EMBLEM	NECESSARY	68.00	68.00
1	TAILGATE TSI EMBLEM	NECESSARY	68.00	68.00
1	TAILGATE W/SCREEN MOULDING	NECESSARY	240.00	124.00
1	TAILGATE WEATHERSTRIP	DISTORTED / DENTED	250.00	189.20
1	REAR W/SCREEN	CUT	1,800.00	859.56
1	REAR WIPER MOTOR	JAMMED	840.50	632.50
2	TAILLAMPS	N/S MTG CRACKED / O/S SERVICEABLE	1,680.00	485.50
2	TAILLAMPS SIDE CLIPS	NOT NECESSARY	40.00	-
2	TAILLAMP PANELS	TO REPAIR SEE LABOUR	480.00	-
2	TAIL LAMP LOWER BRACKETS	SERVICEABLE	440.00	-
2	REAR NO PLATE LAMPS	SERVICEABLE	460.00	-
1	END PANEL	BUCKLED	680.00	517.33
1	END PANEL TOP GARNISH	SERVICEABLE	385.00	-
1	FLOOR PANEL	TO REPAIR SEE LABOUR	780.50	-
1	FLOOR PANEL TOP BOARD	SERVICEABLE	688.00	-
1	REAR BUMPER	BUCKLED / CRACKED	1,685.00	1,063.75
2	REAR BUMPER SIDE RETAINERS	O/S DISTORTED	480.00	240.00
1	REAR BUMPER SPONGE	SERVICEABLE	336.00	-
1	REAR BUMPER REINFORCEMENT	BENT	722.50	455.00
2	REAR BUMPER BRACKETS	TO REPAIR SEE LABOUR	460.00	-

Report Ref No. CS/SMO19022673/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BUMPER SCREWS	SERVICEABLE	80.00	-
8	REAR BUMPER CLIPS	NECESSARY	36.00	36.00
2	REAR BUMPER REFLECTORS	O/S CRACKED	560.00	128.00
1	SET REAR BUMPER SENSOR CABLE	SERVICEABLE	385.00	-
2	REAR FENDERS (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR EXHAUST	TO REPAIR SEE LABOUR	1,978.00	-
1	REAR EXHAUST MOUNTING	SERVICEABLE	226.00	-
	LESS 10% DISCOUNT		-2,044.45	-689.22
			18,400.05	6,202.94
2	REAR BUMPER SENSORS (SN)	SHORTED	480.00	200.00
	LESS 10% DISCOUNT		-48.00	-
			432.00	200.00
	SPECIAL NETT ITEMS			
1	2T REAR W/SCREEN SEALANT (SN)	NECESSARY	140.00	40.00
1	SET REAR NO PLATE WITH FRAME (SN)	CRACKED	220.00	45.00
			360.00	85.00
	LABOUR			
	LABOUR CHARGES,TO DO CUTTING,WELDING,REPLACE,REPAIR ACCIDENT DAMAGE AREA.INCLUSIVE OF THE REPAIR OF TAILLAMP PANELS,FLOOR PANEL,REAR BUMPER BRACKETS,REAR FENDERS AND REAR EXHAUST.		1,200.00	600.00
	TRANSFER TAILGATE PARTS TO ANOTHER TAILGATE.		100.00	60.00
	REPLACE REAR W/SCREEN.		140.00	120.00
	TO CHECK REAR WIRING SYSTEM,ELECTRICAL DOOR CONTROL,RESET DIAGNOSE SENSORS,DECODING REPROGRAMME AFTER REPAIR.	NOT NECESSARY	500.00	-
	TO REPLACE MALFUNCTION REVERSE CAMERA & SETTING.		200.00	50.00
	REMOVE REFIX,REPLACE REAR CAR SEAT,GARNISH,TRIM BOARD,UPHOLSTERY ETC FOR ACCIDENT REPAIR.		500.00	60.00
	TO REPLACE REAR EXHAUST.	NOT NECESSARY	250.00	-

Report Ref No. CS/SMO19022673/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DO ANTI RUST.		150.00	60.00
	TO DO SEALANT, SEAL GAP, WATER PROOFING ON CUTTING, WELDING AFFECTED AREA.		280.00	30.00
	TO DO SPRAY PAINTING ON INNER OUTER, ACCIDENT AFFECTED AREA.		1,400.00	600.00
			4,720.00	1,580.00
GRAND TOTAL			23,912.05	8,067.94
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,400.00

Report Ref No. CS/SMO19022673/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.