

ASSIGNMENT

Surveyor:

RASUL

DOI: 26/12/2019

Date / Time: 26/12/2019

Registered in Merimen: _____

Pre-assign / CCU / FTE



Insured Vehicle No. : FZ 2423S

Name of Insured : AHMAD SUHAIMI BIN ABDUL RAHIM

Insured Tel No. : _____ HP: +65-96653571

Excess Sec II : S\$

Is driver the owner? (YES / NO)

D.O.A : 23/12/2019 18:30

Nature of Accident : _____

Claim No. : S9M02B5A

Policy No. : P2141353

Make / Model : HONDA CB400SF4J M

Place of Accident : ALONG RD 1 UPPER CHANGI RD
EAST TOWARDS SIMEI

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SLL650T

INSRS:
WSP: GOLD
Tel: AUTOWORKS
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
14/12 9:05 pm	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OE:	
	After call ltr to OI:	
21/12	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☒ ☐
	After call ltr to OI:	☒ ☐
	Authorisation To Act:	☒ ☐
	Release Voucher:	☒ ☐
	Final Repair Bill:	☒ ☐
	Car Rental Invoice:	☒ ☐
	Towing Invoice:	☒ ☐
	LTA / GIA :	☒ ☐
	Medical Bill:	☒ ☐
	PIR:	☒ ☐
	Mandate/Reject Instruction:	☒ ☐
	LOD	☒ ☐
	Payment Breakdown Form:	☒ ☐
	Post-Repair Photos:	☒ ☐
	Others:	☒ ☐
PRELIMINARY ADVICE Date/Time: _____ Sent By: _____		
FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____		
Repair Cost: LK\$ S\$ 6000.00	(7 days) Reduction: \$2751.39 % 31	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time: 12/1/2020 Confirm with: Simon		
Final Liability: % 100	(Agreed / Assessed) BOLA S/N No. : 27	If NO or B 28, Ass. Lia : 01 Seal - Order TP.
Repair Cost: (W/AST) S\$ 6420.00		
Loss of Rental (LOR): S\$ 495.00	(7 days) x \$65	
Loss of Use (LOU): S\$ -	(\$ x days)	
Loss of Income (LOI): S\$ -	(\$ x days)	
LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search S\$ 7.45		
Medical: S\$ -		
Disbursement: S\$ -	(e.g. Tow/ Independent)	
Legal Cost S\$ -		
Total: S\$ 6882.45	Global Sum S\$:	
FINAL PAYMENT Date/Time: _____ Confirm with: _____ Confirm by: _____		
Payee 1: S\$ 6882.45	Name 1: Gold Autoworks Pte Ltd	
Payee 2: (Strike if N.A.) S\$ -	Name 2:	
Payee 3: (Strike if N.A.) S\$ -	Name 3:	

X GIA

12/02/2013

ASS. REC. BY:

REF: es

ASM19022676/R1td3

Special Instruction:

Surveyor: Rajul

ASSIGNMENT (Office)

From (Person): Kadi Mafeen

of

ASM(CAXA)

Date/Time: 26/12/19 9:26am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8LL650T

Insured:

FZ 2324S

at Workshop m/s

Gold Autoworks

Tel:

8199 9149

of

48 Juh Auen Road East #01-119

Policy No:

Claim No:

89M02BSAMC/RA

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/12/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:26am 26/12/19

Person Contacted:

Simon

Vehicle IN / OUT

Date/Time	Action/Instruction
	Initiald (X)
	8LL650T-X
	FZ 2324S-X
9/1/2020	Check with Simon do direct settlement anything call Simon.

Veh No: SLL650T Yr Regn: 2017 / PG8
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *LwkhLonh*

Front		Rear	
R/Bal. <u>6</u>	mm	R/Bal. <u>6</u>	mm
L/Bal. <u>6</u>	mm	L/Bal. <u>6</u>	mm
D.O.A. <u>23/12/19</u>		D.O.I. <u>26/12/19</u>	
*Survey held at		Gold Automotives	

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision

To Inspect Vehicle No: SLL 650T
at Workshop n/s GOLD AUTOWORKS
of 48, 70th Gungah Rd GYST #01-119
Insured: ASM (AXA)

Claims No.

Sum Insured: _____ Excess: _____
(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 70 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

N/S	O/S

Date/Time, File Path to

11

Date/Time, File Return to?

29

Report Form:

Received 10 May 2006; accepted 11 July 2006

☐ : Prel. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

□: Interview (\$)

 Tech. Univ. AU

Abstract—This paper presents a new method for the automatic detection of the onset of epileptic seizures. The method is based on the analysis of the non-linear properties of the EEG signals. The non-linear properties are quantified using the Lyapunov exponents. The Lyapunov exponents are calculated for the EEG signals recorded during the seizure onset. The results show that the Lyapunov exponents are significantly different from zero during the seizure onset. This difference can be used to detect the onset of epileptic seizures. The method is applied to the EEG signals recorded during the seizure onset. The results show that the method is able to detect the onset of epileptic seizures with a high accuracy.

Survey Fee:

Transportation:

$$) \quad 8 \in R3 \quad S1$$

5. Planning

1. **Conduct**

10.151

GOLD AUTOWORKS PTE LTD

48 Toh Guan Road East Enterprise Hub #01-119 Singapore 608586
 Email : claims@goldautoworks.com.sg Company Reg no. 201716329M
 CAR MODEL : HONDA VEZEL VEH NO: SLL650T
 CHASSIS NO: HP:8199-9149

Estimate Bill

	List Item	Qty	Unit Price	Amount
1	rear tailgate <i>bt</i>	1	\$ 980.00	\$ 980.00
2	rear tailgate lock <i>X suc</i>	1	\$ 264.80	\$ 264.80
3	rear tailgate inner trim <i>? cm</i>	1	\$ 334.90	\$ 334.90
4	tailgate inner trim clip <i>neu</i>	10	\$ 3.00	\$ 30.00
5	rear tailamp L/R *TAILGATE* <i>LH-X/RH-? cm</i> <i>1pc</i>	2	\$ (345.00)	\$ 690.00
6	rear tailamp L/R *BODY* <i>X RH-cm / LH-Xcm</i> <i>1pc</i>	2	\$ (385.00)	\$ 770.00
7	rear side garnishes <i>de</i>	1	\$ 276.00	\$ 276.00
8	rear tailgate outer garnishes <i>X suc</i>	1	\$ 329.00	\$ 329.00
9	rear bumper <i>de</i>	1	\$ 863.70	\$ 863.70
10	rear bumper clip <i>neu</i>	10	\$ 3.00	\$ 30.00
11	rear bumper retainer L/R *TOP* <i>X suc</i>	2	\$ 120.00	\$ 240.00
12	rear bumper retainer L/R *LOWER* <i>X suc</i>	2	\$ 100.00	\$ 200.00
13	rear wheel arch garnishes RH <i>de</i>	1	\$ 200.00	\$ 200.00
14	wheel arch garnishes clip <i>neu</i>	8	\$ 3.00	\$ 24.00
15	rear lower garnishes <i>de</i>	1	\$ 250.00	\$ 250.00
16	rear lower garnishes clip <i>neu</i>	10	\$ 3.00	\$ 30.00
17	rear end panel <i>bt</i>	1	\$ 876.40	\$ 876.40
18	rear exhaust muffler <i>repair bt</i>	1	\$ 1,059.60	\$ 1,059.60
19	exhaust muffler heat shield <i>bt</i>	1	\$ 288.90	\$ 288.90
20	rear radar sensor <i>X suc</i>	1	\$ 360.00	\$ 360.00
21	rear VEZEL emblem <i>neu</i>	1	\$ 90.00	\$ 90.00
22	rear HONDA logo <i>neu</i>	1	\$ 90.00	\$ 90.00
23	rear end panel inner trim <i>? cm</i>	1	\$ 285.00	\$ 285.00
24	end panel inner trim clip <i>neu</i>	5	\$ 3.00	\$ 15.00
25	rear car tools compartment box <i>neu</i>	1	\$ 328.00	\$ 328.00
26	rear floor panel repair	1	\$ 675.60	\$ 675.60
Total List				\$ 6,751.39
List 20% Discount				\$ 1,350.28
After Discount				\$ 5,401.11
Special Nett Item				
26	rear windscreen moulding <i>neu</i>	4	\$ 60.00	\$ 240.00
27	rear windscreen sealant <i>neu</i>	1	\$ 100.00	\$ 100.00
28	rear PHV sticker <i>X neu</i>	1	\$ 25.00	\$ 25.00
29	rear parking sensor <i>neu</i>	1	\$ 250.00	\$ 250.00
30	body panel sealant <i>neu</i>	1	\$ 80.00	\$ 80.00
Labour				
A	to check rear electrical system and repair wire harness	-	\$ 100.00	\$ 100.00
B	to repair, straighten, realign on affected area	-	\$ 1,200.00	\$ 1,200.00
C	to spray painting & blending on affected area	-	\$ 1,500.00	\$ 1,500.00
D	to apply anti rust coating on affected area	-	\$ 200.00	\$ 200.00
E	to straighten, repair exhaust pipe system	-	\$ 120.00	\$ 120.00
Total S/N & Labour				\$ 3,815.00
Lump-sum 20%				\$ 7,751.39
Total				\$ 11,479.72

I KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Signature
 2/1/2020

Passul
 4p 9000068

7 days

4/5

26/12/19

@1430

Resuming

after

repair

price?

425

60

200 neu

40

30

700 1670

80

60

5425.20

425.00

1670.00

7520.20

20%

6016.16

45-6,000

7 days

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	617W
Vehicle Details	
Vehicle No.:	SLL650T
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Green
Manufacturing Year:	2016
Engine No.:	L15B4408120
Chassis No.:	RU11208120
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,894.00
Original Registration Date:	13 Feb 2017
First Registration Date:	13 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$12,652.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Feb 2027
PARF Rebate Amount:	\$9,489.00
Intended COE Rebate Details	
COE Expiry Date:	12 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,401.00
COE Rebate Amount:	\$34,469.00
Total Rebate Amount:	\$43,958.00

The information contained herein is correct as at 30 Dec 2019

OK

65,000

Nizitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Thursday, 26 December 2019 11:35 AM
To: assignments
Subject: FW: [EXTERNAL] Re: Your Ref : SLL650T Our Ref : S9M02B5AMC/RA

Hi

Kindly assist.

TP SMART.

Thank you.
Best Regards,
Mei Kwan | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: claims@goldautoworks.com.sg <claims@goldautoworks.com.sg>
Sent: Tuesday, 24 December, 2019 3:42 PM
To: KADRI Mateen <mateen.kadri@axa.com.sg>
Subject: [EXTERNAL] Re: Your Ref : SLL650T Our Ref : S9M02B5AMC/RA

Hi Mateen Kadri, without prejudice

We would like to choose 1) LKK AUTO CONSULTANTS PTE LTD

REGARDS,
SIMON TAN
GOLD AUTOWORKS PTE LTD
8199-9149

On 2019-12-24 15:29, KADRI Mateen wrote:

- > 'WITHOUT PREJUDICE'
- > SAVE AS TO COSTS
- >
- > Dear Sir,
- >
- > We want to conduct a pre-repair survey of the damage to your
- > client's/your customer's vehicle jointly with your client/your motor
- > workshop. We propose to use one of the motor surveyors named in the
- > attached list below to conduct the joint pre-repair survey as a Single
- > Joint Expert.
- >
- > List of our motor surveyors:
- > 1.LKK Auto Consultants Pte Ltd
- > 2.Infiniti Appraisal Services
- > 3.Priority Services Pte Ltd
- > 4.AXA in house surveyor
- >
- > Please let us know within two (2) working days whether you agree to

> the appointment of any of these motor surveyors as a single joint
> expert. You may select one or more of the listed motor surveyors. We
> will bear the cost of the pre-repair survey carried out by the single
> joint expert. Meanwhile, please furnish us with estimate quotation in
> order for our surveyor to complete the pre repair survey.

>

> If there be any injury claims by your client, please combine it in one
> Letter of Demand in light of one cause of action, save as to costs and
> expenses.

>

>

> Regards,

> Mateen Kadri

>

>

>

>

>

>

>

> -----Original Message-----

> From: claims@goldautoworks.com.sg [mailto:claims@goldautoworks.com.sg]

> Sent: Tuesday, December 24, 2019 3:02 PM

> To: SG AXA Insurance SM AXA SGP - Motor Survey

> <motor.survey@axa.com.sg>

> Subject: [EXTERNAL] Requesting for PRE-Repair survey for our vehicle

> number SLL650T

>

> ATTENTION MOTOR CLAIM DEPARTMENT

>

> Dear Sir/Mdm,

>

> Accident involving SLL650T & FZ2324S AT UPP CHANGI ROAD EAST INFRONT

> SUMMER GARDENS

>

> 1. We are here to notify you of a road traffic accident on 23/12/2019

> ; 18:30HRS at UPP CHANGI ROAD EAST INFRONT SUMMER GARDENS

>

> involving our client vehicle registration number SLL650T and

> vehicle registration number FZ2324S driven by your insured

>

> at the material time.

>

> 2. As a result of the accident, our client vehicle SLL650T has been

> damaged.

>

> Please arrange and conduct a PRE- REPAIR SURVEY of the vehicle. If

> we do not receive any reply from you within the

>

> stipulated timeline, OUR client shall proceed to repair the

> vehicle without further reference to you.

>

> 3. Please arrange a PRE-REPAIR SURVEY at 48,TOH GUAN RD EAST,

> ENTERPRISE HUB #01-119 S(608586)

>

>

>
>
>
> THANKS & REGARDS,
> SIMON TAN
> GOLD AUTOWORKS PTE LTD
> 8199-9149

> -----Disclaimer-----

> This message may contain confidential information intended solely for
> the use of the named addressee. If you are not the intended recipient,
> you should not read, use, disclose or reproduce the content of this
> message. If you have received this message by mistake, please notify
> the sender immediately. Any views or opinions presented in this
> message are solely those of the author and do not necessarily
> represent those of AXA Singapore - Externals or any other entity of
> the AXA Group, unless otherwise stated by the sender and duly
> authorized by the said companies.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 21/2/2020

Survey Details:

Date of loss	23-Dec-2019
Date of appointment	26-Dec-2019
Date of survey	26-Dec-2019
Location of survey	GOLD AUTOWORKS PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLL 650T
Make and Model	HONDA VEZEL 1.5X CVT
Date of registration	13/2/2017
Parf Rebate	
Market Value	\$ 65,000.00
Parf Rebate	\$ 43,958.00
Nett Loss	\$ 21,042.00

Repair details:

Initial Estimate	\$ 9,183.78
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 5,850.20
Check items (estimate)	\$ -
Labour	\$ 1,670.00
Total	\$ 7,520.20
Lump Sum(if applicable)	\$ 6,000.00

Number of days for repair	7
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)		100%	
Proposed repair cost	\$	6,420.00	W/GST
Loss of use	\$	-	
Loss of rental	\$	455.00	7days x \$65
Loss of income	\$	-	
LTA search fees	\$	7.45	
Others	\$	-	
Proposed Total	\$	6,882.45	



<MANDATE IA> - S9M02B5A {ACCIDENT INVOLVING FZ 2423S (OI) & SLL 650T (TP) ON 23/12/2019}

Type

🔔 Question

Message

LIABILITY: 100% BOLA 527 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$6882.45 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 21/02/2020

Reply



Re:<MANDATE IA> - S9M02B5A {ACCIDENT INVOLVING FZ 2423S (OI) & SLL 650T (TP) ON 23/12/2019}

Type

 Question

Message

Hi, pls proceed as per mandate. TY.

Reply

8/2/2020

48 Toh Guan Rd East, Enterprise Hub
#01-119, Singapore 608586
Email : claims@goldautoworks.com.sg
Fax : 62645948

Contact No : 8199-9149

Letter of Demand

Dear Sir / Mdm,

**CLAIMS FOR DAMAGE ARISING FROM AN ACCIDENT ON 23/12/20 ; 18:30HRS INVOLVING
VEHICLE NO.(S) SLL650T & FZ2423S Location Of Accident : UPP CHANGI RD EAST
INFRONT SUMMER GARDENS**

We refer to the above captioned accident, and demanding the following payment for the property damages with regards to the accident

Please find attached the followings :

- 1) Final Bil
- 2) GIA Report
- 3) Loss Of Rental \$65.00 per day from: 27/12-3/1/20
- 4) LTA Search
- 5) Letter of Authorization

ITEMIZATION OF THE DAMAGES

COST OF REPAIR *GST*	:	\$	6,420.00
LOSS OF RENTAL	:	\$	455.00
LTA SEARCH FEE	:	\$	7.45
TOTAL	:	\$	6,882.45

PLEASE NOTE that we are demanding direct settlement of the total claim amount. Please kindly acknowledge and revert on the possibility of direct settlement within 14 days.

Yours truly,

Gold Autoworks Pte Ltd
Company Reg No. 201716329M
48 Toh Guan Road East #01-119,
Enterprise Hub
Singapore 608586



GOLD AUTOWORKS

48 Toh Guan Rd East, Enterprise Hub

#01-119, Singapore 608586

Email : claims@goldautoworks.com.sg

Fax : 6264 5948

Company Registration : 201716329M

GST Registration No : 201716329M

Tax Invoice : GA-20-650T

Customer Name : DRIVE U SERVICES
Vehicle No : SLL650T
Make : HONDA
Model : VEZEL
Chassis No :

Accident Date : 23/Dec/19
Contact No : 8199-9149
Mileage :
Attended By : WINSTON CHUA
Delivery Date :

S/N	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1	LUMP-SUM REPAIR	-		\$ 6,000.00
2	GST 7%			\$ 420.00

SINGAPORE DOLLARS

- 1) GOODS SOLD ARE NOT RETURNABLE.
- 2) ALL CHEQUE TO BE CROSSED AND DRAWN IN FAVOUR
OF GOLD AUTO WORKS PTE LTD

GRAND TOTAL \$ 6,420.00

NETT TOTAL \$ 6,420.00

FOR & ON BEHALF OF
GOLD AUTO WORKS PTE LTD



AUTHORISED SIGNATURE AND COMPANY
STAMP

LESS DISCOUNT

TOTAL PAYMENT

BALANCE \$ 6,420.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19022676/R1ga3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: RICHARD ANG		Date : 09-03-2020	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FZ 2423S	Veh. Inspected	SLL 650T
Policy No.	AN3175757	Coverage (\$)	0.00
Claim No.	S9M02B5AMC/RA	Excess (\$)	0.00
Assign From	KADRI MATEEN	Assign Date	26/12/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL 1.5X CVT	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU11208120	Colour	GREEN
Odometer	247832	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	LING LONG	6 mm
L/H Front Tyre	215/60 R16	LING LONG	6 mm
R/H Rear Tyre	215/60 R16	LING LONG	6 mm
L/H Rear Tyre	215/60 R16	LING LONG	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/12/2019	Inspection Date	26/12/2019
Survey held at	GOLD AUTOWORKS PTE LTD 48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 650T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAILGATE (CONSISTENT)	BENT	980.00	980.00
1	REAR TAILGATE LOCK (CONSISTENT)	SERVICEABLE	264.80	-
1	REAR TAILGATE INNER TRIM (CONSISTENT)	CRACKED	334.90	334.90
10	TAILGATE INNER TRIM CLIP @ \$3.00 (CONSISTENT)	NECESSARY	30.00	30.00
2	REAR TAILLAMP L/R (TAILGATE) @ \$345.00 (CONSISTENT)	N/S NOT NECESSARY / O/S CRACKED	690.00	345.00
2	REAR TAILLAMP L/R (BODY) @ \$385.00 (CONSISTENT)	O/S CRACKED / N/S NOT NECESSARY	770.00	385.00
1	REAR SIDE GARNISHES (CONSISTENT)	DEFORMED	276.00	276.00
1	REAR TAILGATE OUTER GARNISHES (CONSISTENT)	SERVICEABLE	329.00	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	863.70	863.70
10	REAR BUMPER CLIP @ \$3.00 (CONSISTENT)	NECESSARY	30.00	30.00
2	REAR BUMPER RETAINER L/R (TOP) @ \$120.00 (CONSISTENT)	SERVICEABLE	240.00	-
2	REAR BUMPER RETAINER L/R (LOWER) @ \$100.00 (CONSISTENT)	SERVICEABLE	200.00	-
1	REAR WHEEL ARCH GARNISHES RH (CONSISTENT)	DEFORMED	200.00	200.00
8	WHEEL ARCH GARNISHES CLIP @ \$3.00 (CONSISTENT)	NECESSARY	24.00	24.00
1	REAR LOWER GARNISES (CONSISTENT)	DEFORMED	250.00	250.00
10	REAR LOWER GARNISHES CLIP @ \$3.00 (CONSISTENT)	NECESSARY	30.00	30.00
1	REAR END PANEL (CONSISTENT)	BENT	876.40	876.40
1	REAR EXHAUST MUFFLER (CONSISTENT)	BENT	1,059.60	1,059.60
1	EXHAUST MUFFLER HEAT SHIELD (CONSISTENT)	BENT	288.90	288.90
1	REAR RADAR SENSOR (CONSISTENT)	SERVICEABLE	360.00	-
1	REAR VEZEL EMBLEM (CONSISTENT)	NECESSARY	90.00	90.00
1	REAR HONDA LOGO (CONSISTENT)	NECESSARY	90.00	90.00
1	REAR END PANEL INNER TRIM (CONSISTENT)	CRACKED	285.00	285.00
5	END PANEL INNER TRIM CLIP @ \$3.00 (CONSISTENT)	NECESSARY	15.00	15.00
1	REAR CAR TOOLS COMPARTMENT BOX (CONSISTENT)	CRACKED	328.00	328.00
1	REAR FLOOR PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	675.60	-

Report Ref No. CC4/ASM19022676/R1ga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-1,916.18	-1,356.30
			7,664.72	5,425.20
	<u>SPECIAL NETT ITEMS</u>			
4	REAR WINDSCREEN MOULDING @\$60.00 (SN) (CONSISTENT)	NECESSARY	240.00	125.00
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	100.00	60.00
1	REAR PHV STICKER (SN) (CONSISTENT)	NOT NECESSARY	25.00	-
1	REAR PARKING SENSOR (SN) (CONSISTENT)	NOT WORKING	250.00	200.00
1	BODY PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	40.00
			695.00	425.00
	<u>LABOUR</u>			
	TO CHECK REAR ELECTRICAL SYSTEM AND REPAIR WIRE HARNESS.		100.00	30.00
	TO REPAIR, STRAIGHTEN, REALIGN ON AFFECTED AREA. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.		1,200.00	800.00
	TO SPRAY PAINTING & BLENDING ON AFFECTED AREA.		1,500.00	700.00
	TO APPLY ANTI RUST COATING ON AFFECTED AREA.		200.00	80.00
	TO STRAIGHTEN, REPAIR EXHAUST PIPE SYSTEM.		120.00	60.00
			3,120.00	1,670.00
	GRAND TOTAL		11,479.72	7,520.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,000.00

Report Ref No. CC4/ASM19022676/R1ga3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.