

GOLD AUTOWORKS PTE LTD

48 Toh Guan Road East Enterprise Hub #01-119 Singapore 608586
 Email : claims@goldautoworks.com.sg Company Reg no. 201716329M
 CAR MODEL : HONDA VEZEL VEH NO: SLL650T
 CHASSIS NO: HP:8199-9149

Estimate Bill

	List Item	Qty	Unit Price	Amount
1	rear tailgate <i>bt</i>	1	\$ 980.00	\$ 980.00
2	rear tailgate lock <i>X SUC</i>	1	\$ 264.80	\$ 264.80
3	rear tailgate inner trim <i>? cm</i>	1	\$ 334.90	\$ 334.90
4	tailgate inner trim clip <i>neu</i>	10	\$ 3.00	\$ 30.00
5	rear tailamp L/R *TAILGATE* <i>LH-X / RH-? cm</i>	2	\$ (345.00)	\$ 690.00
6	rear tailamp L/R *BODY* <i>X RH-cm / LH-Xan</i>	2	\$ (385.00)	\$ 770.00
7	rear side garnishes <i>de</i>	1	\$ 276.00	\$ 276.00
8	rear tailgate outer garnishes <i>X SUC</i>	1	\$ 329.00	\$ 329.00
9	rear bumper <i>de</i>	1	\$ 863.70	\$ 863.70
10	rear bumper clip <i>neu</i>	10	\$ 3.00	\$ 30.00
11	rear bumper retainer L/R *TOP* <i>X SUC</i>	2	\$ 120.00	\$ 240.00
12	rear bumper retainer L/R *LOWER* <i>X SUC</i>	2	\$ 100.00	\$ 200.00
13	rear wheel arch garnishes RH <i>de</i>	1	\$ 200.00	\$ 200.00
14	wheel arch garnishes clip <i>neu</i>	8	\$ 3.00	\$ 24.00
15	rear lower garnishes <i>de</i>	1	\$ 250.00	\$ 250.00
16	rear lower garnishes clip <i>neu</i>	10	\$ 3.00	\$ 30.00
17	rear end panel <i>bt</i>	1	\$ 876.40	\$ 876.40
18	rear exhaust muffler <i>repair bt</i>	1	\$ 1,059.60	\$ 1,059.60
19	exhaust muffler heat shield <i>bt</i>	1	\$ 288.90	\$ 288.90
20	rear radar sensor <i>X SUC</i>	1	\$ 360.00	\$ 360.00
21	rear VEZEL emblem <i>neu</i>	1	\$ 90.00	\$ 90.00
22	rear HONDA logo <i>neu</i>	1	\$ 90.00	\$ 90.00
23	rear end panel inner trim <i>? cm</i>	1	\$ 285.00	\$ 285.00
24	end panel inner trim clip <i>neu</i>	5	\$ 3.00	\$ 15.00
25	rear car tools compartment box <i>cm</i>	1	\$ 328.00	\$ 328.00
26	rear floor panel repair	1	\$ 675.60	\$ 675.60
Total List				\$ 8,751.39
List 20% Discount				\$ 1,750.28
After Discount				\$ 6,999.11
Special Nett Item				
26	rear windscreen moulding <i>neu</i>	4	\$ 60.00	\$ 240.00
27	rear windscreen sealant <i>neu</i>	1	\$ 100.00	\$ 100.00
28	rear PHV sticker <i>X neu</i>	1	\$ 25.00	\$ 25.00
29	rear parking sensor <i>neu</i>	1	\$ 250.00	\$ 250.00
30	body panel sealant <i>neu</i>	1	\$ 80.00	\$ 80.00
Labour				
A	to check rear electrical system and reapi wire harness	-	\$ 100.00	\$ 100.00
B	to repair, straighten, realign on affected area	-	\$ 1,200.00	\$ 1,200.00
C	to spray painting & blending on affected area	-	\$ 1,500.00	\$ 1,500.00
D	to apply anti rust coating on affected area	-	\$ 200.00	\$ 200.00
E	to straighten, repair exhaust pipe system	-	\$ 120.00	\$ 120.00
Total S/N & Labour				\$ 3,815.00
Lump-sum 20%				\$ 7,751.39

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Signature
 2/1/2020

Rasul
 4p 900000
 7 days
 4/5
 26/12/19
 @1430

Resurvey after repair
 6781150
 202
 5425.20

price?
 425
 60
 200 neu
 40
 30
 700
 80
 60

5425.20
 425.00
 1670.00
 7520.20
 202
 6016.16

45-6,000
 7 days