

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19022678/T1DS3Q2

**Date:** 28/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800002392

**Claimant**  
**Vehicle No :** SJW9217T **Insured Vehicle No :** SJE3022Y

Date of Loss: 12/12/2019 Nature of Claim: TP Claim No: 0021374976SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW9217T		
Make & Model:	NISSAN LATIO, 1.5 L (A)	Engine No:	HR15104552B
Reg. Date:	28/04/2010 (Man. Year: 2009)	Chassis No:	JN1BAAC11Z0021449
Colour:	Silver	Odometer:	161312 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,500.00</b>		
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>3,500.00</b>	<b>-3,500.00</b>	
<b>+ Loss of Use (14.0 x S\$60.00/day) (\$\$)</b>		840.00		
<b>+ Doc/Search Fee (\$\$)</b>		36.49		
<b>Nett Liability (\$\$)</b>		<b>4,376.49</b>		

### INSPECTION

Date of Assignment: 26/12/2019

Date Inspected: 26/12/2019 Inspected At:

Teamwork Garage Pte Ltd (HQ)  
53 Ubi Ave 1 #01-24, Paya Ubi  
Industrial Park  
Singapore 408934

Estimated Period of Repair: 0.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$14,500.00

LTA REIMBURSEMENT VALUE (RV) : \$10,559.00

NETT VALUE : \$3,941.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

## REPAIR DETAILS

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**