

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61

Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : FIRST CAPITAL INSURANCE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTKB/TP/1912/012
Policy No:	5095356036-02	Date of Loss:	19/12/2019
Vehicle Reg. No.:	SLH9159H	Driveable?	yes
Driver Age:	2/9/1962	Third Party Vehicle No.:	SHC688E
Any Injuries?	no	Contact No:	96474625
Insured/Claimant:	NAZREEN BTE MOHD OSMAN	Driver:	NAZREEN BTE MOHD OSMAN

Make/Model:	Toyota, Wish	Vehicle Reg. Date:	23 Nov 2016
Vehicle Colour:	SILVER	Engine Number:	2ZR1862492
Chassis No:	JTDGG20W60J006132	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	16

Description of Accident/loss CHAIN COLLISION

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	639.00
Labour	3,630.00
Paintwork Labour	2,005.00
Towing	0.00

Gross Total(S\$):	6,274.00
GST 7.00%(S\$):	439.18
Nett Amount(S\$):	6,713.18

This claim is handled by: may chai

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*not authorized
Hale
marcus
26/12/18
1/5 #
The pho Akh up
1 Hdy.*

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT BUMPER <i>Dis</i>	0.00	-25.00	0.00
2	1	FRONT BUMPER INNER SPONGE <i>torn</i>	0.00	-25.00	0.00
3	1	FRONT BUMPER SIDE RETAINER LH <i>scr</i>	0.00	-25.00	0.00
4	1	FRONT BUMPER SIDE RETAINER RH <i>scr</i>	0.00	-25.00	0.00
5	1	FRONT BUMPER REINFORCEMENT <i>scr</i>	0.00	-25.00	0.00
6	1	FRONT BUMPER FOG LAMP RH <i>?</i>	0.00	-25.00	0.00
7	1	FRONT BUMPER FOG LAMP LH <i>?</i>	0.00	-25.00	0.00
8	1	FRONT BUMPER FOG LAMP COVER RH <i>?</i>	0.00	-25.00	0.00
9	1	FRONT BUMPER FOG LAMP COVER LH <i>?</i>	0.00	-25.00	0.00
10	1	FRONT BUMPER LOWER AIR GRILLE	0.00	-25.00	0.00
11	1	FRONT GRILLE	0.00	-25.00	0.00
12	1	FRONT GRILLE CHROME <i>3 complete sent/torn</i>	0.00	-25.00	0.00
13	1	BONNET <i>scr</i>	0.00	-25.00	0.00
14	1	BONNET HINGE RH <i>scr</i>	0.00	-25.00	0.00
15	1	BONNET HINGE LH <i>scr</i>	0.00	-25.00	0.00
16	1	BONNET INSULATOR <i>scr</i>	0.00	-25.00	0.00
17	1	BONNET INSULATOR CLIP <i>scr</i>	0.00	-25.00	0.00
18	1	BONNET LOCK <i>scr</i>	0.00	-25.00	0.00
19	1	BONNET LOCK CATCH <i>scr</i>	0.00	-25.00	0.00
20	1	BRACE PANEL <i>scr</i>	0.00	-25.00	0.00
21	1	HEADLAMP RH <i>mtg cre</i>	0.00	-25.00	0.00
22	1	HEADLAMP LH <i>mtg cre</i>	0.00	-25.00	0.00
23	1	BONNET EMBLEM <i>scr</i>	0.00	-25.00	0.00
24	1	BONNET RUBBER <i>scr</i>	0.00	-25.00	0.00
25	1	FENDER RH <i>scr</i>	0.00	-25.00	0.00
26	1	FENDER LH <i>scr</i>	0.00	-25.00	0.00
27	1	FRONT FENDER INNER SHIELD RH <i>scr</i>	0.00	-25.00	0.00
28	1	FRONT FENDER INNER SHIELD LH <i>scr</i>	0.00	-25.00	0.00
29	1	FRONT SUPPORT PANEL <i>scr</i>	0.00	-25.00	0.00
30	1	FRONT SUPPORT PANEL TOP GARNISH <i>torn</i>	0.00	-25.00	0.00
31	1	AIRCON CONDENSER <i>?</i>	0.00	-25.00	0.00
32	1	CONDENSER FAN MOTOR <i>?</i>	0.00	-25.00	0.00
33	1	CONDENSER FAN BLADE <i>?</i>	0.00	-25.00	0.00
34	1	CONDENSER FAN COWLING <i>?</i>	0.00	-25.00	0.00
35	1	CONDENSER PIPE <i>scr</i>	0.00	-25.00	0.00
36	1	RADIATOR <i>scr</i>	0.00	-25.00	0.00
37	1	RADIATOR FAN MOTOR <i>?</i>	0.00	-25.00	0.00
38	1	RADIATOR FAN BLADE <i>?</i>	0.00	-25.00	0.00
39	1	RADIATOR FAN COWLING <i>?</i>	0.00	-25.00	0.00
40	1	RADIATOR TOP HOSE <i>scr</i>	0.00	-25.00	0.00
41	1	RADIATOR BOTTOM HOSE <i>scr</i>	0.00	-25.00	0.00
42	1	WIPER TANK <i>scr</i>	0.00	-25.00	0.00
43	1	AIR GUIDE RH <i>?</i>	0.00	-25.00	0.00
44	1	AIR GUIDE LH <i>?</i>	0.00	-25.00	0.00
45	1	HORN <i>?</i>	0.00	-25.00	0.00
46	1	REAR TAILGATE <i>3rd 5th</i>	0.00	-25.00	0.00
47	1	REAR TAILGATE INNER BOARD <i>?</i>	0.00	-25.00	0.00
48	1	REAR TAILGATE LOCK <i>scr</i>	0.00	-25.00	0.00
49	1	REAR TAILGATE LOCK CATCH <i>scr</i>	0.00	-25.00	0.00
50	1	REAR TAILGATE LOGO <i>scr</i>	0.00	-25.00	0.00
51	1	REAR TAILGATE OUTER CHROME HANDLE <i>scr</i>	0.00	-25.00	0.00
52	1	REAR TAILGATE ELEGANCE EMBLEM <i>scr</i>	0.00	-25.00	0.00
53	1	REAR TAILGATE RH EMBLEM <i>scr</i>	0.00	-25.00	0.00

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
54	1	REAR BUMPER <i>Dis</i>	0.00	-25.00	0.00
55	1	REAR BUMPER BRACKET LH <i>?</i>	0.00	-25.00	0.00
56	1	REAR BUMPER REFLECTOR LH <i>?</i>	0.00	-25.00	0.00
57	1	REAR BUMPER REFLECTOR RH <i>?</i>	0.00	-25.00	0.00
58	1	REAR BUMPER SIDE RETAINER LH <i>Buy</i>	0.00	-25.00	0.00
59	1	REAR BUMPER SIDE RETAINER RH <i>Buy</i>	0.00	-25.00	0.00
60	1	REAR END PANEL <i>300.00</i>	0.00	-25.00	0.00
61	1	REAR END PANEL INNER GARNISH <i>?</i>	0.00	-25.00	0.00
62	1	REAR SPARE TYRE BOARD <i>?</i>	0.00	-25.00	0.00
63	1	REAR SPARE TYRE PANEL <i>?</i>	0.00	-25.00	0.00
64	1	REAR EXHAUST PIPE <i>?</i>	0.00	-25.00	0.00
65	1	REAR EXHAUST PIPE MOUNTING <i>?</i>	0.00	-25.00	0.00
66	1	REAR WINDSCREEN MOULDING <i>nu</i>	0.00	-25.00	0.00
67	1	REAR TAILLAMP LH <i>?</i>	0.00	-25.00	0.00
68	1	REAR TAILLAMP RH <i>?</i>	0.00	-25.00	0.00
69	1	REAR LH FENDER <i>rx</i>	0.00	-25.00	0.00
70	1	REAR LH DOOR <i>rx</i>	0.00	-25.00	0.00

Total Parts (\$\$) 0.00

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT NUMBER PLATE <i>sent</i>	35.00	0.00	35.00
2	1	FRONT BUMPER CLIP <i>nu</i>	30.00	0.00	30.00
3	1	REAR BUMPER CLIP <i>nu</i>	30.00	0.00	30.00
4	1	REAR NUMBER PLATE <i>sent</i>	35.00	0.00	35.00
5	1	FRONT FENDER INNER SHIELD CLIP <i>11</i>	25.00	0.00	25.00
6	1	SUPPORT PANEL TOP GARNISH CLIP <i>100</i>	60.00	0.00	60.00
7	1	REAR WINDSCREEN SEALANT <i>nu</i>	24.00	0.00	24.00
8	4	REAR BUMPER SENSOR <i>shut</i>	400.00	0.00	400.00

Sub Total (\$\$) 639.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00
2	1	To Do Up Interior Cleaning and Chemical Wash.	200.00	0.00	200.00
3	1	To Remove and Refit Rear Cushion Fittings. <i>7.10</i>	80.00	0.00	80.00
4	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	0.00	180.00
5	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00
6	1	To Pressure Test Air Con Condenser and Radiator For Leakage.	120.00	0.00	120.00
7	1	To Transfer Rear Tailgate.	80.00	0.00	80.00
8	1	To Remove & Refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	180.00	0.00	180.00
9	1	Towing Charges.	80.00	0.00	80.00
10	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00
11	1	To Remove and Replace the above Damaged	2,500.00	0.00	2,500.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
		Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.			
			Gross Labour Cost (\$\$)		<u>3,630.00</u>

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	80.00	0.00	80.00 ✓
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	0.00	45.00 X
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	80.00	0.00	80.00 X
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,800.00	0.00	1,800.00 1780
			Gross Labour Cost (\$\$)		<u>2,005.00</u>

< END OF ESTIMATES >