



**CAR CITY AUTO CENTRE PTE LTD**  
Car City Always

Blk 9006 Tampines st93 #01-198 S'pore 528840

TEL: 6781 0300 FAX: 6782 0300

E-mail : [ccacpl@singnet.com.sg](mailto:ccacpl@singnet.com.sg)

*not Authorised 1 OF 1*  
*26/12/19 Hdy.*  
*2/5th*  
*whenever Authorised*

DATE : 24-Dec-19

TO: INDIA INTERNATIONAL INSURANCE

JOB TYPE : 3RD PARTY CLAIM

ATTN: MOTOR CLAIMS DEPT

ESTIMATE REPORT

OWNER'S PARTICULAR

NAME: PANG KOK WAH

ADDRESS:

CONTACT NO H/P:

TEL:

OWNERS INSURER : CHINA TAIPING

POLICY NO: DMPCSN3063511902

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

VEH NO : SKS546L

MODEL : TOYOTA / CAMRY 2.5A

CHASSIS NO : MR053AK5004008670

ENGINE NO:

ACCIDENT DATE : 14/12/2019

QUOTATION SUMMARY

CLAIM DETAIL: PARTS

REQUESTOR CONTACT :

HO / 67810300

S/NO	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	LH FRONT FENDER <i>R X</i>	1	\$827.50	\$827.50 <i>X</i>
2	LH FRONT FENDER BRACKET <i>L X</i>	1	\$125.10	\$125.10 <i>X</i>
3	LH OUTER ROCKER PANEL <i>garnish ?</i>	1	\$493.80	\$493.80 <i>?</i>
4	LH FRONT DOOR <i>20/201</i>	1	\$1,639.50	\$1,639.50 <i>-</i>
5	LH REAR DOOR <i>R X</i>	1	\$1,539.50	\$1,539.50 <i>X</i>
6	LH FRONT & REAR DOOR STICKER (BLACK) <i>L X</i>	3	\$75.30	\$225.90 <i>X</i>
7	LH OUTER ROCKER PANEL CHROME <i>500</i>	1	\$250.00	\$250.00 <i>-</i>
8				

PARTS PRICE : \$5,101.30

LESS 25% : \$1,275.33

SUB TOTAL PRICE : \$3,825.98

TOTAL PARTS PRICE : \$3,825.98

**CLAIM DETAIL : LABOURS & SPRAY PAINTING**

No	JOB DESCRIPTION	PRICE	REVISED PRICE
1	TO REMOVE & REFIT AFFECTED PARTS; PANEL BEATING ON DAMAGED AREAS, CUT, WELD, KNOCK STRAIGHTEN, REALIGN & RESHAPE.FRONT BONNET, FRONT FENDER LH,O LH FRONT DOOR, LH REAR DOOR AND THER.	\$1,000.00	400
2	TO APPLY ANTI-RUST UNDERCOAT ON REPLACE & REPAIRED PANELS.	\$80.00	30
3	TO PUTTY, CLEANING, SANDING, POLISHING, WAXING & SPRAY PAINT ON ALL NECESSARY PARTS AND AREAS. FRONT FENDER LH, FRONT LH DOOR , REAR DOOR LH.....ETC.	\$1,200.00	800
4	TO CHECK & REPAIR WIRING SYSTEM, REMOVE & REPLACE DAMAGED WIRE.SIGNAL LIGHT WIRE, HEADLAMP WIRE, SENSOR WIRE & OTHER WIRING.	\$50.00	20
5	TO TRANSFER LH FRONT & REAR DOOR INNER PARTS	\$100.00	60
6	ALIGNMENT	\$80.00	not
7			
<b>TOTAL LABOUR &amp; SPRAY PAINTING PRICES:</b>		\$2,510.00	

VEHICLE NO : SKS546L

**ESTIMATE REPORT**

TOTAL LABOUR COST : \$2,510.00  
 TOTAL PARTS COST : \$3,825.98  
 TOTAL REPAIR COST : \$6,335.98

**APPROVAL DETAILS**

EXCESS :  
 NO. OF DAY :  
 PART BY PART OR LUMP-SUM :  
 DATE OF SURVEY :  
 SURVEY BY :  
 CONTACT NO :  
 FAX NO. :

**NOTE :** LUMP-SUM AMOUNT OR COST OF REPAIR  
 WOULD BE REVISED IF SUPPLEMENT REPAIR  
 IS REQUIRED